

# PRE-DEMOLITION HAZARDOUS MATERIALS SURVEY

Former Scherer Bros Lumber  
900 Sibley Street NE  
9 - 9<sup>TH</sup> Avenue NE  
9 - 8<sup>TH</sup> Avenue NE  
15 - 8<sup>TH</sup> Avenue NE  
Minneapolis, Minnesota

Prepared For:

Minneapolis Park and Recreation Board

July 8, 2011

PRE-DEMOLITION HAZARDOUS MATERIALS SURVEY  
FORMER SCHERER BROS LUMBER  
900 SIBLEY STREET NE  
9 – 9<sup>TH</sup> AVENUE NE  
9 – 8<sup>TH</sup> AVENUE NE  
15 - 8<sup>TH</sup> AVENUE NE  
MINNEAPOLIS, MINNESOTA  
(Peer File #20074)

Prepared For:

Minneapolis Park and Recreation Board  
2117 West River Road  
Minneapolis, Minnesota 55411

Prepared by:

Peer Engineering, Inc.  
7615 Golden Triangle Drive, Suite N  
Eden Prairie, Minnesota 55344  
(952) 831-3341

July 8, 2011

## TABLE OF CONTENTS

<b>1.0</b>	<b>INTRODUCTION .....</b>	<b>1</b>
<b>2.0</b>	<b>SURVEY INFORMATION .....</b>	<b>1</b>
2.1	ASBESTOS.....	2
2.1.1	General Information and Definitions.....	2
2.1.2	Sampling and Analytical Testing.....	3
2.1.3	Results.....	4
2.1.3.1	Building 1A .....	4
2.1.3.2	Building 1B.....	5
2.1.3.3	Building 1C .....	9
2.1.3.4	Building 1D.....	10
2.1.3.5	Building 5.....	11
2.1.3.6	Building 6.....	12
2.1.3.7	Building 9.....	13
2.1.4	Limitations .....	14
2.2	HAZARDOUS MATERIALS.....	14
2.2.1	General Information .....	14
2.2.2	Observations & Results .....	15
2.2.3	Limitations .....	18
2.3	LEAD-BASED PAINT.....	19
2.3.1	General Information and Definitions.....	19
2.3.2	Observations & Results .....	19
2.3.3	Limitations .....	21
2.4	PCBS IN CAULKING .....	22
2.4.1	General Information and Definitions.....	22
2.4.2	Observations and Results .....	22
<b>3.0</b>	<b>CONCLUSIONS AND RECOMMENDATIONS.....</b>	<b>22</b>
<b>4.0</b>	<b>STANDARD OF CARE &amp; QUALIFICATIONS.....</b>	<b>23</b>

## **LIST OF FIGURES**

Figure 1 – Site Buildings

Figure 2 – Oblique View of Building Layout

## **LIST OF TABLES**

Table 1 – PCBs in Caulk

## **LIST OF APPENDICES**

Appendix A – MPCA Category I Non-Friable ACM Guidance Document

Appendix B – MPCA Category II Non-Friable ACM Guidance Document

Appendix C – Asbestos Summary Table and Sample Location Diagram (Building 1A)

Appendix D – Asbestos Analytical Results (Building 1A)

Appendix E – Asbestos Summary Table and Sample Location Diagram (Building 1B)

Appendix F – Asbestos Analytical Results (Building 1B)

Appendix G – Asbestos Summary Table and Sample Location Diagram (Building 1C)

Appendix H – Asbestos Analytical Results (Building 1C)

Appendix I – Asbestos Summary Table and Sample Location Diagram (Building 1D)

Appendix J – Asbestos Analytical Results (Building 1D)

Appendix K – Asbestos Summary Table and Sample Location Diagram (Building 5)

Appendix L – Asbestos Analytical Results (Building 5)

Appendix M – Asbestos Summary Table and Sample Location Diagram (Building 6)

Appendix N – Asbestos Analytical Results (Building 6)

Appendix O – Asbestos Summary Table and Sample Location Diagram (Building 9)

Appendix P – Asbestos Analytical Results (Building 9)

Appendix Q – Lead-Based Paint Testing Results

Appendix R – Lead-Based Paint Testing Location Diagrams

Appendix S – PCB Analytical Results

Appendix T – Summary of Qualifications

## 1.0 INTRODUCTION

Peer Engineering, Inc. (Peer) was retained by the City of Minneapolis to perform a pre-demolition hazardous materials survey of the commercial buildings located on the former Scherer Bros Lumber Company property located between 8<sup>th</sup> Avenue NE and 10<sup>th</sup> Avenue NE, and between Sibley Street and the Mississippi River in Minneapolis, Minnesota (the Site). The Site is occupied by four vacant buildings. The proposed plans contemplated for the Site include demolition and redevelopment of the Site.

The work performed as part of this project was completed to meet the following objectives:

1. Identify friable and non-friable asbestos-containing materials (ACM) at the Site as defined by the Environmental Protection Agency (EPA), Minnesota Pollution Control Agency (MPCA), and the Minnesota Department of Health (MDH).
2. Identify regulated ACM (friable or non-friable) at the Site that could become friable during demolition activities, and according to current State and Federal regulations, would require abatement prior to initiating demolition activities.
3. Identify lead-based paint (LBP) surfaces that have the potential to be disturbed during renovation activities, and if classified as lead-based paint, require abatement and/or special management prior to demolition activities.
4. Inventory potentially hazardous materials that should be removed and properly disposed prior to initiating demolition activities.
5. Identify caulking at the Site that contains polychlorinated biphenyls (PCBs) and according to current State and Federal regulations, would require abatement and/or special management prior to initiating demolition activities.

This report summarizes the findings of our pre-demolition hazardous materials survey.

## 2.0 SURVEY INFORMATION

Mr. Kelly Brown, a MDH Certified Asbestos Inspector and Lead Risk Assessor, and/or Mr. Rick Fink and Ms. Kristie Rykken of Peer completed the building survey and associated destructive sampling activities on June 15 through 20, 2011. A walk-through reconnaissance of the structures was conducted to identify suspect ACM, hazardous materials and lead-based paint.

A diagram identifying and depicting the layout of the buildings for the Site is included as **Figure 1**. Building 1 was divided into four sections (1A through 1D) based on visual

evidence that these four sections were additions or separate buildings that were subsequently connected. The Site consists of the following buildings:

- ◆ Building 1A – a one-story showroom.
- ◆ Building 1B – a three-story office and storage building.
- ◆ Building 1C – a one-story storage and wood shop building.
- ◆ Building 1D – a one-story shop building with a partial mezzanine.
- ◆ Building 5 – a one-story warehouse.
- ◆ Building 6 – a partial two-story shop and warehouse.
- ◆ Building 9 – a one-story warehouse.

## 2.1 ASBESTOS

### 2.1.1 General Information and Definitions

For the purpose of this assessment, each of the above-identified structure was considered as one functional area as defined by the Asbestos Hazard Emergency Response Act (AHERA). Upon completion of the reconnaissance, the suspect ACM was assessed, inventoried, and sampled for laboratory analysis.

The following definitions apply to this report:

- ◆ The EPA defines ACM as any material that contains greater than one percent asbestos. Materials found to contain one percent or less asbestos are not regulated as ACM.
- ◆ Friable ACM is defined as any material that contains greater than one percent asbestos, and which can be crumbled, pulverized, or reduced to powder by hand pressure.
- ◆ Category I non-friable ACM means asbestos-containing packings, gaskets, resilient floor covering, and asphalt roofing products containing more than one percent asbestos. Category I non-friable ACM is not allowed to remain in place during renovation or demolition if it is in a condition where the renovation/demolition activities might cause it to become friable. A guidance document prepared by the MPCA in December 2000 pertaining to the removal, transport and disposal of Category I non-friable ACM is included as **Appendix A**.
- ◆ Category II non-friable ACM means any material, excluding Category I non-friable ACM, containing more than one percent asbestos that, when dry, cannot be crumbled, pulverized, or reduced to a powder by hand pressure. Category II non-friable ACM is not allowed to remain in place during renovation or demolition if it has a high probability of becoming crumbled, pulverized, or reduced to a powder during renovation, demolition, transport, or disposal. A guidance document prepared by the MPCA in January 2002 pertaining to the removal, transport and disposal of Category II non-friable ACM is included as **Appendix B**.

## 2.1.2 Sampling and Analytical Testing

### *Non-Suspect Material*

The following materials were determined to be non-suspect ACM and were not targeted for sampling during this inventory:

- ◆ Pipes, ducts, and/or boilers insulated with foam.
- ◆ Concrete floors.
- ◆ Metal walls or ceilings.
- ◆ Wood walls, floors, or ceilings

### *Suspect ACM Targeted for Sampling*

Suspect ACM identified and subsequently sampled at the Site included:

- ◆ Stucco.
- ◆ Concrete block.
- ◆ Various types of textured ceiling material.
- ◆ Brick and mortar.
- ◆ Various types of caulking.
- ◆ Various types of glaze.
- ◆ Various types of floor tile and associated mastic.
- ◆ Various types of vinyl sheet flooring and associated mastic.
- ◆ Various types of ceiling tile.
- ◆ Plaster with skimcoat.
- ◆ Drywall and drywall composite.
- ◆ Sink undercoating.
- ◆ Carpet mastic.
- ◆ Various types of electrical box insulators.
- ◆ Various types of vinyl baseboard.
- ◆ Various types of wall and ceiling insulation.
- ◆ Various types of roofing materials.
- ◆ Vapor barrier paper.
- ◆ Various types of countertop material.
- ◆ Various types of wall panel and associated mastic.
- ◆ Fiberglass pipe insulation.
- ◆ Fiberglass duct insulation.
- ◆ Cloth vibration joint.

## Sample Analysis

A total of 220 bulk samples were submitted for laboratory analysis. Some of the bulk samples consisted of several layers. A total of 332 samples (including layers) were analyzed using polarized light microscopy (PLM) in accordance with EPA analytical protocol {EPA-600 R93/116} by EMSL Analytical, Inc. of Plymouth, Minnesota. Materials that were analyzed and found to contain **one percent or less** asbestos are considered “non-asbestos” per current State and Federal regulations. Materials that were found to contain **greater than one percent** asbestos are considered to be ACM.

Under current Federal regulations, if the PLM results detect asbestos at a concentration of less than 10% in one or more of the samples from any sample unit, the owner or operator of the building may (1) elect to assume the amount to be greater than 1% and treat the material as ACM or (2) require verification of the amount by utilizing the Point-Count Method. If the Point-Count Method analysis determines that the concentration of asbestos is greater than one percent, the material will be determined to be regulated ACM. If the Point-Count Method analysis determines that the concentration of asbestos is one percent or less, the material will be determined to be unregulated and non-asbestos containing.

### 2.1.3 Results

An Asbestos Summary Table and a sample location diagram for Building 1A are included as **Appendix C**. A copy of the analytical laboratory report for Building 1A is included as **Appendix D**.

#### 2.1.3.1 Building 1A

##### *ACM (Confirmed by Sampling and Analysis)*

The following building materials sampled from Building 1A were determined to be ACM based on the definitions provided in current State and Federal regulations:

##### Friable ACM

No building materials sampled from Building 1A were determined to be friable ACM.

##### Non-Friable ACM (Category I)

- ◆ Black mastic on pegboard panel behind white pressboard wall panel on north interior wall (sample 21), approximately 1,000 square feet.
- ◆ Remnant black floor mastic and carpet mastic (sample set 22), approximately 4,075 square feet.
- ◆ Black mastic below 12” gray ceramic floor tile (sample 30), approximately 345 square feet.
- ◆ Black tar on roof membrane (sample 32), approximately 4,415 square feet.

### Non-Friable ACM (Category II)

No building materials sampled from Building 1A were determined to be Category II non-friable ACM.

### *Non-ACM (Confirmed by Sampling and Analysis)*

The following building materials sampled from Building 1A were determined to be non-ACM based on the definitions provided in current State and Federal regulations (see **Appendix C** for specific locations):

- ◆ Display shingles and black tar (samples 1-18).
- ◆ Drywall composite (sample 19).
- ◆ White pressboard wall panel (sample 20).
- ◆ Peghole panel behind white pressboard wall panel (sample 21).
- ◆ Black tar on wall behind drywall (sample 23).
- ◆ White display covering (sample 24).
- ◆ Gray countertop (sample 25).
- ◆ Gray speckle countertop (sample 26).
- ◆ Black tar on concrete block (sample 27).
- ◆ Interior brown door caulk (sample 28).
- ◆ 7" gray ceramic floor tile, grout and bedding (sample 29).
- ◆ 12" gray ceramic floor tile, grout, bedding and yellow mastic (sample 30).
- ◆ Roof shingle and black tar (sample 31).
- ◆ Roof membrane (sample 32).
- ◆ Gray roof vent caulk (sample 33).
- ◆ Brick and mortar (sample 34).
- ◆ Exterior pressboard siding and vapor barrier (sample 35).
- ◆ Exterior gray caulk at base of brick (sample 36).
- ◆ Exterior gray caulk at base of siding (sample 37).
- ◆ Exterior tan window glaze (sample 38).
- ◆ Exterior brown window caulk at base of window (sample 39).
- ◆ Exterior white window caulk alongside of window (sample 40).
- ◆ Exterior black door caulk (sample 41).
- ◆ Gray/clear roof duct putty (sample 42).

### 2.1.3.2 Building 1B

An Asbestos Summary Table and a sample location diagram for Building 1B are included as **Appendix E**. A copy of the analytical laboratory report for Building 1B is included as **Appendix F**.

### ACM (Confirmed by Sampling and Analysis)

The following building materials sampled from Building 1B were determined to be ACM based on the definitions provided in current State and Federal regulations:

#### Friable ACM

- ◆ Off-white w/gray speckles vinyl sheet flooring in 2<sup>nd</sup> floor restrooms (sample 16), approximately 86 square feet.
- ◆ Lower layer of vinyl flooring in 2<sup>nd</sup> floor restrooms (samples 17 and 18), approximately 86 square feet.

#### Non-Friable ACM (Category I)

- ◆ Black mastic on wood wall panel in 2<sup>nd</sup> floor women's restroom (sample 19), approximately 40 square feet.
- ◆ Black tar behind drywall (sample 27), assumed along entire north wall on 1<sup>st</sup> floor, approximately 1,200 square feet.
- ◆ 9" x 9" brown floor tile in 1<sup>st</sup> floor vault (sample 31), approximately 120 square feet.
- ◆ Black mastic beneath 7" ceramic floor tile in the 1<sup>st</sup> floor women's restroom (sample 33), approximately 96 square feet. Asbestos was not detected in the floor tile, grout or bedding; however, if the black mastic is found to be adhering to these materials, these materials should be handled and disposed as ACM.
- ◆ Green flooring in the 1<sup>st</sup> floor lunchroom, hall and communications room (sample 34), approximately 540 square feet.
- ◆ Tan flooring in the 1<sup>st</sup> floor office hall (sample 35), approximately 72 square feet.
- ◆ Brown flooring in 1<sup>st</sup> floor office hall and office 1 (sample 36), approximately 395 square feet.
- ◆ Dark red flooring in the 1<sup>st</sup> floor hall (sample 37), approximately 416 square feet.
- ◆ Silver layer of tarpaper beneath shingles on the roof (sample 53), approximately 2,500 square feet.
- ◆ Brown caulk along shingles on the roof (sample 55), approximately 150 linear feet.
- ◆ Silver/black tar near vent on the metal roof (sample 56), approximately 10 linear feet.
- ◆ Brown/black vent caulk on the metal roof (sample 57), approximately 12 linear feet.
- ◆ Silver layer of flashing on the roof below the stucco (sample 60), approximately 120 square feet.
- ◆ Silver layer of flashing on the roof below the shingles (sample 62), approximately 200 square feet.
- ◆ Silver layer of flashing on the roof (east side – southeast corner) (sample 63), approximately 50 square feet.
- ◆ Silver layer of flashing on the roof (west side along west drive thru) (sample 64), approximately 120 square feet.
- ◆ Silver layer of flashing on the roof (south side along Building 9) (sample 65), approximately 150 square feet.

- ♦ Silver/black skylight flashing on the roof above the west drive thru (sample 68), approximately 48 linear square feet.

#### Non-Friable ACM (Category II)

No building materials sampled from Building 1B were determined to be Category II non-friable ACM.

#### *Assumed ACM*

A total of 18 metal-clad fire doors were observed in Building 1B. Attempts to observe the interior material of the doors were not successful. Therefore, the fire doors must be assumed to be ACM at this time.

#### *Non-ACM (Confirmed by Sampling and Analysis)*

The following building materials sampled from Building 1B were determined to be non-ACM based on the definitions provided in current State and Federal regulations (see **Appendix E** for specific locations):

- ♦ White pressboard wall panel (sample 1).
- ♦ White ceiling material (sample set 2).
- ♦ Gray countertop (sample 3).
- ♦ Gray marble countertop (sample 4).
- ♦ White countertop (sample 5).
- ♦ Gray duct putty (sample 6).
- ♦ Tan duct putty (sample 7).
- ♦ Tan fiberglass wall panel and tan mastic (sample 8).
- ♦ Cloth vibration joint (sample 9).
- ♦ Fiberglass wall insulation (sample 10).
- ♦ Fiberglass ceiling insulation (sample 11).
- ♦ White vinyl baseboard and yellow mastic (sample 12).
- ♦ Gray vinyl baseboard and tan mastic (sample 13).
- ♦ Brown vinyl baseboard and yellow mastic (sample 14).
- ♦ Drywall composite (sample set 15).
- ♦ Tan and gray mastics associated with off-white w/ gray speckles vinyl sheet flooring (sample 16).
- ♦ Mastic associated with lower layer of vinyl sheet flooring (samples 17 and 18).
- ♦ Textured ceiling material (sample set 20).
- ♦ Foam ball insulation (sample set 21).
- ♦ 18" smooth ceiling tile and brown mastic (sample 22).
- ♦ 1' x 1' peghole ceiling tile and brown mastic (sample 23).
- ♦ 2' x 2' gypsum ceiling tile (sample 24).
- ♦ 2' x 2' textured ceiling tile (sample 25).
- ♦ 1' x 1' smooth ceiling tile and mastic (sample 26).

- ◆ Brown ceiling insulation (sample 28).
- ◆ 1' x 1' gray marble floor tile, tan mastic and white floor leveler (sample 29).
- ◆ 6" brown ceramic floor tile, grout and bedding (sample 30).
- ◆ Black and tan mastics associated with 9" x 9" brown floor tile (sample 31).
- ◆ 3" tan ceramic floor tile, grout and bedding (sample 32).
- ◆ 7" tan ceramic floor tile, grout and bedding (sample 33).
- ◆ Tan carpet mastic and black mastic associated with green flooring (sample 34).
- ◆ Tan carpet mastic and black mastic associated with tan flooring (sample 35).
- ◆ Tan carpet mastic and black mastic associated with brown flooring (sample 36).
- ◆ Tan carpet mastic and black mastic associated with dark red flooring (sample 37).
- ◆ Fiberboard floor panels (sample 38).
- ◆ Paper backing beneath fiberboard floor panels (sample 39).
- ◆ Fiberglass pipe insulation (sample set 40).
- ◆ Fiberglass duct insulation (sample set 41).
- ◆ Exterior gray window caulk along frame and stucco (sample 42).
- ◆ Exterior gray and brown window caulk on frame (sample 43).
- ◆ Exterior gray door caulk (sample 44).
- ◆ Stucco (sample set 45).
- ◆ Concrete block (sample 46).
- ◆ Concrete block and foam ball filler (sample 47).
- ◆ Exterior brown window caulk at base of window (sample 48).
- ◆ Exterior white door caulk (sample 49).
- ◆ Exterior brown vent caulk (sample 50).
- ◆ Silver roof duct caulk (sample 51).
- ◆ Roof shingles (sample 52).
- ◆ Black fibrous layer of tarpaper beneath roof shingles (sample 53).
- ◆ Flashing on rooftop HVAC units (sample 54).
- ◆ Gray roof caulk at base of stucco (sample 58).
- ◆ Tar, gravel, fiberboard roof deck material (sample 59).
- ◆ Black tar and black fibrous layer of silver/black flashing at base of stucco (sample 60).
- ◆ Black tar on flashing below shingles (sample 61).
- ◆ Black tar and black fibrous layer of silver/black tar flashing below shingles (sample 62).
- ◆ Black fibrous layer of silver tarpaper roof flashing (sample 63).
- ◆ Black fibrous layer of silver/black roof flashing (sample 64).
- ◆ Black fibrous layer of silver/black flashing (sample 65).
- ◆ Roof deck material over west drive thru (sample 66).
- ◆ Roof flashing over west drive thru (sample 67).

### 2.1.3.3 Building 1C

An Asbestos Summary Table and a sample location diagram for Building 1C are included as **Appendix G**. A copy of the analytical laboratory report for Building 1C is included as **Appendix H**.

#### *ACM (Confirmed by Sampling and Analysis)*

The following building materials sampled from Building 1C were determined to be ACM based on the definitions provided in current State and Federal regulations:

#### Friable ACM

No building materials sampled from Building 1C were determined to be friable ACM.

#### Non-Friable ACM (Category I)

- ◆ Gray/black tar and tarpaper on the northeast corner of the roof (sample 15), approximately 240 square feet.
- ◆ Silver/black tar on the roof stack above the open area (sample 18), approximately 10 linear feet.

#### Non-Friable ACM (Category II)

No building materials sampled from Building 1C were determined to be Category II non-friable ACM.

#### *Assumed ACM*

A total of 5 metal-clad fire doors were observed in Building 1C. Attempts to observe the interior material of the doors were not successful. Therefore, the fire doors must be assumed to be ACM at this time.

#### *Non-ACM (Confirmed by Sampling and Analysis)*

The following building materials sampled from Building 1C were determined to be non-ACM based on the definitions provided in current State and Federal regulations (see **Appendix G** for specific locations):

- ◆ Fiberglass pipe insulation (sample set 1).
- ◆ Fiberglass ceiling insulation (sample 2).
- ◆ Remnant gray wall mastic (sample 3).
- ◆ Interior white wall caulk (sample 4).
- ◆ Glass block window mortar (sample 5).
- ◆ Drywall ceiling (sample 6).
- ◆ 2' x 4' pinhole/divot ceiling tile (sample 7).

- ◆ Brown duct putty (sample 8).
- ◆ Fiberboard behind wood siding (sample 9).
- ◆ Brown exterior door caulk (sample 10).
- ◆ White exterior door caulk (sample 11).
- ◆ Concrete block (sample 12).
- ◆ Roof deck materials (sample 13).
- ◆ Roof flashing (sample 14).
- ◆ Exterior gray skylight caulk (sample 16).
- ◆ Black roof stack tar (sample 17).
- ◆ Clear caulk on roof stack (sample 18).

#### 2.1.3.4 Building 1D

An Asbestos Summary Table and a sample location diagram for Building 1D are included as **Appendix I**. A copy of the analytical laboratory report for Building 1D is included as **Appendix J**.

*ACM (Confirmed by Sampling and Analysis)*

The following building materials sampled from Building 1D were determined to be ACM based on the definitions provided in current State and Federal regulations:

##### Friable ACM

No building materials sampled from Building 1D were determined to be friable ACM.

##### Non-Friable ACM (Category I)

- ◆ Black tar on silver shingle/tarpaper on roof beneath membrane (sample 14), approximately 4,480 square feet.

##### Non-Friable ACM (Category II)

No building materials sampled from Building 1D were determined to be Category II non-friable ACM.

*Non-ACM (Confirmed by Sampling and Analysis)*

The following building materials sampled from Building 1D were determined to be non-ACM based on the definitions provided in current State and Federal regulations (see **Appendix I** for specific locations):

- ◆ Brown duct putty (sample 1).
- ◆ Fiberglass ceiling insulation (sample 2).
- ◆ Gray feather countertop (sample 3).
- ◆ Brick and mortar (sample 4).
- ◆ Drywall composite (sample 5).

- ◆ Fiberboard behind wood siding (sample 6).
- ◆ Exterior fiberboard wall panel (sample 7).
- ◆ Exterior gray door caulk (sample 8).
- ◆ Concrete block (sample 9).
- ◆ Black roof stack tar (sample 10).
- ◆ Clear/silver caulk on roof dust collector (sample 11).
- ◆ Black tar on roof dust collector (sample 12).
- ◆ Roof deck membrane, black seam tar and fiberboard underlay (sample 13).
- ◆ Silver shingle/tarpaper (sample 14).
- ◆ Green shingle/tarpaper and black tar (sample 15).

#### 2.1.3.5 Building 5

An Asbestos Summary Table and a sample location diagram for Building 5 are included as **Appendix K**. A copy of the analytical laboratory report for Building 5 is included as **Appendix L**.

#### *ACM (Confirmed by Sampling and Analysis)*

The following building materials sampled from Building 5 were determined to be ACM based on the definitions provided in current State and Federal regulations:

#### Friable ACM

No building materials sampled from Building 5 determined to be friable ACM.

#### Non-Friable ACM (Category I)

- ◆ Tarpaper on roof (sample 7), approximately 15,675 square feet.

#### Non-Friable ACM (Category II)

No building materials sampled from Building 5 were determined to be Category II non-friable ACM.

#### *Non-ACM (Confirmed by Sampling and Analysis)*

The following building materials sampled from Building 5 were determined to be non-ACM based on the definitions provided in current State and Federal regulations (see **Appendix K** for specific locations):

- ◆ Stucco (sample set 1).
- ◆ Concrete block (sample 2).
- ◆ Drywall (sample 3).
- ◆ Interior gray door caulk (samples 4 and 5).
- ◆ Exterior gray door caulk (sample 6).
- ◆ Roof shingles (sample 7).

### 2.1.3.6 Building 6

An Asbestos Summary Table and a sample location diagram for Building 6 are included as **Appendix M**. A copy of the analytical laboratory report for Building 6 is included as **Appendix N**.

*ACM (Confirmed by Sampling and Analysis)*

#### Friable ACM

No building materials sampled from Building 6 determined to be friable ACM.

#### Non-Friable ACM (Category I)

- ◆ Black mastic associated with 1' x 1' tan marble floor tile located in the lunchroom/locker room (sample 16), approximately 630 square feet. Asbestos was not detected in the floor tile; however, since the tile is adhered by asbestos-containing mastic, the tile should be handled and disposed as ACM.
- ◆ Silver layer on roof flashing (sample 26), approximately 1,350 linear feet.

#### Non-Friable ACM (Category II)

No building materials sampled from Building 6 were determined to be Category II non-friable ACM.

*Assumed ACM*

One metal-clad fire door was observed in Building 6 at the mechanical room. Attempts to observe the interior material of the door were not successful. Therefore, the fire door must be assumed to be ACM at this time.

*Non-ACM (Confirmed by Sampling and Analysis)*

The following building materials sampled from Building 6 were determined to be non-ACM based on the definitions provided in current State and Federal regulations (see **Appendix M** for specific locations):

- ◆ Fiberglass duct insulation (sample set 1).
- ◆ Fiberglass pipe insulation (sample set 2).
- ◆ Tan countertop (sample 3).
- ◆ Green countertop (sample 4).
- ◆ Off-white countertop (sample 5).
- ◆ Gray countertop (sample 6).
- ◆ Maroon vinyl baseboard and black and yellow mastics (sample 7).
- ◆ 4" white ceramic wall tile and yellow mastic (sample 8).
- ◆ Concrete block and foam ball filler (sample 9).

- ◆ Gray sink undercoat (sample 10).
- ◆ Fiberglass ceiling insulation (sample 11).
- ◆ Drywall composite (sample 12).
- ◆ Carpet mastic (sample 13).
- ◆ Interior tan door caulk (sample 14).
- ◆ 6" brown ceramic floor tile (sample 15).
- ◆ 2' x 2' pinhole/divot ceiling tile (sample 17).
- ◆ 2' x 2' pinhole/fissure ceiling tile (sample 18).
- ◆ 2' x 2' chicken scratch ceiling tile (sample 19).
- ◆ 2' x 2' pinhole/fissure ceiling tile (sample 20).
- ◆ Exterior gray door caulk (sample 21).
- ◆ Exterior tan wall caulk (sample 22).
- ◆ Exterior decorative concrete block (sample 23).
- ◆ Exterior gray wall caulk (sample 24).
- ◆ Roof deck material (sample 25).
- ◆ Black fibrous layer of roof flashing (samples 26 and 29).
- ◆ Black roof deck tar (sample 27).
- ◆ Roof deck fiberboard (sample 28).
- ◆ Gray wall on roof (sample 30).
- ◆ Black wall caulk on roof (sample 31).

#### 2.1.3.7 Building 9

An Asbestos Summary Table and a sample location diagram for Building 9 are included as **Appendix O**. A copy of the analytical laboratory report for Building 9 is included as **Appendix P**.

##### *ACM (Confirmed by Sampling and Analysis)*

No building materials sampled from Building 9 were determined to be ACM based on the definitions provided in current State and Federal regulations.

##### *Assumed ACM*

A total of 5 metal-clad fire doors were observed in Building 9. Attempts to observe the interior material of the doors were not successful. Therefore, the fire doors must be assumed to be ACM at this time.

##### *Non-ACM (Confirmed by Sampling and Analysis)*

The following building materials sampled from Building 9 were determined to be non-ACM based on the definitions provided in current State and Federal regulations (see **Appendix O** for specific locations):

- ◆ Remnant black floor tar (sample 1).
- ◆ Fiberglass pipe insulation (sample set 2).
- ◆ Drywall (sample 3).
- ◆ Gray countertop (sample 4).
- ◆ Exterior white wall caulk (sample 5).
- ◆ Exterior gray wall caulk (sample 6).
- ◆ Exterior tan door caulk (sample set 7).
- ◆ Concrete block (sample 8).
- ◆ Roof deck materials (sample 9).
- ◆ Roof flashing (sample 10).

#### 2.1.4 Limitations

The roof of Building 5 was only accessed along the edges of the eastern and western sides of the building due to height restrictions and roof integrity concerns. Therefore, there is a potential for additional ACM-containing roofing materials on Building 5 (as discussed in Section 2.1.3.5, tarpaper on the roof was identified as ACM). Any additional roofing materials that may be encountered during demolition must be assumed to be ACM until they can be sampled and analyzed.

As previously discussed, metal-clad fire doors were observed on the Site. Attempts to observe the interior material of the doors were not successful. Therefore, the fire doors must be assumed to be ACM at this time.

Electrical power to the buildings had not been disconnected at the time of the site visit. Therefore, Peer did not sample wire coverings or disassemble electrical switchboxes, fuse boxes or panels in the structures for assessment and material sampling. Peer did not disassemble furnaces, water heaters, other appliances, or operational equipment. There is a potential for ACM components inside of this equipment.

Based on these limitations, the quantities listed in this inventory reflect the visibility available at the time of the survey. All quantities in this inventory are estimations and should not be considered exact measurements when used for obtaining abatement bids.

## 2.2 HAZARDOUS MATERIALS

### 2.2.1 General Information

A walk-through reconnaissance of the structures was conducted to identify and inventory potential hazardous materials or materials that have special disposal requirements that should be removed prior to demolition. These materials include, but are not limited to, hazardous substances, petroleum products, PCB-containing light ballasts, mercury-containing lights and switches, and refrigerants.

## 2.2.2 Observations & Results

The following potential hazardous equipment and materials and potential environmental concerns were identified in the structures:

### *Building 1A*

- ◆ 348 4' fluorescent lamps.
- ◆ 174 4' fluorescent lamp fixtures with ballasts.
- ◆ 2 compact fluorescent lamps.
- ◆ 2 exit/emergency lamp fixtures.
- ◆ 1 security system keypad panel.
- ◆ Security cameras.
- ◆ 5 smoke alarms.
- ◆ 9 electrical panels/boxes/switches.
- ◆ 2 fire alarm/strobe fixtures.
- ◆ 1 fire pull alarm.
- ◆ 3 fire extinguishers.
- ◆ 8 hydraulic door closers.
- ◆ 2 thermostats.
- ◆ 1 humidity control switch.
- ◆ 11 wall-mounted baseboard heaters.
- ◆ 2 wall-mounted area heaters.
- ◆ 1 ceiling-mounted area heater.
- ◆ 2 roof-mounted HVAC units.

### *Building 1B*

- ◆ 1 exterior pad-mounted transformer.
- ◆ 5 interior high intensity lamps.
- ◆ 1 exterior high intensity lamp.
- ◆ 591 4' fluorescent lamps.
- ◆ 182 4' fluorescent lamp fixtures with ballasts.
- ◆ 84 8' fluorescent lamps.
- ◆ 52 8' fluorescent lamp fixtures with ballasts.
- ◆ 9 compact fluorescent lamps.
- ◆ 16 exit/emergency light fixtures.
- ◆ 62 smoke alarms.
- ◆ 9 electrical panels/boxes/switches.
- ◆ 2 electric garage openers.
- ◆ 19 fire alarms/strobes.
- ◆ 11 fire extinguishers.
- ◆ 14 hydraulic door closers.

- ◆ 1 motion-activated door.
- ◆ 2 water heaters.
- ◆ 9 thermostats.
- ◆ 4 air freshener units.
- ◆ 2 wall-mounted area heaters.
- ◆ 1 furnace.
- ◆ 1 ceiling-mounted area heater.
- ◆ 1 oven exhaust hood.
- ◆ 2 drinking fountains.
- ◆ 1 large exhaust fan.
- ◆ 6 roof-mounted HVAC units.
- ◆ Interior security system.
- ◆ Exterior security cameras.

### *Building 1C*

- ◆ 20 interior high intensity lamps.
- ◆ 1 exterior high intensity lamp.
- ◆ 79 4' fluorescent lamps.
- ◆ 36 4' fluorescent lamp fixtures with ballasts.
- ◆ 14 8' fluorescent lamps.
- ◆ 7 8' fluorescent lamp fixtures with ballasts.
- ◆ 1 exit/emergency lamp fixture.
- ◆ 5 smoke alarms.
- ◆ 1 fire alarm/strobe.
- ◆ 12 electrical panels/boxes/switches.
- ◆ 7 electric garage openers.
- ◆ 6 fire extinguishers.
- ◆ 2 hydraulic door closers.
- ◆ 4 thermostats.
- ◆ 5 ceiling-mounted area heaters.

### *Building 1D*

- ◆ 13 interior high intensity lamps.
- ◆ 2 4' fluorescent lamps.
- ◆ 1 4' fluorescent lamp fixtures with ballast.
- ◆ 20 8' fluorescent lamps.
- ◆ 10 8' fluorescent lamp fixtures with ballasts.
- ◆ 1 exit/emergency lamp fixture.
- ◆ 44 electrical panels/boxes/switches.
- ◆ 2 electric garage openers.
- ◆ 4 fire extinguishers.
- ◆ 2 thermostats.

- ◆ 1 HVAC unit.
- ◆ 3 ceiling-mounted heaters.
- ◆ 1 fire pull alarm.
- ◆ 1 microwave oven.
- ◆ 1 stereo.
- ◆ 1 television.
- ◆ 1 electric motor.
- ◆ 2 quarts of 409 cleaner.
- ◆ 1 quart 10W-30 motor oil.

#### *Building 5*

- ◆ 8 interior high intensity lamps.
- ◆ 2 exterior high intensity lamps.
- ◆ 1 exterior pad-mounted transformer.
- ◆ 1 exit sign fixture.
- ◆ 33 smoke alarms.
- ◆ 2 electrical panels/boxes/switches.
- ◆ 2 electric garage openers.
- ◆ 2 fire extinguishers.
- ◆ 1 hydraulic door closer.
- ◆ 2 large exhaust fans.

#### *Building 6*

- ◆ 53 interior high intensity lamps.
- ◆ 9 exterior high intensity lamps.
- ◆ 2 2' fluorescent lamps.
- ◆ 1 2' fluorescent lamp fixture with ballast.
- ◆ 62 4' fluorescent lamps.
- ◆ 17 4' fluorescent lamp fixtures with ballasts.
- ◆ 1 smoke alarm.
- ◆ 6 electrical panels/boxes/switches.
- ◆ 7 electric garage openers.
- ◆ 6 fire extinguishers.
- ◆ 11 hydraulic door closers.
- ◆ 1 water heater.
- ◆ 1 interior air conditioning unit.
- ◆ 3 thermostats.
- ◆ 1 air freshener unit.
- ◆ 1 wall-mounted area heater.
- ◆ 1 gallon of bleach.
- ◆ 1 gallon Bausch & Lomb Sight Saver.
- ◆ 2 cans of spray paint.

- ◆ 1 compressor.
- ◆ 1 furnace.
- ◆ 1 electric heater.
- ◆ 2 large exhaust fans.
- ◆ 1 exterior electric sign.
- ◆ Exterior security cameras.

### *Building 9*

- ◆ 6 exterior pole-mounted transformers.
- ◆ 1 interior dry transformer.
- ◆ 1 exterior high intensity lamp.
- ◆ 111 4' fluorescent lamps.
- ◆ 30 4' fluorescent lamp fixtures with ballasts.
- ◆ 4 8' fluorescent lamps.
- ◆ 2 8' fluorescent lamp fixtures with ballasts.
- ◆ 81 smoke alarms.
- ◆ 11 electrical panels/boxes/switches.
- ◆ 3 electric garage openers.
- ◆ 5 fire extinguishers.
- ◆ 5 emergency light fixtures.
- ◆ 2 hydraulic door closers.
- ◆ 1 water heater.

In addition, various solid wastes including, but not limited to, road signs, benches, pallets, furniture, and empty 55-gallon drums, were observed inside Building 9. These materials should also be properly removed or recycled and/or disposed.

### 2.2.3 Limitations

The method of the hazardous materials inventory consisted of walking through all areas of the structures and making observations for components that typically contain hazardous substances that are incidental to the structures. Peer recommends that these materials and any associated containers for these materials be removed for appropriate recycling and/or disposition prior to initiating demolition activities.

As previously discussed, Peer did not disassemble furnaces, water heaters, other appliances, electrical equipment, or operational equipment. There is a potential for mercury switches to be part of this equipment.

## 2.3 LEAD-BASED PAINT

### 2.3.1 General Information and Definitions

Testing for lead-based paint was conducted. The testing was limited to painted surfaces that were in fair to poor condition and that, if determined to be lead-based paint, would require stabilization prior to demolition (e.g., lead that is not attached to the substrate must be managed/disposed in accordance with applicable hazardous waste and/or solid waste rules and regulations and cannot be managed as normal demolition material). In addition, concrete floors, walls, and/or ceilings were tested in case the concrete is to be recycled during demolition.

Based on current regulatory definitions, lead-based paint is defined as paint containing lead concentrations equal to or greater than 1.0 milligrams per square centimeter (mg/cm<sup>2</sup>) when using a Niton XL X-ray fluorescence (XRF) analyzer. The XRF provides the measured lead concentration in weight of lead per unit area. Calibration checks of the XRF were frequently conducted and are recorded with the test data included in **Appendix Q**. The test results along with test location, component, substrate, date, and exact time are recorded on the tables in **Appendix Q**. No paint chip sampling or laboratory analysis was performed as part of the targeted sampling activities. Diagrams depicting the test locations are included as **Appendix R**.

Interior sides of the rooms are based upon the direction facing while conducting the testing. Side A faces north, Sides B faces east (Sibley Street NE), Side C faces south (8<sup>th</sup> Avenue NE), and Side D faces west (Mississippi River). Common and exterior areas are specified using the same method.

### 2.3.2 Observations & Results

Testing for lead-based paint was conducted on painted, glazed, and stained surfaces at the Site. Surfaces observed to be in fair to poor condition were specifically targeted during this survey. A copy of the testing results is included in **Appendix Q** (test results determined to be lead-based paint are in bold and highlighted).

#### *Building 1A*

Coated surfaces in fair to poor condition included exterior wood siding trim. Based on the results of the limited testing, lead-based paint was not identified.

#### *Building 1B*

Coated surfaces in fair to poor condition included interior wood walls, interior concrete floor stripes, exterior wood window components, exterior wood door components, and

exterior wood wall components. In addition, intact coated concrete floors, walls, and/or ceilings were tested in case the concrete is to be recycled during demolition. Based on the results of the limited testing, lead-based paint was identified on the following component:

- ♦ White-painted interior wood wall (Tests 26 and 27) on wall A in the south drive thru area, approximately 2,000 square feet.

A test on a concrete wall (Side C) in 1<sup>st</sup> floor vault (Test 7) tested positive for lead; however, the results of two subsequent confirmatory retests (Tests 9 and 10) on that wall were negative for lead. It appears that Test 7 was a false positive as all additional tests conducted on concrete wall throughout the entire site were negative for lead.

### *Building 1C*

Coated surfaces in fair to poor condition included interior and exterior concrete block walls, interior wood walls, and interior metal doors. In addition, intact coated concrete floors, walls, and/or ceilings were tested in case the concrete is to be recycled during demolition. Based on the results of the limited testing, lead-based paint was identified on the following component:

- ♦ White-painted interior wood wall (Test 48) on wall B in the south loading dock, approximately 60 square feet.
- ♦ Yellow-painted stripe on interior concrete floor (Test 55) in the wood shop, approximately 75 linear feet.
- ♦ Yellow-painted stripe on interior concrete floor (Test 64) in the north loading dock, approximately 40 square feet.

### *Building 1D*

Coated surfaces in fair to poor condition included exterior concrete block walls, exterior brick walls, exterior wood walls, exterior overhang beam, and exterior wood columns. In addition, intact coated concrete floors, walls, and/or ceilings were tested in case the concrete is to be recycled during demolition. Based on the results of the limited testing, lead-based paint was identified on the following component:

- ♦ White-painted interior wood wall (Test 66) on wall B in the shop area, approximately 100 square feet.

### *Building 5*

Coated surfaces in fair to poor condition included exterior concrete block walls, exterior wood columns, and exterior roof components. In addition, intact coated concrete floors, walls, and/or ceilings were tested in case the concrete is to be recycled during

demolition. Based on the results of the limited testing, lead-based paint was not identified.

### *Building 6*

Coated surfaces in fair to poor condition included interior stripes on concrete floors, exterior door wood components, and exterior concrete overhang ceilings. In addition, intact coated concrete floors, walls, and/or ceilings were tested in case the concrete is to be recycled during demolition. Based on the results of the limited testing, lead-based paint was identified on the following component:

- ◆ Yellow-painted interior concrete door bollard (Test 152) on wall B in Bay 1, approximately 96 square feet.
- ◆ Yellow-painted stripe on interior concrete floor (Test 153) in Bay 1, approximately 80 linear feet.
- ◆ Yellow-painted interior concrete door bollard (Test 182) on wall D in Bay 2, approximately 48 square feet.
- ◆ Yellow-painted exterior concrete column (Test 215) on the north side of Building 6, approximately 200 square feet.

### *Building 9*

Coated surfaces in fair to poor condition included exterior concrete block walls and interior stripes on asphalt floors. In addition, intact coated concrete floors, walls, and/or ceilings were tested in case the concrete is to be recycled during demolition. Based on the results of the limited testing, lead-based paint was identified on the following component:

- ◆ Yellow-painted stripe on interior asphalt floor (Test 136), approximately 360 linear feet.
- ◆ Yellow-painted stripe on interior concrete floor (Test 140), approximately 200 linear feet.

### 2.3.3 Limitations

The testing conducted was not intended to represent a lead paint inspection as defined in accordance with the U.S. Department of Housing and Urban Development (HUD) document entitled “Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing – Chapter 7: Lead-Based Paint Inspection, 1997 Revision”. In addition, the observations and testing conducted were not intended to represent a comprehensive survey of all painted surfaces and was not intended to represent regulated lead work as defined by the MDH.

## 2.4 PCBS IN CAULKING

### 2.4.1 General Information and Definitions

Peer collected fifteen representative samples (C-1 through C-15) of exterior caulking from the buildings on the Site on June 23, 2011. The samples were collected from ground level assessable areas. Thirteen samples were submitted to TestAmerica for analytical testing of PCBs by EPA Method 8082.

### 2.4.2 Observations and Results

A copy of the laboratory analytical report and chain-of-custody form is included in **Appendix S**. PCBs were not detected in the samples of caulk analyzed at or above the laboratory reporting limits. A table summarizing the type and locations of the caulk samples is included as **Table 1**. Although chromatograph interferences prevented an acceptable reporting limit for sample C-14, Building 6 was constructed in 1985, following the ban on PCBs in 1979.

## 3.0 CONCLUSIONS AND RECOMMENDATIONS

The following recommendations are provided based on the results of this hazardous materials inventory:

- ◆ Friable and Category I and Category II non-friable ACM was identified in the structures as listed in Section 2.1.3.
- ◆ A licensed asbestos abatement contractor should remove all identified and assumed Category I non-friable ACM prior to initiating building demolition. If left in place, Category I non-friable ACM must be segregated and disposed of as asbestos-containing waste during demolition.
- ◆ A licensed asbestos abatement contractor must remove all identified friable and Category II non-friable ACM prior to initiating building demolition.
- ◆ Any unidentified suspect ACM that may be encountered during demolition activities should be assumed to contain asbestos until they are sampled and analyzed.
- ◆ All hazardous equipment, hazardous substances and/or petroleum products (as listed in Section 2.2.2) should be removed and properly disposed of prior to building demolition.

- ♦ All lead-based paint determined to be in poor condition and not adhering to its substrate (as listed in Section 2.3.2) is required to be stabilized prior to building demolition per state and federal regulations regarding management of lead-contaminated waste.
- ♦ Lead-based paint residues generated by stabilization or removal must be managed/disposed in accordance with applicable hazardous waste and/or solid waste rules and regulations and cannot be managed as normal demolition material.
- ♦ PCBs were not detected in the representative caulk samples collected at the Site as outlined in Section 2.4 (see **Appendix S** and **Table 1** for analytical results).
- ♦ If the demolition plans should change (i.e., controlled burn), environmental needs for the Site need to be revisited.

#### 4.0 STANDARD OF CARE & QUALIFICATIONS

Services performed by Peer have been conducted in accordance with generally recognized industry standards and current MPCA and MDH guidelines, where applicable. The services performed by Peer have been conducted with the level of care and skill ordinarily exercised by reputable members of the profession, practicing in the same locality under similar budget and time constraints. No other warranty is made or intended.


A summary of corporate and individual qualifications for Peer and the individuals associated with this project is included in **Appendix T**.

Prepared by:



Kelly W. Brown  
Senior Environmental Professional  
MDH Asbestos Inspector No.: I3036  
MDH Lead Risk Assessor No.: 188

Reviewed by:



Robert J. Rykken, P.E., P.G.  
Senior Engineer

TABLE 1  
 LABORATORY ANALYTICAL RESULTS – PCBs in CAULK  
 SCHERER BROS. HAZARDOUS MATERIALS SURVEY

Sample No.	Description	PCB Concentrations (µg/kg)
C-1	Light grey, door trim, south side of building 1D.	< 3,100
C-2	Light tan, between wood siding and corner wood trim, west side of building 1C	< 2,900
C-3	Light tan, between block and wood siding, north intersection of buildings 1C and 1B.	NA - same as C-2
C-4	Grey, along metal door trim, north side of building 1B.	< 3,100
C-5	Grey, between lap siding and corner trim, north side of building 1B.	NA - same as C-4
C-6	White/translucent, between lap siding and corner trim, north side of building 1A.	< 2,600
C-7	Dark brown, between metal door and trim, north side of building 1A.	NA - same as C-8
C-8	Dark brown, between lap siding and wood trim, north side of building 1A	< 3,600
C-9	Brown, between window and siding, north side of building 1A.	< 3,300
C-10	White/light grey, between window and siding, north side of building 1A.	< 2,800
C-11	Grey, along window bay and sill block, east side of building 1A.	<4,200
C-12	Dark brown, along window trim, east side of building 1A.	< 3,800
C-13	Grey, metal door trim, east side of building 6.	< 28,000
C-14	Yellow, between concrete blocks, south side of building 6.	< 290,000*
C-15	Grey, metal door trim, west side of building 6.	< 3,100

\* Laboratory indicated this sample is primarily composed of silicone.

NA = Not Analyzed

µg/kg = microgram per kilogram = parts per billion



SiteBuildings.dwg



PROJECT #: 20074

SITE BUILDINGS

JULY 2011

FORMER SCHERER BROS LUMBER  
MINNEAPOLIS, MINNESOTA

FIGURE

1

FIGURE 2 - OBLIQUE VIEW OF BUILDING LAYOUT



NORTH →



**APPENDIX A**



Minnesota  
Pollution  
Control  
Agency

Metro District,  
Regular  
Facilities  
Section

# Guidance for the Removal, Transport, and Disposal of Category I Asbestos-Containing Materials

Air Quality/Asbestos Program/#4.04/December 2000

This document offers guidance on the removal, transport, and disposal of Category I Asbestos-Containing Materials (ACM) as defined by the asbestos National Emission Standards for Hazardous Air Pollutants (asbestos NESHAP), 40 Code of Federal Regulations (CFR) pt. 61, subp. M, which has been incorporated into Minn. R. 7011.9920.

## What is Category I ACM

Category I ACM consists of asbestos-containing gaskets, resilient floor coverings (including vinyl asbestos tile and linoleum), and asphalt roofing products that contain greater than one percent asbestos using the method described in appendix A, subpart F, 40 CFR Part 763, section 1, Polarized Light Microscopy.

## When does the Asbestos Neshap Apply

Category I ACM is regulated by the asbestos NESHAP if it is or will become friable due to the forces expected to act on it. Friable ACM is any ACM that can be crushed, crumbled, pulverized, or reduced to powder by hand pressure when dry. Also, any sanding, cutting, grinding, abrading, or intentional burning of Category I ACM will render the ACM regulated.

Category I ACM that is subjected to forces or removal methods that would crush, crumble, pulverize, or reduce the Category I ACM to a powder by sanding, cutting, grinding, or abrading, including the use of mechanical chippers, is considered

Regulated Asbestos-Containing Material (RACM) and therefore, must be removed by licensed asbestos abatement contractors using specific work practice controls.

If any of the demolition materials are to be recycled it is necessary to remove any Category I ACM that may be present. The recycling process could result in previously nonfriable Category I ACM becoming crushed, crumbled, or reduced to a powder. If the Category I ACM is not removed prior to demolition then the building materials containing, mixed in with, or coated with Category I ACM may not be used for recycle.

## Removal of Category I ACM

The first consideration in your renovation must be the determination of what materials are present that contain asbestos. Certain building materials have been known to contain asbestos (i.e. 9"X 9" floor tiles), but others must be tested to determine if the material contains asbestos. Once you have identified a Category I ACM in your renovation, the next consideration is the method of removal. If the removal involves quantities greater than 160 square feet, then the following procedures must be followed:

- A) Friable ACM must be removed by licensed asbestos removal contractors. Category I ACM that is able to be crushed or crumbled by hand pressure is friable. This determination must be made prior to any other regarding the





removal of the Category I ACM. The Minnesota Pollution Control Agency (MPCA) and the U.S. Environmental Protection Agency maintain that in most cases the asbestos-containing paper backing of a linoleum product is considered to be friable material. If you elect to remove *nonfriable* Category I ACM the removal must be done in such a manner that it does not cause the Category I ACM to be crushed, crumbled, pulverized, or reduced to powder or subject the ACM to any sanding, cutting, grinding, or abrading rendering the Category I ACM to become RACM. Examples of removal methods that would render the Category I ACM to RACM are shot blasting, mechanical chipping, intentional burning, or specific grinding, sanding, cutting, or abrading.

- B) Nonfriable Category I ACM that is removed by hand tools and not subject to extensive breakage may be removed by nonlicensed contractors. The removal must be careful to keep the Category I ACM as intact as possible. For example, the use of solvents, heat machines, or dry ice to loosen Category I ACM nonfriable floor tiles are examples of removal methods that are not likely to cause the Category I ACM to become RACM.
- C) The MPCA reminds you that asbestos removal projects may be subject to other applicable rules and regulations regarding asbestos removal and disposal. Removal of asbestos is also governed by:
  - 1) 29 CFR Parts 1910 et. al., Occupational Safety and Health Administration (OSHA) laws; and
  - 2) Minn. R. 4620.3000 - 4620.3700, Asbestos Abatement Rules, administered by the Minnesota Department of Health. For more info call (651) 215-0900.
- D) The determination of who is allowed to remove Category I ACM is dependent on the removal method used and the quantity of ACM involved. Proceeding with an incorrect understanding of applicable rules, regulations, or standards could lead you to be out of compliance and subject you to an enforcement action that could potentially include monetary penalties.

## Packaging and Transport of Category I ACM

- A) All Asbestos-Containing Waste Material (ACWM) must be adequately wet, packaged in leak-tight containers, and appropriately labeled with asbestos warning signs and waste generator labels.
- B) The MPCA recommends that all Category I ACM be packaged and transported in the same manner as RACM and reminds you that approved landfills will only accept ACWM that has been properly wetted, packaged, and manifested.
- C) Some types of Category I ACM may have sharp edges and will need to be packaged to avoid any further breakage of the ACWM or puncturing or tearing of the containers.
- D) Asbestos is considered a hazardous air pollutant and a class 9 hazardous waste. Proper labeling and transportation of ACWM includes identification of it as a class 9 hazardous waste and proper placards placed on the vehicle during the loading and unloading of ACWM.

## Disposal of Asbestos-Containing Waste Material

- A) All ACWM must be disposed of at a site approved by the U.S. Environmental Protection Agency which is operated in accordance with 40 CFR § 61.154.
- B) For a complete listing of landfills currently approved to receive ACWM in Minnesota, please contact the MPCA asbestos team.

## Category I ACM in Demolition Projects

Category I ACM may remain in place during normal demolition as long as the Category I ACM is nonfriable, in good condition, and will not specifically be subjected to sanding, cutting, grinding, abrading, or intentional burning. As a reminder, you are advised that all ACM other than Category I ACM cannot remain in place for demolition and must be removed prior to demolition or any activity that would break up, disturb, dislodge, or preclude access to the material.



If you have any questions regarding the classification, removal, transport, disposal, or any questions regarding asbestos rules, regulations, or standards, please feel free to contact the MPCA asbestos team at the numbers below:

(651) 296-6300

(800) 657-3864

This guidance document is not intended as a substitute for reading the rules or regulations and making your own independent determination of its applicability to your asbestos removal or demolition project. Examples in the guidance document do not represent an exhaustive listing of projects or removal methods to which the regulation might apply.

**MPCA Web site:** <http://www.pca.state.mn.us>



**APPENDIX B**



Minnesota  
Pollution  
Control  
Agency

Metro District,  
Regular  
Facilities  
Section

# Guidance for the Removal, Transport, and Disposal of Category II Asbestos-Containing Materials

Air Quality/Asbestos Program/#4.05/January 2002

This document offers guidance on the removal, transport, and disposal of Category II Asbestos-Containing Materials (ACM) as defined by the asbestos National Emission Standards for Hazardous Air Pollutants (asbestos NESHAP), 40 Code of Federal Regulations (CFR) pt. 61, subp. M, which has been incorporated into Minn. R. 7011.9920.

## What is Category II ACM

Category II ACM consists of any material, excluding Category I nonfriable ACM (i.e. floor tile, linoleum, asphalt roofing products), containing more than one percent asbestos as determined using the methods specified in appendix A, subpart F, 40 CFR part 763, section 1, Polarized Light Microscopy that, when dry, cannot be crumbled, pulverized or reduced to a powder by hand pressure. The most common form of Category II ACM is cementitious asbestos board, which is often referred to by its trade name "Transite®." Other Category II ACM includes but is not limited to, Transite® shingles and siding, asbestos cement, asbestos putties, asbestos sealants, and certain asbestos-containing adhesives.

## When Does the Asbestos NESHAP Apply

Category II ACM is regulated by the asbestos NESHAP if it is or will become friable and/or crushed, crumbled and reduced to a powder, due to the forces expected to act on the ACM during a

renovation or demolition project. Friable ACM is any ACM that can be crushed, crumbled, pulverized, or reduced to powder by hand pressure when dry.

Category II ACM that is going to be or has been subjected to demolition forces or removal methods that would crush, crumble, pulverize, or reduce the Category II ACM to a powder including sanding, cutting, grinding, abrading, or intentional burning, is considered Regulated Asbestos-Containing Material (RACM) and therefore, must be removed by licensed asbestos abatement contractors using specific work practice methods.

## Removal of Category II ACM

The first consideration in your renovation or demolition project must be the determination of what materials are present that contain asbestos. Certain building materials have been known to contain asbestos (i.e. slate-like siding on homes) but others must be tested to determine if the material contains asbestos. Once you have identified a Category II ACM in your renovation or demolition project, the next considerations are the quantity of ACM and the methods of removal. If the removal involves quantities greater than 160 square feet, then the following procedures must be followed:

- A) Friable ACM must be removed by licensed asbestos removal contractors. Category II ACM that is able to be





crushed or crumbled by hand pressure is friable. The determination of friability must be made prior to any other regarding the removal of the Category II ACM. If you elect to remove nonfriable Category II ACM, the removal must be done in such a manner that does not cause the Category II ACM to be crushed, crumbled, pulverized, or reduced to powder and does not subject the ACM to any sanding, cutting, grinding, or abrading which would cause the Category II ACM to become RACM. Examples of removal methods that would render the Category II ACM to RACM are smashing it, dropping it to the ground, intentional burning, subjecting it to crushing by heavy machinery, or specific grinding, sanding, cutting, or abrading.

- B) Nonfriable Category II ACM that is carefully removed by hand tools and not subject to extensive breakage may be removed by nonlicensed contractors. During the removal, care must be taken to keep the Category II ACM as intact as possible. For example, in removal of Category II ACM panels, the bolts or nails holding the panels in place can be removed first allowing for the panel to be removed intact which is not likely to cause the Category II ACM to become RACM.
- C) The Minnesota Pollution Control Agency reminds you that asbestos removal projects may be subject to other applicable rules and regulations regarding asbestos removal and disposal. Removal of asbestos is also governed by:
  - 1) 29 CFR Parts 1910 et. al., Occupational Safety & Health Administration (OSHA) laws; and
  - 2) Minn. R. 4620.3000 - 4620.3700, Asbestos Abatement Rules, administered by the Minnesota Department of Health. For more info call (651) 215-0900.
- D) The determination of who is allowed to remove Category II ACM is dependent on the removal method used and the quantity of ACM involved. Proceeding with an incorrect understanding of applicable rules, regulations, or standards could lead you to be out of compliance and subject you to an enforcement action that could potentially include monetary penalties.

## Packaging and Transport of Category II ACM

- A) All Asbestos-Containing Waste Material (ACWM) must be adequately wet, packaged in leak-tight containers, and appropriately labeled with asbestos warning signs and waste generator labels.
- B) All Category II ACM must be packaged and transported in the same manner as RACM. In addition, landfills will only accept ACWM that has been properly wetted, packaged, and manifested.
- C) Some types of Category II ACM may have sharp edges and will need to be packaged to avoid any further breakage of the ACWM or puncturing or tearing of the containers.
- D) Asbestos is considered a hazardous air pollutant and a class 9 hazardous waste. Proper labeling and transportation of ACWM includes identification of it as a class 9 hazardous waste and proper placards placed on the vehicle or dumpster. Asbestos warning signs must be placed on the vehicle or dumpster during the loading and unloading of ACWM in accordance with 40CFR 61.150(c).

## Disposal of Asbestos-Containing Waste Material

- A) All ACWM must be disposed of at a site approved by the U.S. Environmental Protection Agency which is operated in accordance with 40 CFR § 61.154.
- B) For a complete listing of landfills currently approved to receive ACWM in Minnesota please contact the MPCA asbestos team.

## Category II ACM in Demolition Projects

The forces of a demolition project can and will cause Category II ACM to be crushed, crumbled, and reduced to a powder. Therefore, in a demolition project all Category II ACM is considered to be RACM and must be removed prior to the commencement of demolition.



If you have any questions regarding the classification, removal, transport, disposal, or any questions regarding asbestos rules, regulations, or standards, please feel free to contact the MPCA asbestos team at the numbers below. If you intend to remove Category II ACM on your own please call for instructions specific to your situation.

(651) 296-6300

(800) 657-3864

This guidance document is not intended as a substitute for reading the rules or regulations and making your own independent determination of their applicability to your asbestos removal or demolition project. Examples in this guidance document do not represent an exhaustive listing of projects or removal methods to which the regulation might apply.

**MPCA Web site:** <http://www.pca.state.mn.us>



**APPENDIX C**

<b>ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 1A, Minneapolis, MN</b>					
<b>SAMPLE REFERENCE NUMBER</b>	<b>SUSPECT MATERIAL</b>	<b>LOCATION</b>	<b>% ASBESTOS ANALYTICAL RESULTS</b>	<b>FRIABLE OR NON-FRIABLE</b>	<b>QUANTITY</b>
1	Royal Sovereign	Interior - display	ND	NA	NA
2	Timberline	Interior - display	ND	NA	NA
3	Prestige and black tar	Interior - display	ND	NA	NA
4	Raised Profile	Interior - display	ND	NA	NA
5	Hatteras	Interior - display	ND	NA	NA
6	Grand Sequoia and black tar	Interior - display	ND	NA	NA
7	Slateline	Interior - display	ND	NA	NA
8	Grande	Interior - display	ND	NA	NA
9	Capstone	Interior - display	ND	NA	NA
10	Grand Canyon and black tar	Interior - display	ND	NA	NA
11	Country Mansion and black tar	Interior - display	ND	NA	NA
12	Camelot	Interior - display	ND	NA	NA
13	Landmark and black tar	Interior - display	ND	NA	NA
14	Independence	Interior - display	ND	NA	NA
15	New Horizon	Interior - display	ND	NA	NA
16	CertainTeed	Interior - display	ND	NA	NA
17	Centennial Slate and black tar	Interior - display	ND	NA	NA
18	Grand Manor and black tar	Interior - display	ND	NA	NA
19	Drywall composite	Interior	ND	NA	NA
20	White pressboard wall panel	Interior	ND	NA	NA
<b>21</b>	<b>Peghole panel with black mastic behind white pressboard wall panel</b>	<b>Interior - north wall</b>	<b>ND (panel) 6% (mastic)</b>	<b>Category I non-friable</b>	<b>1,000 SF</b>
<b>22A-B</b>	<b>Carpet mastic and remnant black mastic</b>	<b>Interior</b>	<b>3%</b>	<b>Category I non-friable</b>	<b>4,075 SF</b>
23	Black tar on wall behind drywall	Interior	ND	NA	NA
24	White display covering	Interior	ND	NA	NA
25	Gray countertop material	Interior - west	ND	NA	NA
26	Gray speckle countertop material	Interior - reception	ND	NA	NA
27	Black tar on concrete block wall	Interior- electrical closet	ND	NA	NA
28	Brown door caulk	Interior - entries	ND	NA	NA

ND - Not detected at or above the laboratory detection limits.  
SF - Square Feet.  
LF - Linear Feet.

**ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 1A, Minneapolis, MN**

SAMPLE REFERENCE NUMBER	SUSPECT MATERIAL	LOCATION	% ASBESTOS ANALYTICAL RESULTS	FRIABLE OR NON-FRIABLE	QUANTITY
29	7" gray ceramic floor tile, grout and bedding	Interior - west	ND	NA	NA
30	12" gray ceramic floor tile, grout, bedding, yellow and black mastics	Interior - reception	ND (tile, grout, bedding and yellow mastic) 7% (black mastic)	Category I non-friable	345 SF
31	Roof shingle and black tar	Roof	ND	NA	NA
32	Roof membrane and tar	Roof	ND (membrane) 6% (tar)	Category I non-friable	4,415 SF
33	Gray vent caulk	Roof	ND	NA	NA
34	Brick and mortar	Exterior	ND	NA	NA
35	Pressboard siding and vapor barrier	Exterior	ND	NA	NA
36	Gray caulk at base of brick	Exterior - north	ND	NA	NA
37	Gray caulk at base of siding	Exterior	ND	NA	NA
38	Tan window glaze	Exterior	ND	NA	NA
39	Brown window caulk at base	Exterior	ND	NA	NA
40	White window caulk along side	Exterior	ND	NA	NA
41	Black door caulk	Exterior - north	ND	NA	NA
42	Gray/clear duct putty	Roof	ND	NA	NA

ND - Not detected at or above the laboratory detection limits.  
 SF - Square Feet.  
 LF - Linear Feet.




7615 Golden Triangle Dr., Suite N  
Eden Prairie, MN 55344  
(952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 1A

By NOT TO SCALE Date \_\_\_\_\_

Sibley Street NE





**APPENDIX D**



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103467

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1A**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1 351103467-0001	Royal Sovereign	Brown/Black Fibrous Homogeneous	35% Glass	65% Non-fibrous (other)	None Detected
2 351103467-0002	Timberline	Non-Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected
3-Shingle 351103467-0003	Prestique	Gray/Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected
3-Tar 351103467-0003A	Prestique	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
4 351103467-0004	Raised Profile	Black Fibrous Homogeneous	35% Glass	65% Non-fibrous (other)	None Detected
5 351103467-0005	Hatteras	Gray/Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 10:56:52

Analyst(s)  

---

*Heidi Johnson (69)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103467

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1A**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
6-Gray Shingle 351103467-0006	Grand Sequoia	Gray/Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected
6-Tar 351103467-0006A	Grand Sequoia	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
6-Black Shingle 351103467-0006B	Grand Sequoia	Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected
7 351103467-0007	Slateline	Red/Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected
8 351103467-0008	Grange	Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected
9 351103467-0009	Capstone	Gray/Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 10:56:52

Analyst(s)  

---

*Heidi Johnson (69)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103467

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1A**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
10-Green Shingle <i>351103467-0010</i>	Grand Canyon	Black/Green Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	<b>None Detected</b>
10-Tar <i>351103467-0010A</i>	Grand Canyon	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	<b>None Detected</b>
10-Black Shingle <i>351103467-0010B</i>	Grand Canyon	Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	<b>None Detected</b>
11-Shingle <i>351103467-0011</i>	Country Mansion	Tan/White/Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	<b>None Detected</b>
11-Tar <i>351103467-0011A</i>	Country Mansion	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	<b>None Detected</b>
12 <i>351103467-0012</i>	Camelot	Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	<b>None Detected</b>

Initial report from 06/22/2011 10:56:52

Analyst(s)  

---

*Heidi Johnson (69)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103467

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1A**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
13-Tan Shingle 351103467-0013	Landmark TL	Tan/Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected
13-Tar 351103467-0013A	Landmark TL	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
13-Black Shingle 351103467-0013B	Landmark TL	Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected
14 351103467-0014	Independence	Gray/Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected
15 351103467-0015	New Horizon	Black/Blue Fibrous Heterogeneous	30% Glass 5% Cellulose	65% Non-fibrous (other)	None Detected
16 351103467-0016	CertainTeed	Brown/Tan/Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 10:56:52

Analyst(s)  

---

*Heidi Johnson (69)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103467

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1A**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
17-Black Shingle 351103467-0017	Centennial Slate	Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected
17-Tar 351103467-0017A	Centennial Slate	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
17-Gray Shingle 351103467-0017B	Centennial Slate	Gray/Black Fibrous Heterogeneous	30% Glass	70% Non-fibrous (other)	None Detected
18-Black Shingle 351103467-0018	Grand Manor	Black Non-Fibrous Homogeneous	35% Glass	65% Non-fibrous (other)	None Detected
18-Tar 351103467-0018A	Grand Manor	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
18-Gray Shingle 351103467-0018B	Grand Manor	Gray/Black Fibrous Heterogeneous	30% Glass	70% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 10:56:52

Analyst(s)  

---

*Heidi Johnson (69)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103467

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1A**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19 351103467-0019	SR - Comp	Tan/White Non-Fibrous Heterogeneous	15% Cellulose	85% Non-fibrous (other)	None Detected
Sheetrock/Joint Compound					
20 351103467-0020	White Pressboard Panel	Tan Fibrous Homogeneous	100% Cellulose	0% Non-fibrous (other)	None Detected
21-Paneling 351103467-0021	Peghole Panel Behind 2D	Tan/Cream Fibrous Heterogeneous	85% Cellulose	15% Non-fibrous (other)	None Detected
21-Adhesive 351103467-0021A	Peghole Panel Behind 2D	Black Non-Fibrous Homogeneous		94% Non-fibrous (other)	6% Chrysotile
22A 351103467-0022	Carpet Mastic & Remnant Mastic	Black/Yellow Non-Fibrous Homogeneous		97% Non-fibrous (other)	3% Chrysotile
22B 351103467-0023	Carpet Mastic & Remnant Mastic	Black/Yellow Non-Fibrous Homogeneous		97% Non-fibrous (other)	3% Chrysotile

Initial report from 06/22/2011 10:56:52

Analyst(s)  

---

*Heidi Johnson (69)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103467

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1A**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
23-Sheetrock 351103467-0024	Tar Behind SR - East End	Tan/White Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (other)	None Detected
23-Mastic 351103467-0024A	Tar Behind SR - East End	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
24 351103467-0025	White Display Covering	Gray/Tan Fibrous Heterogeneous	65% Cellulose	35% Non-fibrous (other)	None Detected
25 351103467-0026	Gray Countertop - West	Brown/Gray Fibrous Heterogeneous	45% Cellulose	55% Non-fibrous (other)	None Detected
26 351103467-0027	Gray Speckle Countertop - Reception	Brown/Green Non-Fibrous Homogeneous	40% Cellulose	60% Non-fibrous (other)	None Detected
27 351103467-0028	Black tar on Conc Block - Electrical	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 10:56:52

Analyst(s)  

---

*Heidi Johnson (69)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103467

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1A**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
28 351103467-0029	Door Caulk Interior - Double Door - East Entry	Brown Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
29-Ceramic Tile 351103467-0030	7" Gray Ceramic F7	Gray Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
29-Grout 351103467-0030A	7" Gray Ceramic F7	Gray Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
29-Bedding 351103467-0030B	7" Gray Ceramic F7	Grayish Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
30-Ceramic Tile 351103467-0031	12" Gray Ceramic F7	Gray/Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
30-Grout 351103467-0031A	12" Gray Ceramic F7	Gray Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 10:56:52

Analyst(s)  

---

*Heidi Johnson (69)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103467

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1A**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
30-Bedding 351103467-0031B	12" Gray Ceramic F7	Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
30-Yellow Mastic 351103467-0031C	12" Gray Ceramic F7	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
30-Black Mastic 351103467-0031D	12" Gray Ceramic F7	Black Non-Fibrous Homogeneous		93% Non-fibrous (other)	7% Chrysotile
31-Tan Shingle 351103467-0032	Roof Shingle	Tan/Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected
31-Tar 351103467-0032A	Roof Shingle	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
31-Brown Shingle 351103467-0032B	Roof Shingle	Brown/Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 10:56:52

Analyst(s)

Heidi Johnson (69)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103467

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1A**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
32-Membrane 351103467-0033	Roof Membrane & Tar	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
32-Tar 351103467-0033A	Roof Membrane & Tar	Black Non-Fibrous Homogeneous		94% Non-fibrous (other)	6% Chrysotile
33 351103467-0034	Roof Vent Caulk 20LF	Gray/White Non-Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (other)	None Detected
34-Brick 351103467-0035	Brick & Mortar - Exterior North	Brown Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
34-Mortar 351103467-0035A	Brick & Mortar - Exterior North	Gray Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
35-Siding 351103467-0036	Pressboard Siding & Vapor Barrier - Exterior North	Gray Fibrous Homogeneous	65% Cellulose	35% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 10:56:52

Analyst(s)  

---

*Heidi Johnson (69)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103467

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1A**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
35-Black Fibrous Layer 351103467-0036A	Pressboard Siding & Vapor Barrier - Exterior North	Black	60%	Cellulose	30% Non-fibrous (other) <b>None Detected</b>
		Fibrous	10%	Synthetic	
		Homogeneous			
36 351103467-0037	Caulk at Base of Brick - Exterior North	Gray Non-Fibrous Homogeneous	10%	Synthetic	90% Non-fibrous (other) <b>None Detected</b>
37 351103467-0038	Caulk at Base of Siding - Exterior North	Gray Non-Fibrous Homogeneous	10%	Synthetic	90% Non-fibrous (other) <b>None Detected</b>
38 351103467-0039	Window Glaze - Exterior North	Cream Non-Fibrous Homogeneous			100% Non-fibrous (other) <b>None Detected</b>
39 351103467-0040	Window Caulk at Base - Exterior North	Black Non-Fibrous Homogeneous	10%	Synthetic	90% Non-fibrous (other) <b>None Detected</b>
40 351103467-0041	Window Caulk Alongside - Exterior North	White Non-Fibrous Homogeneous	10%	Synthetic	90% Non-fibrous (other) <b>None Detected</b>

Initial report from 06/22/2011 10:56:52

Analyst(s)  

---

*Heidi Johnson (69)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103467

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1A**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
41 351103467-0042	Door Caulk - Exterior East (40CF) West (25 LF)	Black Non-Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (other)	None Detected
42-Gray Layer 351103467-0043	Duct Putty - Roof 120 LF	Gray Non-Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (other)	None Detected
42-Clear Layer 351103467-0043A	Duct Putty - Roof 120 LF	Clear Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 10:56:52

Analyst(s)  

---

*Heidi Johnson (69)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



# Asbestos Lab Services Chain of Custody

## EMSL Order Number (Lab Use Only):

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

3467

Company: Peer Engineering		EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments**	
Street: 7615 Golden Triangle Drive Suite N		Third Party Billing requires written authorization from third party	
City/State/Zip: Eden Prairie, MN 55447			
Report To (Name): Kelly Brown		Fax:	
Telephone: 952-831-3341		Email Address: kbrown@peerengineering.com	
Project Name/Number: <u>Scheper</u>			
Please Provide Results: Email		Purchase Order:	State Samples Taken: MN

**Turnaround Time (TAT) Options\* - Please Check**

3 Hour   
  6 Hour   
  24 Hour   
  48 Hour   
  72 Hour   
  96 Hour   
  1 Week   
  2 Week

\*For TEM Air 3 hours/6 hours, please call ahead to schedule. There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

<b>PCM - Air</b> <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA <b>PLM - Bulk (reporting limit)</b> <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198.1 (friable in NY) <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY) <input type="checkbox"/> NIOSH 9002 (<1%)	<b>TEM - Air</b> <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 <b>TEM - Bulk</b> <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5 <b>TEM - Water:</b> EPA 100.2 Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	<b>TEM - Dust</b> <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167) <b>Soil/Rock/Vermiculite</b> <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> EPA Protocol (Semi-Quantitative) <input type="checkbox"/> EPA Protocol (Quantitative) <b>Other:</b> <input type="checkbox"/>
---	--	---

Check For Positive Stop - Clearly Identify Homogenous Group

Samplers Name: Kelly Brown      Samplers Signature: [Signature]

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
1	Royal Sovereign		6-15-11
2	Z. in hallway		
3	Prestige		
4	Raised Profile		
5	Mattress		
6	Grand Sequoia		
7	Slateline		
8	Grande		

Client Sample # (s): 1-42      Total # of Samples: 43 bags

Relinquished (Client): [Signature]      Date: 6-19-11      Time: \_\_\_\_\_

Received (Lab): [Signature]      Date: 6/20/11      Time: 10:45am      came in

Comments/Special Instructions: Big 1A



## Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3467

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
9	Capstone		
10	Grand Canyon		
11	Country Mansion		
12	Camelot		
13	Landmark 7L		
14	Independence		
15	New Horizon		
16	Centennial TEED		
17	Centennial Slate		
18	Grand Manor		
19	SR-comp - eg		
20	white pressboard panel -		
21	pegboard panel behind 20		
22A	ceiling acoustic + remnant acoustic		
22B	" " " "		
23	tile behind SR - east end		
<b>Comments/Special Instructions:</b> <span style="float: right; font-family: cursive;">Blng 1A</span>			



## Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3467

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
24	white duplex covering		
25	gray countertop - west		
26	gray speckle countertop - reception		
27	black tile on concrete block - electrical		
28	Door caulk interior - double door - east entry		
29	7" gray ceramic P7		
30	12" gray ceramic P7		
31	Roof shingle		
32	Roof membrane + flash		
33	roof vent caulk 20CF		
34	brick + mortar - exterior north		
35	pressure board siding + vapor barrier - exterior north		
36	caulk at base of brick - " "	"	
37	caulk at base of siding - " "	"	
38	window glaze - " "		
39	window caulk at base - " "		
<b>Comments/Special Instructions:</b> <span style="font-size: 1.2em;">Blind 1A</span>			

Controlled Document - Asbestos Lab Services COC - A1.0 - 11/23/2009

Page 3 of 4 Pages





**APPENDIX E**

<b>ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 1B, Minneapolis, MN</b>					
<b>SAMPLE REFERENCE NUMBER</b>	<b>SUSPECT MATERIAL</b>	<b>LOCATION</b>	<b>% ASBESTOS ANALYTICAL RESULTS</b>	<b>FRIABLE OR NON-FRIABLE</b>	<b>QUANTITY</b>
1	White pressboard wall panel	1st floor office hall	ND	NA	NA
2A-C	White ceiling material	1st floor vault	ND	NA	NA
3	Gray countertop material	1st floor lunchroom, kitchen, communications room, west open area and storage 3	ND	NA	NA
4	Gray marble countertop material	1st floor men's (whse)	ND	NA	NA
5	White countertop material	1st floor storage 3	ND	NA	NA
6	Gray duct putty	1st floor storage 3	ND	NA	NA
7	Tan duct putty	1st floor service area and 2nd floor mezzanine	ND	NA	NA
8	Tan fiberglass wall panel and tan mastic	1st floor men's (whse)	ND	NA	NA
9	Cloth vibration joint	1st floor mechanical (whse)	ND	NA	NA
10	Fiberglass wall insulation	South drive thru	ND	NA	NA
11	Fiberglass ceiling insulation	1st floor throughout	ND	NA	NA
12	White vinyl baseboard and yellow mastic	2nd floor men's	ND	NA	NA
13	Gray vinyl baseboard and tan mastic	1st floor west open area, men's restroom (whse), and ramp area	ND	NA	NA
14	Brown vinyl baseboard and yellow mastic	East and west stairwells	ND	NA	NA
15A-B	Drywall composite	Throughout	ND	NA	NA
16	Off-white w/gray speckles vinyl sheet flooring and tan and gray mastics	2nd floor restrooms	30% (sheet flooring) ND (mastics)	Friable	86 SF
17	Lower vinyl floor and mastic	2nd floor men's	30% (sheet flooring) ND (mastic)	Friable	56 SF
18	Lower vinyl floor and mastic	2nd floor women's	30% (sheet flooring) ND (mastics)	Friable	30 SF
19	Black mastic on wood wall panel	2nd floor women's	7%	Category I non-friable	40 SF

ND - Not detected at or above the laboratory detection limits.

SF - Square Feet.

LF - Linear Feet.

<b>ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 1B, Minneapolis, MN</b>					
<b>SAMPLE REFERENCE NUMBER</b>	<b>SUSPECT MATERIAL</b>	<b>LOCATION</b>	<b>% ASBESTOS ANALYTICAL RESULTS</b>	<b>FRIABLE OR NON-FRIABLE</b>	<b>QUANTITY</b>
20A-E	Textured ceiling material	2nd floor office area	ND	NA	NA
21A-B	Foam ball insulation inside concrete block	Interior	ND	NA	NA
22	18" smooth ceiling tile and brown mastic	1st floor lunchroom, hall, communications room, office 1, office hall and women's restroom	ND	NA	NA
23	1' x 1' peghole ceiling tile and brown mastic	1st floor hall and office hall	ND	NA	NA
24	2' x 2' gypsum ceiling tile	1st floor kitchen	ND	NA	NA
25	2' x 2' textured ceiling tile	1st floor throughout	ND	NA	NA
26	1' x 1' smooth ceiling tile and brown mastic	1st floor hall and kitchen	ND	NA	NA
27	<b>Tar behind drywall</b>	<b>1st floor hall (assumed along entire north wall on 1st floor)</b>	<b>7%</b>	<b>Category I non-friable</b>	<b>1,200 SF</b>
28	Brown ceiling insulation	1st floor hall	ND	NA	NA
29	1' x 1' gray marble floor tile, tan mastic, and white floor leveler	1st floor west open area and ramp area	ND	NA	NA
30	6" brown ceramic floor tile, grout and bedding	1st floor kitchen	ND	NA	NA
31	<b>9" x 9" brown floor tile and black and tan mastics</b>	<b>1st floor vault</b>	<b>10% (tile) ND (mastics)</b>	<b>Category I non-friable</b>	<b>120 SF</b>
32	3" tan ceramic floor and wall tile, grout and bedding	1st floor men's	ND	NA	NA
33	<b>7" tan ceramic floor tile, grout, bedding and black mastic</b>	<b>1st floor women's</b>	<b>ND (tile, grout and bedding) 6% (mastic)</b>	<b>Category I non-friable</b>	<b>96 SF</b>
34	<b>Green flooring and black mastic and tan carpet mastic</b>	<b>1st floor lunchroom, hall and communications room</b>	<b>15% (green flooring) ND (mastics)</b>	<b>Category I non-friable</b>	<b>540 SF</b>

ND - Not detected at or above the laboratory detection limits.  
SF - Square Feet.  
LF - Linear Feet.

<b>ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 1B, Minneapolis, MN</b>					
<b>SAMPLE REFERENCE NUMBER</b>	<b>SUSPECT MATERIAL</b>	<b>LOCATION</b>	<b>% ASBESTOS ANALYTICAL RESULTS</b>	<b>FRIABLE OR NON-FRIABLE</b>	<b>QUANTITY</b>
35	Tan flooring and black mastic and tan carpet mastic	1st floor office hall (room)	12% (tan flooring) ND (mastics)	Category I non-friable	72 SF
36	Brown flooring and black mastic and tan carpet mastic	1st floor office 1 and office hall	15% (brown flooring) ND (mastics)	Category I non-friable	395 SF
37	Dark red flooring and black mastic and tan carpet mastic	1st floor hall	10% (dark red flooring) ND (mastics)	Category I non-friable	416 SF
38	Fiberboard floor panels	2nd floor and 3rd floor attics	ND	NA	NA
39	Fiberboard floor panels paper backing	3rd floor	ND	NA	NA
40A-C	Fiberglass pipe insulation	South drive thru	ND	NA	NA
41A-C	Fiberglass duct insulation	2nd floor and 3rd floor attics	ND	NA	NA
42	Gray window caulk along frame and stucco	Exterior - 2nd floor east	ND	NA	NA
43	Gray and brown window caulk on frame	Exterior - 2nd floor east	ND	NA	NA
44	Gray door caulk	Exterior - north (west drive thru)	ND	NA	NA
45A-G	Stucco	Exterior	ND	NA	NA
46	Concrete block	Throughout	ND	NA	NA

ND - Not detected at or above the laboratory detection limits.  
SF - Square Feet.  
LF - Linear Feet.

<b>ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 1B, Minneapolis, MN</b>					
<b>SAMPLE REFERENCE NUMBER</b>	<b>SUSPECT MATERIAL</b>	<b>LOCATION</b>	<b>% ASBESTOS ANALYTICAL RESULTS</b>	<b>FRIABLE OR NON-FRIABLE</b>	<b>QUANTITY</b>
47	Concrete block with foam ball insulation	1st floor storage 1, storage 2, and east stairwell	ND	NA	NA
48	Brown window caulk	Exterior - 2nd floor north at base of window on frame	ND	NA	NA
49	White door caulk	Exterior - west (roof access door)	ND	NA	NA
50	Brown vent caulk	Shingle roof - north	ND	NA	NA
51	Silver duct caulk	Shingle roof - north	ND	NA	NA
52	Shingles	Shingle roof - north	ND	NA	NA
53	<b>Tarpaper beneath shingles</b>	<b>Shingle roof</b>	<b>5% (silver layer) ND (black fibrous layer)</b>	<b>Category I non-friable</b>	<b>2,500 SF</b>
54	Flashing on HVAC units	Roof - west	ND	NA	NA
55	<b>Brown caulk along shingles</b>	<b>Roof</b>	<b>4%</b>	<b>Category I non-friable</b>	<b>150 LF</b>
56	<b>Silver/black tar near vent</b>	<b>Metal roof</b>	<b>15%</b>	<b>Category I non-friable</b>	<b>10 LF</b>
57	<b>Brown/black vent caulk</b>	<b>Metal roof</b>	<b>10%</b>	<b>Category I non-friable</b>	<b>12 LF</b>
58	Gray caulk	Roof - west (base of stucco)	ND	NA	NA
59	Tar, gravel and fiberboard roof deck	Roof	ND	NA	NA

ND - Not detected at or above the laboratory detection limits.  
SF - Square Feet.  
LF - Linear Feet.

<b>ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 1B, Minneapolis, MN</b>					
<b>SAMPLE REFERENCE NUMBER</b>	<b>SUSPECT MATERIAL</b>	<b>LOCATION</b>	<b>% ASBESTOS ANALYTICAL RESULTS</b>	<b>FRIABLE OR NON-FRIABLE</b>	<b>QUANTITY</b>
60	Black and silver/black flashing	Roof - below stucco	ND (black tar and black fibrous layer) 4% (silver layer)	Category I non-friable	120 SF
61	Black tar on flashing	Roof - south (below shingles)	ND	NA	NA
62	Silver/black tar flashing	Roof - below shingles	ND (black tar and black fibrous layer) 3% (silver layer)	Category I non-friable	200 SF
63	Silver tarpaper flashing	Roof - east (SEC)	ND (black fibrous layer) 2% (silver layer)	Category I non-friable	50 SF
64	Silver/black flashing	Roof - west (along west drive thru)	ND (black fibrous layer) 5% (silver layer)	Category I non-friable	120 SF
65	Black & silver/black flashing	Roof - south (along Building 9)	ND (black fibrous layer) 3% (silver layer)	Category I non-friable	150 SF

ND - Not detected at or above the laboratory detection limits.  
SF - Square Feet.  
LF - Linear Feet.

<b>ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 1B, Minneapolis, MN</b>					
<b>SAMPLE REFERENCE NUMBER</b>	<b>SUSPECT MATERIAL</b>	<b>LOCATION</b>	<b>% ASBESTOS ANALYTICAL RESULTS</b>	<b>FRIABLE OR NON-FRIABLE</b>	<b>QUANTITY</b>
66	Roof deck	Roof - west drive thru	ND	NA	NA
67	Roof flashing	Roof - west drive thru	ND	NA	NA
68	<b>Black/silver skylight flashing</b>	<b>Roof - west drive thru</b>	<b>5%</b>	<b>Category I non-friable</b>	<b>48 LF</b>
	<b>Metal-clad fire doors</b>	<b>Throughout</b>	<b>Assumed</b>		<b>18 EA</b>

ND - Not detected at or above the laboratory detection limits.  
 SF - Square Feet.  
 LF - Linear Feet.




7615 Golden Triangle Dr., Suite N  
 Eden Prairie, MN 55344  
 (952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 1B

By NOT TO SCALE Date \_\_\_\_\_

Sibley Street NE



Ground Floor






7615 Golden Triangle Dr., Suite N  
 Eden Prairie, MN 55344  
 (952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 1B

By NOT TO SCALE Date \_\_\_\_\_

Sibley Street NE



2nd Floor



NORTH




7615 Golden Triangle Dr., Suite N  
 Eden Prairie, MN 55344  
 (952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 1B

By \_\_\_\_\_ Date \_\_\_\_\_





**APPENDIX F**



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1 351103475-0001	White Press Board Panel - 1st flr office hall	Brown/White Fibrous Homogeneous	90% Cellulose	10% Non-fibrous (other)	None Detected
2A 351103475-0002	White Ceiling - Vault	White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
2B 351103475-0003	White Ceiling - Vault	White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
2C 351103475-0004	White Ceiling - Vault	White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
3 351103475-0005	Gray Countertop - 1st Flr Lunchroom	Brown/Gray Fibrous Heterogeneous	65% Cellulose	35% Non-fibrous (other)	None Detected
4 351103475-0006	Gray Marble Countertop - 1st Flr Men's (Whse)	Brown/Green Fibrous Heterogeneous	75% Cellulose	25% Non-fibrous (other)	None Detected

Initial report from 06/23/2011 08:30:18

Analyst(s)  

---

Kaitlyn Kubokawa (143)

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
5 351103475-0007	White Countertop - 1st Flr Storage 3	Brown/White Fibrous Heterogeneous	90% Cellulose	10% Non-fibrous (other)	None Detected
6 351103475-0008	Gray Duct Putty - 1st Flr Storage 3	Silver Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
7 351103475-0009	Tan Duct Putty - 2nd Flr mezz.	Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
8-Wall Panel 351103475-0010	Tan FG Wall Panel & Mastic - 1st Flr Men's (Whse)	White/Beige Fibrous Heterogeneous	60% Glass	40% Non-fibrous (other)	None Detected
8-Mastic 351103475-0010A	Tan FG Wall Panel & Mastic - 1st Flr Men's (Whse)	Beige Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
9 351103475-0011	Cloth vib jt - 1st flr mech (whse)	White/Black Fibrous Heterogeneous	50% Glass	50% Non-fibrous (other)	None Detected

Initial report from 06/23/2011 08:30:18

Analyst(s)

Kaitlyn Kubokawa (143)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
10 351103475-0012	FG Wall Insul - South Drive Thru	Yellow Fibrous Homogeneous	95% Min. Wool	5% Non-fibrous (other)	None Detected
11 351103475-0013	FG Ceiling Insul. - 1st Flr Lunchroom	Brown/Silver Fibrous Heterogeneous	60% Cellulose	40% Non-fibrous (other)	None Detected
12-Baseboard 351103475-0014	White Vinyl/BB - 2nd Flr men	White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
12-Mastic 351103475-0014A	White Vinyl/BB - 2nd Flr men	Yellow Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
13-Baseboard 351103475-0015	Gray Vinyl/BB - 1st Flr West Open Area	Gray Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
13-Mastic 351103475-0015A	Gray Vinyl/BB - 1st Flr West Open Area	Tan Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected

Initial report from 06/23/2011 08:30:18

Analyst(s)  

---

Kaitlyn Kubokawa (143)

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0





**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
16-Tan/White Mastic <small>351103475-0019B</small>	Off White w/gray speckles vinyl - 2nd Flr Men	Tan/White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
16-Brown Linoleum <small>351103475-0019C</small>	Off White w/gray speckles vinyl - 2nd Flr Men	Brown/Gray Fibrous Heterogeneous		70% Non-fibrous (other)	30% Chrysotile
16-Gray Mastic <small>351103475-0019D</small>	Off White w/gray speckles vinyl - 2nd Flr Men	Gray Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
17-Linoleum <small>351103475-0020</small>	Lower Vinyl - 2nd Flr Men	Gray/Beige Non-Fibrous Heterogeneous		70% Non-fibrous (other)	30% Chrysotile
17-Mastic <small>351103475-0020A</small>	Lower Vinyl - 2nd Flr Men	Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
18-Linoleum <small>351103475-0021</small>	Lower Vinyl - 2nd Flr Women	Gray/Tan Fibrous Heterogeneous		70% Non-fibrous (other)	30% Chrysotile

Initial report from 06/23/2011 08:30:18

Analyst(s)  

---

*Kaitlyn Kubokawa (143)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
18-Mastic 351103475-0021A	Lower Vinyl - 2nd Flr Women	White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
19 351103475-0022	Black Mastic on Wood Wall Panel - 2nd Flr Women	Black Non-Fibrous Heterogeneous		93% Non-fibrous (other)	7% Chrysotile
20A 351103475-0023	Text Ceil - 2nd Flr Office 2	White Non-Fibrous Homogeneous		85% Non-fibrous (other) 15% Mica	None Detected
20B 351103475-0024	Text Ceil - 2nd Flr Open Area	White Non-Fibrous Homogeneous		85% Non-fibrous (other) 15% Mica	None Detected
20C 351103475-0025	Text Ceil - 2nd Flr Open Area	White Non-Fibrous Homogeneous		85% Non-fibrous (other) 15% Mica	None Detected
20D 351103475-0026	Text Ceil - 2nd Flr East Room	White Non-Fibrous Homogeneous		85% Non-fibrous (other) 15% Mica	None Detected

Initial report from 06/23/2011 08:30:18

Analyst(s)  
Kaitlyn Kubokawa (143)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



# EMSL Analytical, Inc.

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
20E 351103475-0027	Text Ceil - 2nd Flr Office 6	White Non-Fibrous Homogeneous		85% Non-fibrous (other) 15% Mica	None Detected
21A 351103475-0028	Foam Ball Wall Insulation - 1st Flr East Stair	White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
21B-Styrofoam 351103475-0029	In Conc Block Foam Ball Wall Insulation - 1st Flr	White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
21B-Concrete Block 351103475-0029A	In Conc Block Foam Ball Wall Insulation - 1st Flr	Gray Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
22-Ceiling Tile 351103475-0030	18" Smooth CT - 1st Flr Lunchroom	Brown Fibrous Heterogeneous	90% Cellulose	10% Non-fibrous (other)	None Detected
22-Mastic 351103475-0030A	18" Smooth CT - 1st Flr Lunchroom	Brown Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected

Initial report from 06/23/2011 08:30:18

Analyst(s)

Kaitlyn Kubokawa (143)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos			Asbestos
			%	Fibrous	% Non-Fibrous	% Type
23-Ceiling Tile 351103475-0031	1x1 Peghole CT - 1st Hall	Brown/Yellow Fibrous Heterogeneous	10%	Cellulose	10% Non-fibrous (other)	None Detected
			80%	Min. Wool		
23-Mastic 351103475-0031A	1x1 Peghole CT - 1st Hall	Brown Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
24-Texture 351103475-0032	2x2 SR CT - 1st Flr - Kitchen	White Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
24-Sheetrock 351103475-0032A	2x2 SR CT - 1st Flr - Kitchen	Brown/White Fibrous Heterogeneous	20%	Cellulose	80% Non-fibrous (other)	None Detected
			<1%	Glass		
25 351103475-0033	2x2 Textured CT - 1st Flr Hall	Brown/White/Silver Fibrous Heterogeneous	5%	Cellulose	20% Non-fibrous (other)	None Detected
			75%	Min. Wool		
26-Ceiling Tile 351103475-0034	1x1 Smooth CT - 1st Flr Hall	Brown Fibrous Heterogeneous	90%	Cellulose	10% Non-fibrous (other)	None Detected

Initial report from 06/23/2011 08:30:18

Analyst(s)  
Kaitlyn Kubokawa (143)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
26-Mastic 351103475-0034A	1x1 Smooth CT - 1st Flr Hall	Brown Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
27 351103475-0035	Tar Behind SR - 1st Flr Hall	Black Non-Fibrous Homogeneous		93% Non-fibrous (other)	7% Chrysotile
28 351103475-0036	Ceiling Insulation - 1st Flr Hall	Brown Fibrous Homogeneous	85% Cellulose	15% Non-fibrous (other)	None Detected
29-Floor Tile 351103475-0037	12x12 Gray Marble FT - 1st Flr West Open Area	Gray Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
29-Mastic 351103475-0037A	12x12 Gray Marble FT - 1st Flr West Open Area	Tan/Green Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
29-Leveler 351103475-0037B	12x12 Gray Marble FT - 1st Flr West Open Area	White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected

Initial report from 06/23/2011 08:30:18

Analyst(s)  
Kaitlyn Kubokawa (143)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



# EMSL Analytical, Inc.

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
30-Ceramic Tile <i>351103475-0038</i>	6" Brown Ceramic FT - 1st Flr Kitchen	Brown Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
30-Grout <i>351103475-0038A</i>	6" Brown Ceramic FT - 1st Flr Kitchen	Brown Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
30-Bedding <i>351103475-0038B</i>	6" Brown Ceramic FT - 1st Flr Kitchen	Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
31-Black Mastic <i>351103475-0039</i>	9x9 Brown FT - Vault	Black Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
31-Floor Tile <i>351103475-0039A</i>	9x9 Brown FT - Vault	Tan Non-Fibrous Heterogeneous		90% Non-fibrous (other)	10% Chrysotile
31-Tan Mastic <i>351103475-0039B</i>	9x9 Brown FT - Vault	Tan Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected

Initial report from 06/23/2011 08:30:18

Analyst(s)

*Kaitlyn Kubokawa (143)*

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
32-Ceramic Tile <i>351103475-0040</i>	3" Tan Ceramic FT - 1st Flr Men's	Tan Non-Fibrous Heterogeneous		100% Non-fibrous (other)	<b>None Detected</b>
32-Grout <i>351103475-0040A</i>	3" Tan Ceramic FT - 1st Flr Men's	Tan Non-Fibrous Heterogeneous		100% Non-fibrous (other)	<b>None Detected</b>
32-Bedding <i>351103475-0040B</i>	3" Tan Ceramic FT - 1st Flr Men's	Brown/Gray Non-Fibrous Heterogeneous	10% Cellulose	90% Non-fibrous (other)	<b>None Detected</b>
33-Ceramic Tile <i>351103475-0041</i>	3" Tan Ceramic FT - 1st Flr Women's	Tan/Red Non-Fibrous Heterogeneous		100% Non-fibrous (other)	<b>None Detected</b>
33-Grout <i>351103475-0041A</i>	3" Tan Ceramic FT - 1st Flr Women's	Gray Non-Fibrous Heterogeneous		100% Non-fibrous (other)	<b>None Detected</b>
33-Bedding <i>351103475-0041B</i>	3" Tan Ceramic FT - 1st Flr Women's	Gray Non-Fibrous Heterogeneous		100% Non-fibrous (other)	<b>None Detected</b>

Initial report from 06/23/2011 08:30:18

Analyst(s)  

---

*Kaitlyn Kubokawa (143)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0





**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
35-Flooring <small>351103475-0043A</small>	Tan Flooring - 1st Flr Office Hall (room)	Tan Fibrous Heterogeneous		88% Non-fibrous (other)	12% Chrysotile
35-Black Mastic <small>351103475-0043B</small>	Tan Flooring - 1st Flr Office Hall (room)	Black Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
36-Tan Mastic <small>351103475-0044</small>	Brown Flooring - 1st Flr Office 1	Tan Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
36-Flooring <small>351103475-0044A</small>	Brown Flooring - 1st Flr Office 1	Brown Non-Fibrous Heterogeneous		85% Non-fibrous (other)	15% Chrysotile
36-Black Mastic <small>351103475-0044B</small>	Brown Flooring - 1st Flr Office 1	Black Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
37-Tan Mastic <small>351103475-0045</small>	Dark Red Flooring & Carpet Mastic - 1st Flr Hall	Tan Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected

Initial report from 06/23/2011 08:30:18

Analyst(s)  

---

*Kaitlyn Kubokawa (143)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
37-Flooring 351103475-0045A	Dark Red Flooring & Carpet Mastic - 1st Flr Hall	Red Fibrous Heterogeneous		90% Non-fibrous (other)	10% Chrysotile
37-Black Mastic 351103475-0045B	Dark Red Flooring & Carpet Mastic - 1st Flr Hall	Black Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
38 351103475-0046	Fiberboard Floor Panels - 2nd Flr Attic	Brown Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (other)	None Detected
39 351103475-0047	Fiberboard Paperbacking - 3rd Floor	Brown/Black Fibrous Heterogeneous	75% Cellulose	25% Non-fibrous (other)	None Detected
40A-Wrap 351103475-0048	FG TSI - South Drive Thru	White/Silver Fibrous Heterogeneous	45% Cellulose 5% Glass	50% Non-fibrous (other)	None Detected
40A-Insulation 351103475-0048A	FG TSI - South Drive Thru	Yellow Non-Fibrous Heterogeneous	95% Min. Wool	5% Non-fibrous (other)	None Detected

Initial report from 06/23/2011 08:30:18

Analyst(s)  
Kaitlyn Kubokawa (143)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos			Asbestos
			%	Fibrous	% Non-Fibrous	% Type
40B-Wrap 351103475-0049	FG TSI - South Drive Thru	White/Silver Fibrous Heterogeneous	45%	Cellulose 5% Glass	50% Non-fibrous (other)	None Detected
40B-Insulation 351103475-0049A	FG TSI - South Drive Thru	Yellow Fibrous Heterogeneous	95%	Min. Wool	5% Non-fibrous (other)	None Detected
40C-Wrap 351103475-0050	FG TSI - South Drive Thru	White Fibrous Heterogeneous	45%	Cellulose 5% Glass	50% Non-fibrous (other)	None Detected
40C-Insulation 351103475-0050A	FG TSI - South Drive Thru	Yellow Fibrous Heterogeneous	95%	Min. Wool	5% Non-fibrous (other)	None Detected
41A-Wrap 351103475-0051	FG Duct - 3rd Flr	Brown/Silver Fibrous Heterogeneous	50%	Cellulose	50% Non-fibrous (other)	None Detected
41A-Insulation 351103475-0051A	FG Duct - 3rd Flr	Yellow Fibrous Heterogeneous	95%	Min. Wool	5% Non-fibrous (other)	None Detected

Initial report from 06/23/2011 08:30:18

Analyst(s)

Kaitlyn Kubokawa (143)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos			Asbestos
			%	Fibrous	% Non-Fibrous	% Type
41B-Wrap <small>351103475-0052</small>	FG Duct - 3rd Flr	Brown/Silver Fibrous Heterogeneous	50%	Cellulose	50% Non-fibrous (other)	None Detected
41B-Insulation <small>351103475-0052A</small>	FG Duct - 3rd Flr	Yellow Fibrous Heterogeneous	95%	Min. Wool	5% Non-fibrous (other)	None Detected
41C-Wrap <small>351103475-0053</small>	FG Duct - 3rd Flr	Brown/Silver Fibrous Heterogeneous	50%	Cellulose	50% Non-fibrous (other)	None Detected
41C-Insulation <small>351103475-0053A</small>	FG Duct - 3rd Flr	Yellow Fibrous Heterogeneous	95%	Min. Wool	5% Non-fibrous (other)	None Detected
42 <small>351103475-0054</small>	Window Caulk Along Frame & Stucco - 2nd Flr Exteri	Gray Fibrous Homogeneous	5%	Synthetic	95% Non-fibrous (other)	None Detected
43-Gray Caulk <small>351103475-0055</small>	Window Caulk on Frame - 2nd Flr Exterior East	Gray Fibrous Heterogeneous	5%	Synthetic	95% Non-fibrous (other)	None Detected

Initial report from 06/23/2011 08:30:18

Analyst(s)  

---

*Kaitlyn Kubokawa (143)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0







**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
49 351103475-0067	Door Caulk - Exterior Roof Access Door West 20 LF	White Fibrous Homogeneous	3% Synthetic	97% Non-fibrous (other)	None Detected
50 351103475-0068	Brown Vent Caulk - Shingle Roof North 10 LF	Brown Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
51 351103475-0069	Silver Duct Caulk - Shingle Roof North 30 LF	Silver Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
52 351103475-0070	Shingles - Shingle Roof North	Black Fibrous Heterogeneous	15% Glass	85% Non-fibrous (other)	None Detected
53-Silver Layer 351103475-0071	Tar Paper Beneath Shingles - Shingle Roof North	Silver Non-Fibrous Heterogeneous		95% Non-fibrous (other)	5% Chrysotile
53-Black Fibrous Layer 351103475-0071A	Tar Paper Beneath Shingles - Shingle Roof North	Black Fibrous Heterogeneous	30% Cellulose 10% Glass	60% Non-fibrous (other)	None Detected

Initial report from 06/23/2011 08:30:18

Analyst(s)  
Kaitlyn Kubokawa (143)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos			Asbestos
			%	Fibrous	% Non-Fibrous	% Type
54-Top Tar Layer <small>351103475-0072</small>	Flashing on HVAC Unit & Roof West 80 SF	Black Fibrous Heterogeneous	25%	Cellulose	75% Non-fibrous (other)	None Detected
54-Fibrous Black Layer with Rocks <small>351103475-0072A</small>	Flashing on HVAC Unit & Roof West 80 SF	Black Fibrous Heterogeneous	25%	Synthetic	75% Non-fibrous (other)	None Detected
54-2nd Tar Layer <small>351103475-0072B</small>	Flashing on HVAC Unit & Roof West 80 SF	Black Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
54-Brown Fibrous Layer <small>351103475-0072C</small>	Flashing on HVAC Unit & Roof West 80 SF	Brown Fibrous Heterogeneous	70%	Cellulose	10% Non-fibrous (other)	None Detected
			10%	Min. Wool	10% Perlite	
55 <small>351103475-0073</small>	Brown Caulk Along Shingles - Roof West 150 LF	Brown Non-Fibrous Homogeneous			96% Non-fibrous (other)	4% Chrysotile
56 <small>351103475-0074</small>	Silver Black Tar Near Vent - Metal Roof 10 LF	Black/Silver Fibrous Homogeneous			85% Non-fibrous (other)	15% Chrysotile

Initial report from 06/23/2011 08:30:18

Analyst(s)  

---

*Kaitlyn Kubokawa (143)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
57 351103475-0075	Vent Caulk - Metal Roof - 12 LF	Brown/Black Fibrous Homogeneous		90% Non-fibrous (other)	10% Chrysotile
58 351103475-0076	Gray Caulk - Roof West Base of Stucco 60 LF	Gray Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
59-Brown Fibrous Layer 351103475-0077	Fiberboard Tar & Gravel Roof Deck - Roof North	Brown Fibrous Heterogeneous	90% Cellulose	10% Non-fibrous (other)	None Detected
59-Black Layer 351103475-0077A	Fiberboard Tar & Gravel Roof Deck - Roof North	Non-Fibrous Heterogeneous	10% Glass	90% Non-fibrous (other)	None Detected
60-Top Tar Layer 351103475-0078	Black & Silver/Black Flashing - Roof West Below S	Black Fibrous Heterogeneous	10% Cellulose	90% Non-fibrous (other)	None Detected
60-Silver Layer 351103475-0078A	Black & Silver/Black Flashing - Roof West Below S	Silver Non-Fibrous Heterogeneous		96% Non-fibrous (other)	4% Chrysotile

Initial report from 06/23/2011 08:30:18

Analyst(s)

Kaitlyn Kubokawa (143)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos			Asbestos
			%	Fibrous	% Non-Fibrous	% Type
60-Black Fibrous Layer <small>351103475-0078B</small>	Black & Silver/Black Flashing - Roof West Below S	Black Fibrous Heterogeneous	15%	Glass	85% Non-fibrous (other)	None Detected
61 <small>351103475-0079</small>	Black Tar On Flashing - Roof South Below Shingles	Black Fibrous Heterogeneous	10%	Glass	90% Non-fibrous (other)	None Detected
62-Silver Layer <small>351103475-0080</small>	Silver Black Tar Flashing - Roof North Below Shing	Black/Silver Non-Fibrous Heterogeneous			97% Non-fibrous (other)	3% Chrysotile
62-Fibrous Black Layer <small>351103475-0080A</small>	Silver Black Tar Flashing - Roof North Below Shing	Black Fibrous Heterogeneous	20%	Glass	80% Non-fibrous (other)	None Detected
62-Tar Layer <small>351103475-0080B</small>	Silver Black Tar Flashing - Roof North Below Shing	Black Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
62-Shingle w/Silver Layer in Middle <small>351103475-0080C</small>	Silver Black Tar Flashing - Roof North Below Shing	Black/Silver Fibrous Heterogeneous	10%	Cellulose	87% Non-fibrous (other)	3% Chrysotile

Initial report from 06/23/2011 08:30:18

Analyst(s)  

---

*Kaitlyn Kubokawa (143)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
63-Silver Layer <i>351103475-0081</i>	Silver Tar Paper Flashing - Roof East (SEC) Over E	Silver Non-Fibrous Heterogeneous		98% Non-fibrous (other)	<b>2% Chrysotile</b>
63-Black Fibrous Layer <i>351103475-0081A</i>	Silver Tar Paper Flashing - Roof East (SEC) Over E	Black Fibrous Heterogeneous	35% Glass	65% Non-fibrous (other)	<b>None Detected</b>
64-Silver Layer <i>351103475-0082</i>	Silver Black Flashing - Roof West Along West Drive	Silver Non-Fibrous Heterogeneous		95% Non-fibrous (other)	<b>5% Chrysotile</b>
64-Black Layer <i>351103475-0082A</i>	Silver Black Flashing - Roof West Along West Drive	Black Fibrous Heterogeneous	20% Glass	80% Non-fibrous (other)	<b>None Detected</b>
65-Silver/Loose Black Tar Layer <i>351103475-0083</i>	Black and Silver/Black Flashing - Roof South Along	Black/Silver Non-Fibrous Heterogeneous		97% Non-fibrous (other)	<b>3% Chrysotile</b>
65-Fibrous Black Layer <i>351103475-0083A</i>	Black and Silver/Black Flashing - Roof South Along	Black Fibrous Heterogeneous	20% Glass	80% Non-fibrous (other)	<b>None Detected</b>

Initial report from 06/23/2011 08:30:18

Analyst(s)  

---

*Kaitlyn Kubokawa (143)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103475

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer - Bldg 1B**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
66 <i>351103475-0084</i>	Roof Deck - West Drive Thru	Black Non-Fibrous Heterogeneous		100% Non-fibrous (other)	<b>None Detected</b>
67-Top Black Fibrous Layer <i>351103475-0085</i>	Roof Flashing - West Drive Thru	Black Fibrous Heterogeneous	40% Cellulose	60% Non-fibrous (other)	<b>None Detected</b>
67-Tar Paper <i>351103475-0085A</i>	Roof Flashing - West Drive Thru	Black Fibrous Heterogeneous	60% Cellulose	40% Non-fibrous (other)	<b>None Detected</b>
67-Tar Layer with Woven Fibrous Layer <i>351103475-0085B</i>	Roof Flashing - West Drive Thru	Black Fibrous Heterogeneous	10% Glass 10% Cellulose	80% Non-fibrous (other)	<b>None Detected</b>
68 <i>351103475-0086</i>	Skylight Flashing - West Drive Thru	Black/Silver Fibrous Homogeneous	5% Cellulose	90% Non-fibrous (other)	<b>5% Chrysotile</b>

Initial report from 06/23/2011 08:30:18

Analyst(s)  

---

*Kaitlyn Kubokawa (143)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



# Asbestos Lab Services Chain of Custody

## EMSL Order Number (Lab Use Only):

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

3475

Company: Peer Engineering		EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different <small>If Bill to is Different note instructions in Comments**                  Third Party Billing requires written authorization from third party</small>	
Street: 7615 Golden Triangle Drive Suite N			
City/State/Zip: Eden Prairie, MN 55447			
Report To (Name): Kelly Brown		Fax:	
Telephone: 952-831-3341		Email Address: kbrown@peerengineering.com	
Project Name/Number: <u>Scherer</u>			
Please Provide Results: Email		Purchase Order:	State Samples Taken: MN
<b>Turnaround Time (TAT) Options* - Please Check</b>			
<input type="checkbox"/> 3 Hour <input type="checkbox"/> 6 Hour <input type="checkbox"/> 24 Hour <input type="checkbox"/> 48 Hour <input checked="" type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input type="checkbox"/> 1 Week <input type="checkbox"/> 2 Week			
*For TEM Air 3 hours/6 hours, please call ahead to schedule. There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.			
<b>PCM - Air</b> <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA		<b>TEM - Air</b> <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312	
<b>PLM - Bulk (reporting limit)</b> <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/ Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198.1 (friable in NY) <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY) <input type="checkbox"/> NIOSH 9002 (<1%)		<b>TEM - Bulk</b> <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5 <b>TEM - Water:</b> EPA 100.2 Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	
		<b>TEM - Dust</b> <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167)	
		<b>Soil/Rock/Vermiculite</b> <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> EPA Protocol (Semi-Quantitative) <input type="checkbox"/> EPA Protocol (Quantitative)	
<input type="checkbox"/> Check For Positive Stop - Clearly Identify Homogenous Group			
Samplers Name: <u>Kelly Brown</u>		Samplers Signature: <u>[Signature]</u>	
Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
1	white pass, bands panel - 1" flk off wall		6-15-11
2A-C	white ceiling - vault		
3	gray contact - 1" flk ladder		
4	gray rubble, contact - 1" flk men's (white)		
5	white contact - 1" flk storage		
6	gray duct patty - 1" flk storage		
7	tan duct patty - 2nd flk mark		
8	tan FG wall panel + waste - 1" flk men's (white)		
Client Sample # (s): <u>1-68</u>		Total # of Samples: <u>86 bags</u>	
Relinquished (Client): <u>[Signature]</u> Date: <u>6-19-11</u>		Time:	
Received (Lab): <u>CROTHUR CONNER</u> Date: <u>6-20-11</u>		Time: <u>10:45 AM</u>	
Comments/Special Instructions: <u>Bldg 1B</u>			



## Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3475

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
9	clutter v. bjt - 1 <sup>st</sup> Flr mech (white)		
10	f6 wall panel - substructure		
11	f6 ceiling panel - 1 <sup>st</sup> Flr kitchen		
12	white vinyl BB - 2 <sup>nd</sup> Flr men		
13	gray vinyl/BB - 1 <sup>st</sup> Flr west open area		
14	brown BB - 1 <sup>st</sup> Flr east stair		
15A	SR comp - 1 <sup>st</sup> Flr Storage 2		
15B	" - 3 <sup>rd</sup> Flr		
16	off white / gray speckles vinyl - 2 <sup>nd</sup> Flr men		
17	lower vinyl - 2 <sup>nd</sup> Flr men		
18	lower vinyl - 2 <sup>nd</sup> Flr women		
19	black mat/c on wood wall panel - 2 <sup>nd</sup> Flr women		
20A	test cell - 2 <sup>nd</sup> Flr office 2		
20B	" " " open area		
20C	" " " open area		
20D	" " " conf room		
20E	" " " office 6		

Comments/Special Instructions:

Bldg 1B



## Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3475

Minneapolis, MN  
14375 23rd Avenue North  
Minneapolis, MN 55447  
PHONE: (763) 449-4922  
FAX: (763) 449-4924

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
21A	Round wall insulation - 1 <sup>st</sup> Flr east stair		
21B	1 <sup>st</sup> conc blocks 1 <sup>st</sup> Flr storage		
22	18" smooth CT - 1 <sup>st</sup> Flr lunchroom		
23	1x1 peg tile CT - 1 <sup>st</sup> Flr hall		
24	2x2 SR CT, 1 <sup>st</sup> Flr - kitchen		
25	2x2 textured CT - 1 <sup>st</sup> Flr hall		
26	1x1 smooth CT - 1 <sup>st</sup> Flr hall		
27	tan belies SR - 1 <sup>st</sup> Flr hall		
28	ceiling insulation - 1 <sup>st</sup> Flr hall		
29	12x12 gray marble CT - 1 <sup>st</sup> Flr west open area		
30	6" brown ceramic FT - 1 <sup>st</sup> Flr kitchen		
31	9x9 brown FT - vault		
32	3" tan ceramic FT - 1 <sup>st</sup> Flr men's		
33	3" tan ceramic FT - 1 <sup>st</sup> Flr women's		
34	green flooring - 1 <sup>st</sup> Flr lunchroom		
35	tan flooring - 1 <sup>st</sup> Flr office hall (room)		
Comments/Special Instructions: Bldg 1B			

Controlled Document - Asbestos Lab Services COC - A1.0 - 11/23/2009

Page 3 of 6 Pages



## Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3475

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
36	brown flooring - 1 <sup>st</sup> flr office 1		
37	dark red flooring + carpet waste - 1 <sup>st</sup> flr hall		
38	fiberboard floor panels - 2 <sup>nd</sup> flr attic		
39	" " paper backing - 3 <sup>rd</sup> flr		
40A-C	FG TSI - south driveway		
41A-C	RG Duct - 3 <sup>rd</sup> flr		
42	Window caulk along frame + stucco - 2 <sup>nd</sup> flr exterior east		
43	Window caulk on frame - " "		
44	Door caulk - exterior north-west driveway 201C		
45A	Stucco - exterior east 1 <sup>st</sup> flr		
45B	" "		
45C	" " north 1 <sup>st</sup> flr NW		
45D	" " north 2 <sup>nd</sup> flr		
45E	" " roof west		
45F	" " north 2 <sup>nd</sup> flr		
45G	" " roof east		
<b>Comments/Special Instructions:</b> <span style="font-size: 1.5em; margin-left: 20px;">Bldg 1B</span>			

Controlled Document - Asbestos Lab Services COC - A1.0 - 11/23/2009

Page 4 of 9 Pages



## Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3475

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
46	conc block - storage 1		
47	conc block w/ foam ball filler - storage 1		
48	window caulk - exterior 2 <sup>nd</sup> fl <sup>r</sup> north at base of window frame		
49	door caulk - exterior roof access door west	20 CF	
50	brown vent caulk - shingle roof north	10 CF	
51	silvca deck caulk - shingle roof north	30 CF	
52	shingles - shingle roof north		
53	tampaper beneath shingles - " "		
54	flashing on HVAC unit - roof west	flashing, tampaper, tarp, fl <sup>r</sup> bundles of sealant BOSF	
55	brown caulk along shingles - roof west	150 CF	
56	silvca black tan near vent - metal roof	10 CF	
57	vent caulk - metal roof	12 CF	
58	gray caulk - roof west base of stucco	60 CF	
59	<sup>fl<sup>r</sup> boards</sup> tarp + gravel roof deck - roof north		
60	black + silver/black flashing - roof west	below stucco	
61	black tan on flashing - roof south	below shingles	100 CF
<b>Comments/Special Instructions:</b> <div style="text-align: center; font-size: 1.5em; margin-top: 10px;">Blind B</div>			

Controlled Document - Asbestos Lab Services COC - A1.0 - 11/23/2009

Page 5 of 6 Pages



**APPENDIX G**

<b>ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 1C, Minneapolis, MN</b>					
<b>SAMPLE REFERENCE NUMBER</b>	<b>SUSPECT MATERIAL</b>	<b>LOCATION</b>	<b>% ASBESTOS ANALYTICAL RESULTS</b>	<b>FRIABLE OR NON-FRIABLE</b>	<b>QUANTITY</b>
1A-C	Fiberglass pipe insulation	Interior	ND	NA	NA
2	Fiberglass ceiling insulation	Interior	ND	NA	NA
3	Remnant gray wall mastic	Wood shop	ND	NA	NA
4	White wall caulk	South loading dock	ND	NA	NA
5	Glass block window mortar	Open area, north loading dock, wood shop	ND	NA	NA
6	Drywall ceiling	Open area and south loading dock	ND	NA	NA
7	2' x 4 pinhole/divot ceiling tile	Office	ND	NA	NA
8	Brown duct putty	Open area and wood shop	ND	NA	NA
9	Fiberboard behind wood siding	South loading dock	ND	NA	NA
10	Brown door caulk	Exterior - north (NWC)	ND	NA	NA
11	White door caulk	Exterior - north (NEC)	ND	NA	NA
12	Concrete block	Interior and exterior	ND	NA	NA
13	Roof deck material (tar, fiberboard and foam)	Roof	ND	NA	NA
14	Roof flashing (tar, tarpaper and fiberboard)	Roof	ND	NA	NA
15	<b>Gray/black tar and tarpaper</b>	<b>Roof - NEC</b>	<b>15%</b>	<b>Category I non-friable</b>	<b>240 SF</b>
16	Gray caulk on skylights	Roof	ND	NA	NA
17	Black tar on stack	Roof - wood shop	ND	NA	NA
18	<b>Silver/black tar and clear caulk on stack</b>	<b>Roof - open area</b>	<b>15% (silver/black tar) ND (clear caulk)</b>	<b>Category I non-friable</b>	<b>10 LF</b>
	<b>Metal-clad fire doors</b>	<b>Throughout</b>	<b>Assumed</b>		<b>5EA</b>

ND - Not detected at or above the laboratory detection limits.  
SF - Square Feet.  
LF - Linear Feet.




7615 Golden Triangle Dr., Suite N  
Eden Prairie, MN 55344  
(952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scheerer Brothers - Building 1C

By NOT TO SCALE Date \_\_\_\_\_





**APPENDIX H**



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103468

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 1C**

EMSL Proj:  
Analysis Date: 6/21/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1A 351103468-0001	F6 TSI open Area/woodshop/open Area	White/Silver/Yellow Fibrous Heterogeneous	10% Cellulose 85% Min. Wool	5% Non-fibrous (other)	None Detected
1B 351103468-0002	F6 TSI open Area/woodshop/open Area	White/Silver/Yellow Fibrous Heterogeneous	10% Cellulose 85% Min. Wool	5% Non-fibrous (other)	None Detected
1C 351103468-0003	F6 TSI open Area/woodshop/open Area	White/Silver/Yellow Fibrous Heterogeneous	10% Cellulose 85% Min. Wool	5% Non-fibrous (other)	None Detected
2 351103468-0004	F6 ceiling insulation-open Area	Yellow Fibrous Homogeneous	95% Min. Wool	5% Non-fibrous (other)	None Detected
3 351103468-0005	remnant wall mastic - woodshop	Gray Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
4 351103468-0006	wall caulk - South Dock	White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected

Initial report from 06/21/2011 16:12:20

Analyst(s)  

---

*Heidi Johnson (24)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103468

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 1C**

EMSL Proj:  
Analysis Date: 6/21/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
5 351103468-0007	glass block window mortar - open Area	Tan Non-Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (other)	None Detected
6 351103468-0008	ISR ceiling - open Area	Tan/White Non-Fibrous Homogeneous	10% Cellulose 5% Glass	85% Non-fibrous (other)	None Detected
7 351103468-0009	2x4 p/d/c7 - office	Tan/White Fibrous Homogeneous	40% Cellulose 40% Min. Wool	10% Non-fibrous (other) 10% Perlite	None Detected
8 351103468-0010	brown duct putty - wood shop	Tan Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (other)	None Detected
9 351103468-0011	fiberboard behind wood siding - South Dock	Tan Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (other)	None Detected
10 351103468-0012	brown Door caulk - exterior north NWC	Brown/Gray Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected

Initial report from 06/21/2011 16:12:20

Analyst(s)

Heidi Johnson (24)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103468

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 1C**

EMSL Proj:  
Analysis Date: 6/21/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
11 351103468-0013	white Door caulk - exterior north NEC	White Non-Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (other)	None Detected
12 351103468-0014	coneblock - open Area	Gray Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
13-Tar Layer 351103468-0015	Roof deck - north loading Dock	Black Non-Fibrous Homogeneous	5% Glass	95% Non-fibrous (other)	None Detected
13-Black Layer 351103468-0015A	Roof deck - north loading Dock	Non-Fibrous Heterogeneous	25% Cellulose	75% Non-fibrous (other)	None Detected
13-Fibrous Layer 351103468-0015B	Roof deck - north loading Dock	Brown Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (other)	None Detected
14-Black Layer 351103468-0016	Roof flashing - north loading Dock	Black Non-Fibrous Homogeneous	15% Cellulose	85% Non-fibrous (other)	None Detected

Initial report from 06/21/2011 16:12:20

Analyst(s)

Heidi Johnson (24)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103468

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 1C**

EMSL Proj:  
Analysis Date: 6/21/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
14-Gray Layer 351103468-0016A	Roof flashing - north loading Dock	Gray/Black Non-Fibrous Homogeneous	30% Cellulose	70% Non-fibrous (other)	None Detected
15 351103468-0017	gray black tar - north loading Dock NEC	Gray/Black Non-Fibrous Homogeneous		85% Non-fibrous (other)	15% Chrysotile
16 351103468-0018	gray caulk on skylights - 8x14 Lf	Gray Non-Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (other)	None Detected
17 351103468-0019	black tan on stack - roof woodshop 4 Lf	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
18-White Layer 351103468-0020	silver black tar on stack & clear caulk - roof ope	White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
18-Black Layer 351103468-0020A	silver black tar on stack & clear caulk - roof ope	Black Non-Fibrous Homogeneous		85% Non-fibrous (other)	15% Chrysotile

Initial report from 06/21/2011 16:12:20

Analyst(s)

Heidi Johnson (24)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



# Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3708

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

Company: Peer Engineering		EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different <small>If Bill to is Different note instructions in Comments**                  Third Party Billing requires written authorization from third party</small>	
Street: 7615 Golden Triangle Drive Suite N			
City/State/Zip: Eden Prairie, MN 55447			
Report To (Name): Kelly Brown		Fax:	
Telephone: 952-831-3341		Email Address: kbrown@peerengineering.com	
Project Name/Number: <u>Schepers</u>			
Please Provide Results: Email		Purchase Order:	State Samples Taken: MN
<b>Turnaround Time (TAT) Options* - Please Check</b>			
<input type="checkbox"/> 3 Hour <input type="checkbox"/> 6 Hour <input type="checkbox"/> 24 Hour <input checked="" type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input type="checkbox"/> 1 Week <input type="checkbox"/> 2 Week			
<small>*For TEM Air 3 hours/6 hours, please call ahead to schedule. There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.</small>			
<b>PCM - Air</b> <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA <b>PLM - Bulk (reporting limit)</b> <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198.1 (friable in NY) <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY) <input type="checkbox"/> NIOSH 9002 (<1%)		<b>TEM - Air</b> <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 <b>TEM - Bulk</b> <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5 <b>TEM - Water: EPA 100.2</b> Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	
		<b>TEM-Dust</b> <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167) <b>Soil/Rock/Vermiculite</b> <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> EPA Protocol (Semi-Quantitative) <input type="checkbox"/> EPA Protocol (Quantitative) <b>Other:</b> <input type="checkbox"/>	
<input type="checkbox"/> Check For Positive Stop - Clearly Identify Homogenous Group			
Samplers Name: <u>Kelly Brown</u>		Samplers Signature: <u>[Signature]</u>	
Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
1A-C	F6 T57 open areas/woodshop/open areas		6-15-11
2	F6 ceiling in utility - open areas		
3	remnant wall <del>matrix</del> - woodshop		
4	wall <del>matrix</del> - south dock		
5	glass block window monitor - open areas		
6	15R ceiling - open areas		
7	2x4 p/d/ct - office		
8	brown duct pit - wood shop		
Client Sample # (s): <u>1A-13</u>		Total # of Samples: <u>20 bags</u>	
Relinquished (Client): <u>[Signature]</u> Date: <u>6-15-11</u>		Time:	
Received (Lab): <u>[Signature]</u> Date: <u>6/20/11</u>		Time: <u>10:45 am</u> <u>corner</u>	
Comments/Special Instructions: <u>Blng 1C</u>			



# Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3468

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
9	Fiberboard <del>to be</del> wood siding - south deck		
10	brown Door caulk - exterior north NWC		
11	white " - exterior north NWC		
12	concrete block - open Area		
13	Roof deck - north loading dock		
14	Roof flashing - " "		
15	gray black tan - " " NWC		
16	gray caulk on skylight - 8x14 LF		
17	black tan on stack - roof wood shop	4 LF	
18	silver black tan on stack + clear caulk - roof open Area	10 LF	

Comments/Special Instructions: Blog 1c

Roof deck  
 tan + gravel  
 Fiberboard  
 tan  
 foam  
 wood on concrete

Flashing  
 tan  
 tan paper  
 Fiberboard



**APPENDIX I**

<b>ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 1D, Minneapolis, MN</b>					
<b>SAMPLE REFERENCE NUMBER</b>	<b>SUSPECT MATERIAL</b>	<b>LOCATION</b>	<b>% ASBESTOS ANALYTICAL RESULTS</b>	<b>FRIABLE OR NON-FRIABLE</b>	<b>QUANTITY</b>
1	Brown duct putty	Shop	ND	NA	NA
2	Fiberglass ceiling insulation	Interior	ND	NA	NA
3	Gray feather countertop material	Electrical room	ND	NA	NA
4	Brick and mortar	Electrical room	ND	NA	NA
5	Drywall composite	Electrical room	ND	NA	NA
6	Fiberboard behind wood siding	Shop	ND	NA	NA
7	Fiberboard wall panel	Exterior - south	ND	NA	NA
8	Gray door caulk	Exterior - south	ND	NA	NA
9	Concrete block	Interior and exterior	ND	NA	NA
10	Black stack tar	Roof	ND	NA	NA
11	Clear/silver caulk on dust collector	Roof	ND	NA	NA
12	Black tar on dust collector	Roof	ND	NA	NA
13	Membrane, black seam tar, and fiberboard underlay	Roof	ND	NA	NA
<b>14</b>	<b>Silver shingle/tarpaper and black tar</b>	<b>Roof</b>	<b>ND (shingle) 10% (tar)</b>	<b>Category I non-friable</b>	<b>4,480 SF</b>
15	Green shingle/tarpaper and black tar	Roof	ND	NA	NA

ND - Not detected at or above the laboratory detection limits.  
SF - Square Feet.  
LF - Linear Feet.




7615 Golden Triangle Dr., Suite N  
Eden Prairie, MN 55344  
(952) 831-3341 • Fax (952) 831-4552


Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 1D

By NOT TO SCALE Date \_\_\_\_\_



Ground Floor



Upper Floor



**APPENDIX J**



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103466

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 1D**

EMSL Proj:  
Analysis Date: 6/21/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1 351103466-0001	Brown Duct Putty	Brown Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
2 351103466-0002	F6 Ceiling Insulation - Mezzanine	Brown Fibrous Homogeneous	95% Min. Wool	5% Non-fibrous (other)	None Detected
3 351103466-0003	Gray Feather Countertop - Electric Room	Gray Non-Fibrous Heterogeneous	45% Cellulose	55% Non-fibrous (other)	None Detected
4 351103466-0004	Brick & Mortar - Electric Room	Gray/White Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
5 351103466-0005	Brick & Mortar - Electric Room	Tan/White Non-Fibrous Heterogeneous	15% Cellulose	85% Non-fibrous (other)	None Detected
			Sheetrock/Joint Compound		
6 351103466-0006	Fiberboard behind woodsiding - Interior	Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (other)	None Detected

Initial report from 06/21/2011 16:13:59

Analyst(s)  

---

*Heidi Johnson (21)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103466

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 1D**

EMSL Proj:  
Analysis Date: 6/21/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
7 351103466-0007	Fiberboard Wall Panel - Exterior South	Brown/White Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (other)	None Detected
8 351103466-0008	Door Caulk - Exterior South	Gray/Tan Non-Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (other)	None Detected
9 351103466-0009	Conc Block	Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
10 351103466-0010	Black Stack Tar - Roof 5LF	Black Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (other)	None Detected
11-Clear Layer 351103466-0011	Clear Caulk on Hoper - Roof	Cream Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
11-Silver Layer 351103466-0011A	Clear Caulk on Hoper - Roof	Silver Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected

Initial report from 06/21/2011 16:13:59

Analyst(s)

Heidi Johnson (21)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103466

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 1D**

EMSL Proj:  
Analysis Date: 6/21/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
12 351103466-0012	Black Tar on Hopper - Roof 8 LF	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
13-Gray Layer 351103466-0013	Roof Membrane, Tar & Fiberboard	Gray Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
13-Fibrous Layer 351103466-0013A	Roof Membrane, Tar & Fiberboard	Tan Fibrous Homogeneous	100% Cellulose	0% Non-fibrous (other)	None Detected
13-Black Layer 351103466-0013B	Roof Membrane, Tar & Fiberboard	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
14-Top Shingle 351103466-0014	Silver Shingle - Roof	White/Black Fibrous Heterogeneous	35% Cellulose	65% Non-fibrous (other)	None Detected
14-Tar 351103466-0014A	Silver Shingle - Roof	Black Non-Fibrous Homogeneous		90% Non-fibrous (other)	10% Chrysotile

Initial report from 06/21/2011 16:13:59

Analyst(s)

Heidi Johnson (21)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103466

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 1D**

EMSL Proj:  
Analysis Date: 6/21/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
14-Bottom Shingle <i>351103466-0014B</i>	Silver Shingle - Roof	Black Fibrous Homogeneous	35% Cellulose	65% Non-fibrous (other)	<b>None Detected</b>
15-Green Shingle <i>351103466-0015</i>	Green Shingle - Roof	Black/Green Fibrous Heterogeneous	35% Cellulose	65% Non-fibrous (other)	<b>None Detected</b>
15-Tar <i>351103466-0015A</i>	Green Shingle - Roof	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	<b>None Detected</b>

Initial report from 06/21/2011 16:13:59

Analyst(s)  

---

*Heidi Johnson (21)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



# Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3466

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

Company: Peer Engineering		EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments** Third Party Billing requires written authorization from third party	
Street: 7615 Golden Triangle Drive Suite N			
City/State/Zip: Eden Prairie, MN 55447			
Report To (Name): Kelly Brown		Fax:	
Telephone: 952-831-3341		Email Address: kbrown@peerengineering.com	
Project Name/Number: <u>Scherer</u>			
Please Provide Results: Email		Purchase Order:	State Samples Taken: MN

**Turnaround Time (TAT) Options\* - Please Check**

3 Hour   
  6 Hour   
  24 Hour   
  48 Hour   
  72 Hour   
  96 Hour   
  1 Week   
  2 Week

\*For TEM Air 3 hours/6 hours, please call ahead to schedule. There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

<b>PCM - Air</b> <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA	<b>TEM - Air</b> <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312	<b>TEM - Dust</b> <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167)
<b>PLM - Bulk (reporting limit)</b> <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198.1 (friable in NY) <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY) <input type="checkbox"/> NIOSH 9002 (<1%)	<b>TEM - Bulk</b> <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5 <b>TEM - Water:</b> EPA 100.2 Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes: <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	<b>Soil/Rock/Vermiculite</b> <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> EPA Protocol (Semi-Quantitative) <input type="checkbox"/> EPA Protocol (Quantitative)
<input type="checkbox"/> Check For Positive Stop - Clearly Identify Homogenous Group		

Samplers Name: Kelly Brown      Samplers Signature: [Signature]

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
1	Ground dirt patty		6-15-11
2	F6 ceiling insulation - mezzanine		
3	gray feather roofing - electric room		
4	brick & mortar - " "		
5	SR comp - " "		
6	Fiberboard behind wood siding - entrance		
7	Fiberboard wall panel - exterior south		
8	Door gasket - exterior south		

Client Sample # (s): 1-15      Total # of Samples: 15 bags

Relinquished (Client): [Signature]      Date: 6-19-11      Time: \_\_\_\_\_

Received (Lab): [Signature]      Date: 6/20/11      Time: 10:45am rainier

Comments/Special Instructions: Blig 110



# Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3466

Corporate -  
Westmont/Cinnaminson, NJ  
200 Route 130 North  
Cinnaminson, NJ 08077  
PHONE: 1-800-220-3675  
FAX: (856) 786-5974

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
9	conc block		
10	black shingle - roof 5LF		
11	clearcalk on hopper - roof		
12	black tan on hopper - roof 9LF		
13	roof membrane, tan + fiberboard		
14	silver shingle - roof		
15	green shingle - roof		
	roof deck		
	rubber membrane w/ tan o - seams		
	fiberboard		
	silver shingle		
	green shingle		
	wood		

Comments/Special Instructions:

Bag 10

**APPENDIX K**

<b>ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 5, Minneapolis, MN</b>					
<b>SAMPLE REFERENCE NUMBER</b>	<b>SUSPECT MATERIAL</b>	<b>LOCATION</b>	<b>% ASBESTOS ANALYTICAL RESULTS</b>	<b>FRIABLE OR NON-FRIABLE</b>	<b>QUANTITY</b>
1A-C	Stucco	Exterior	ND	NA	NA
2	Concrete block	Interior and exterior	ND	NA	NA
3	Drywall	Electrical room	ND	NA	NA
4	Gray door caulk	Interior - south	ND	NA	NA
5	Gray door caulk	Interior - north	ND	NA	NA
6	Gray door caulk	Exterior	ND	NA	NA
<b>7</b>	<b>Shingles and tarpaper</b>	<b>Roof</b>	<b>ND (shingles) 10% (tarpaper)</b>	<b>Category I non-friable</b>	<b>15,675 SF</b>

ND - Not detected at or above the laboratory detection limits.  
 SF - Square Feet.  
 LF - Linear Feet.




7615 Golden Triangle Dr., Suite N  
Eden Prairie, MN 55344  
(952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 5

By NOT TO SCALE Date \_\_\_\_\_



Sibley St NE



**APPENDIX L**



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103478

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 5**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1A 351103478-0001	stucco-Exterior South	White Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (other)	None Detected
1B 351103478-0002	stucco-Exterior South	White Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (other)	None Detected
1C 351103478-0003	stucco-Exterior South	White Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (other)	None Detected
2 351103478-0004	cone block	Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
3 351103478-0005	SR	Gray/Tan/White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
4 351103478-0006	door caulk-interior south	Gray Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 15:56:03

Analyst(s)  

---

*Heidi Johnson (10)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:45 AM  
EMSL Order: 351103478

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 5**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
5 351103478-0007	door caulk-interior north 20 LF	Gray Non-Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (other)	<b>None Detected</b>
6 351103478-0008	door caulk-exterior south 20 LF	Gray Non-Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (other)	<b>None Detected</b>
7-Shingle 351103478-0009	Roof shingles/tan paper	Brown/Black Fibrous Heterogeneous	35% Cellulose	65% Non-fibrous (other)	<b>None Detected</b>
7-Tar Paper 351103478-0009A	Roof shingles/tan paper	Black Fibrous Homogeneous	15% Cellulose	75% Non-fibrous (other)	<b>10% Chrysotile</b>

Initial report from 06/22/2011 15:56:03

Analyst(s)  

---

*Heidi Johnson (10)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



# Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3478

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

Company: Peer Engineering  
 Street: 7615 Golden Triangle Drive Suite N  
 City/State/Zip: Eden Prairie, MN 55447  
 Report To (Name): Kelly Brown  
 Telephone: 952-831-3341  
 Project Name/Number: Scherer  
 Please Provide Results: Email Purchase Order: State Samples Taken: MN

EMSL-Bill to:  Same  Different  
 If Bill to is Different note instructions in Comments\*\*  
 Third Party Billing requires written authorization from third party

Turnaround Time (TAT) Options\* - Please Check  
 3 Hour  6 Hour  24 Hour  48 Hour  72 Hour  96 Hour  1 Week  2 Week  
\*For TEM Air 3 hours/6 hours, please call ahead to schedule. There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

**PCM - Air**  
 NIOSH 7400  
 w/ OSHA 8hr. TWA  
**PLM - Bulk (reporting limit)**  
 PLM EPA 600/R-93/116 (<1%)  
 PLM EPA NOB (<1%)  
 Point Count  
 400 (<0.25%)  1000 (<0.1%)  
 Point Count w/Gravimetric  
 400 (<0.25%)  1000 (<0.1%)  
 NYS 198.1 (friable in NY)  
 NYS 198.6 NOB (non-friable-NY)  
 NIOSH 9002 (<1%)

**TEM - Air**  4-4.5hr TAT (AHERA only)  
 AHERA 40 CFR, Part 763  
 NIOSH 7402  
 EPA Level II  
 ISO 10312  
**TEM - Bulk**  
 TEM EPA NOB  
 NYS NOB 198.4 (non-friable-NY)  
 Chatfield SOP  
 TEM Mass Analysis-EPA 600 sec. 2.5  
**TEM - Water:** EPA 100.2  
 Fibers >10µm  Waste  Drinking  
 All Fiber Sizes  Waste  Drinking

**TEM - Dust**  
 Microvac - ASTM D 5755  
 Wipe - ASTM D6480  
 Carpet Sonication (EPA 600/J-93/167)  
**Soil/Rock/Vermiculite**  
 PLM CARB 435 - A (0.25% sensitivity)  
 PLM CARB 435 - B (0.1% sensitivity)  
 TEM CARB 435 - B (0.1% sensitivity)  
 TEM CARB 435 - C (0.01% sensitivity)  
 EPA Protocol (Semi-Quantitative)  
 EPA Protocol (Quantitative)  
**Other:**

Check For Positive Stop - Clearly Identify Homogenous Group

Samplers Name: Kelly Brown Samplers Signature: [Signature]

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
1A-C	stucco - exterior south		6-17-11
2	conc block		
3	SR		
4	down cable - interior south		
5	" " north 20'F		
6	" " exterior south 20'F		
7	Roof shingles/trapezoid		

Client Sample # (s): 1A - 7 Total # of Samples: 9 bags  
 Relinquished (Client): [Signature] Date: 6-19-11 Time:  
 Received (Lab): Crother Corning Date: 6-20-11 Time: 10:45 am

Comments/Special Instructions: Blind 5

APPENDIX M

**ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 6, Minneapolis, MN**

SAMPLE REFERENCE NUMBER	SUSPECT MATERIAL	LOCATION	% ASBESTOS ANALYTICAL RESULTS	FRIABLE OR/NON-FRIABLE	QUANTITY
1A-C	Fiberglass duct insulation	Mechanical room	ND	NA	NA
2A-C	Fiberglass pipe insulation	Interior	ND	NA	NA
3	Tan countertop material	Women's restroom	ND	NA	NA
4	Green countertop material	Lunchroom	ND	NA	NA
5	Off-white countertop material	Men's restroom	ND	NA	NA
6	Gray countertop material	Office	ND	NA	NA
7	Maroon vinyl baseboard and black and yellow mastics	Office, lunchroom, and locker room	ND	NA	NA
8	4" white ceramic wall tile and yellow mastic	Restrooms	ND	NA	NA
9	Concrete block with foam ball insulation	Interior around rooms in SEC	ND	NA	NA
10	Gray sink undercoat	Lunchroom	ND	NA	NA
11	Fiberglass ceiling insulation	Lunchroom	ND	NA	NA
12	Drywall composite	Office	ND	NA	NA
13	Carpet mastic	Office	ND	NA	NA
14	Tan door caulk	Interior	ND	NA	NA
15	6" brown ceramic floor tile	Restrooms	ND	NA	NA
<b>16</b>	<b>1 x 1' tan marble floor tile and black mastic</b>	<b>Lunchroom and locker room</b>	<b>ND (tile) 10% (mastic)</b>	<b>Category I non-friable</b>	<b>630 SF</b>
17	2' x 2' pinhole/divot ceiling tile	Women's restroom	ND	NA	NA
18	2' x 2' pinhole/fissure ceiling tile	Lunchroom and locker room	ND	NA	NA
19	2' x 2' chicken scratch ceiling tile	Men's restroom	ND	NA	NA
20	2' x 2' pinhole/fissure ceiling tile	Office	ND	NA	NA
21	Gray door caulk	Exterior - east	ND	NA	NA
22	Tan wall caulk	Exterior	ND	NA	NA
23	Decorative concrete	Exterior - east	ND	NA	NA
24	Gray wall caulk on overhang	Exterior - east (NEC)	ND	NA	NA
25	Roof deck material on overhang	Exterior - east (NEC)	ND	NA	NA

ND - Not detected at or above the laboratory detection limits.

SF - Square Feet.

LF - Linear Feet.

<b>ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 6, Minneapolis, MN</b>					
<b>SAMPLE REFERENCE NUMBER</b>	<b>SUSPECT MATERIAL</b>	<b>LOCATION</b>	<b>% ASBESTOS ANALYTICAL RESULTS</b>	<b>FRIABLE OR/NON-FRIABLE</b>	<b>QUANTITY</b>
<b>26</b>	<b>Roof flashing material</b>	<b>Exterior</b>	<b>ND (black fibrous layer) 3% (silver layer)</b>	<b>Category I non-friable</b>	<b>1,350 LF</b>
27	Roof deck tar	Exterior	ND	NA	NA
28	Roof deck fiberboard	Exterior	ND	NA	NA
29	Black fibrous roof flashing material	Exterior	<1%	NA	NA
30	Gray wall caulk on overhang	Exterior - roof	ND	NA	NA
31	Black wall caulk	Exterior - roof	ND	NA	NA
	<b>Metal-clad fire door</b>	<b>Mechanical room</b>	<b>Assumed</b>		<b>1 EA</b>

ND - Not detected at or above the laboratory detection limits.  
 SF - Square Feet.  
 LF - Linear Feet.




7615 Golden Triangle Dr., Suite N  
 Eden Prairie, MN 55344  
 (952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 6

By NOT TO SCALE Date \_\_\_\_\_



Ground Floor




7615 Golden Triangle Dr., Suite N  
Eden Prairie, MN 55344  
(952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 6

By NOT TO SCALE Date \_\_\_\_\_



**APPENDIX N**



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:50 AM  
EMSL Order: 351103477

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 6**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1A-Black Layer 351103477-0001	F6 Duct-mechanical Room	Black Non-Fibrous Homogeneous	15% Glass	85% Non-fibrous (other)	None Detected
1A-Yellow Layer 351103477-0001A	F6 Duct-mechanical Room	Yellow Fibrous Homogeneous	100% Min. Wool	0% Non-fibrous (other)	None Detected
1B-Black Layer 351103477-0002	F6 Duct-mechanical Room	Black/Silver Non-Fibrous Homogeneous	15% Glass	85% Non-fibrous (other)	None Detected
1B-Yellow Layer 351103477-0002A	F6 Duct-mechanical Room	Yellow Fibrous Homogeneous	100% Min. Wool	0% Non-fibrous (other)	None Detected
1C-Black Layer 351103477-0003	F6 Duct-mechanical Room	Black/Silver Non-Fibrous Homogeneous	15% Glass	85% Non-fibrous (other)	None Detected
1C-Yellow Layer 351103477-0003A	F6 Duct-mechanical Room	Yellow Fibrous Homogeneous	100% Min. Wool	0% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 17:10:05

Analyst(s)

Heidi Johnson (44)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:50 AM  
EMSL Order: 351103477

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 6**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
2A-Wrap 351103477-0004	F6 TSI-Room 1 SWC	Tan/White/Silver Non-Fibrous Homogeneous	75% Cellulose 15% Glass	10% Non-fibrous (other)	None Detected
2A-Insulation 351103477-0004A	F6 TSI-Room 1 SWC	Yellow Fibrous Homogeneous	100% Min. Wool	0% Non-fibrous (other)	None Detected
2B-Wrap 351103477-0005	F6 TSI-Room 1 North	Tan/White/Silver Fibrous Homogeneous	65% Cellulose 15% Glass	20% Non-fibrous (other)	None Detected
2B-Insulation 351103477-0005A	F6 TSI-Room 1 North	Yellow Fibrous Homogeneous	100% Min. Wool	0% Non-fibrous (other)	None Detected
2C-Wrap 351103477-0006	F6 TSI-Room 3	Tan/White/Silver Fibrous Homogeneous	65% Cellulose 15% Glass	20% Non-fibrous (other)	None Detected
2C-Insulation 351103477-0006A	F6 TSI-Room 3	Yellow Fibrous Homogeneous	100% Min. Wool	0% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 17:10:05

Analyst(s)  

---

*Heidi Johnson (44)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:50 AM  
EMSL Order: 351103477

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 6**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
3 351103477-0007	tan countertop-women's	Tan Fibrous Heterogeneous	65% Cellulose	35% Non-fibrous (other)	<b>None Detected</b>
4 351103477-0008	green countertop-lunchroom	Tan/Green Fibrous Heterogeneous	65% Cellulose	35% Non-fibrous (other)	<b>None Detected</b>
5 351103477-0009	off white countertop-men's	Tan/Cream Fibrous Heterogeneous	65% Cellulose	35% Non-fibrous (other)	<b>None Detected</b>
6 351103477-0010	gray countertop-office	Gray/Tan Fibrous Heterogeneous	65% Cellulose	35% Non-fibrous (other)	<b>None Detected</b>
7-Baseboard 351103477-0011	maroon BB-office	Red Non-Fibrous Homogeneous		100% Non-fibrous (other)	<b>None Detected</b>
7-Yellow Mastic 351103477-0011A	maroon BB-office	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (other)	<b>None Detected</b>

Initial report from 06/22/2011 17:10:05

Analyst(s)  

---

*Heidi Johnson (44)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:50 AM  
EMSL Order: 351103477

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 6**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
7-Black Mastic 351103477-0011B	maroon BB-office	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
8-Ceramic Tile 351103477-0012	4" white ceramic wall tile-women's	White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
8-Mastic 351103477-0012A	4" white ceramic wall tile-women's	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
9-White Layer 351103477-0013	cone block & foam bull files-by office	White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
9-Gray Layer 351103477-0013A	cone block & foam bull files-by office	Gray Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
10 351103477-0014	gray sink-lunch	Gray Non-Fibrous Homogeneous	15% Cellulose	85% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 17:10:05

Analyst(s)

Heidi Johnson (44)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:50 AM  
EMSL Order: 351103477

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 6**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
11 351103477-0015	F6 ceiling insulation-lunch	Tan/Black/Yellow	45% Cellulose	5% Non-fibrous (other)	None Detected
		Fibrous Homogeneous	50% Min. Wool		
12 351103477-0016	SR comp-office	Tan/White	40% Cellulose	10% Non-fibrous (other)	None Detected
		Non-Fibrous Heterogeneous	40% Min. Wool		
Sheetrock/Joint Compound					
13 351103477-0017	carpet matic-office (1/2 area)	Tan Non-Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (other)	None Detected
14 351103477-0018	Door caulk-office interior 20Lf	Cream Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
15 351103477-0019	6" brown ceramic FT-women's	Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
16-Floor Tile 351103477-0020	1x1 tan marble FT-lunch	Beige Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 17:10:05

Analyst(s)  

---

*Heidi Johnson (44)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:50 AM  
EMSL Order: 351103477

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 6**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
16-Mastic 351103477-0020A	1x1 tan marble FT-lunch	Black Non-Fibrous Homogeneous		90% Non-fibrous (other)	10% Chrysotile
17 351103477-0021	2x2 pld CT-women's	Gray/White Fibrous Homogeneous	40% Cellulose 40% Min. Wool	10% Non-fibrous (other) 10% Perlite	None Detected
18 351103477-0022	2x2 plf CT-lunch	Gray/White Fibrous Homogeneous	40% Cellulose 40% Min. Wool	10% Non-fibrous (other) 10% Perlite	None Detected
19 351103477-0023	2x2 CS CT-men's	Gray/White Fibrous Homogeneous	40% Cellulose 40% Min. Wool	10% Non-fibrous (other) 10% Perlite	None Detected
20 351103477-0024	2x2 plf CT-office	Gray/White Fibrous Homogeneous	40% Cellulose 40% Min. Wool	10% Non-fibrous (other) 10% Perlite	None Detected
21 351103477-0025	Door caulk-Exterior East	Gray Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 17:10:05

Analyst(s)  

---

*Heidi Johnson (44)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:50 AM  
EMSL Order: 351103477

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 6**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
22 351103477-0026	Wall caulk-Exterior NEC + SEC 50Lf	Cream Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
23 351103477-0027	decorative concrete-Exterior East	Gray Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
24 351103477-0028	Wall culk on overhang-Exterior East side (NEC) 45	Gray Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
25-Black Layer 351103477-0029	overhang roof deck-Exterior East Side (NEC) 45x12	Black Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
25-Fibrous Layer 351103477-0029A	overhang roof deck-Exterior East Side (NEC) 45x12	Tan Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (other)	None Detected
26-Tar Layer 351103477-0030	overhang roof flashing-Exterior East Side (NEC)	Black Non-Fibrous Homogeneous	10% Glass	90% Non-fibrous (other)	None Detected

Initial report from 06/22/2011 17:10:05

Analyst(s)

Heidi Johnson (44)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:50 AM  
EMSL Order: 351103477

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 6**

EMSL Proj:  
Analysis Date: 6/22/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
26-Fibrous Black Layer 351103477-0030A	overhang roof flashing-Exterior East Side (NEC)	Black Fibrous Heterogeneous	35% Cellulose	65% Non-fibrous (other)	None Detected
26-Silver layer 351103477-0030B	overhang roof flashing-Exterior East Side (NEC)	Silver Non-Fibrous Homogeneous		97% Non-fibrous (other)	3% Chrysotile

Initial report from 06/22/2011 17:10:05

Analyst(s)  

---

*Heidi Johnson (44)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



# Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3477

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

Company: Peer Engineering		EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments** Third Party Billing requires written authorization from third party	
Street: 7615 Golden Triangle Drive Suite N			
City/State/Zip: Eden Prairie, MN 55447			
Report To (Name): Kelly Brown		Fax:	
Telephone: 952-831-3341		Email Address: kbrown@peerengineering.com	
Project Name/Number: <u>Scheper</u>			
Please Provide Results: Email		Purchase Order:	State Samples Taken: MN

**Turnaround Time (TAT) Options - Please Check**

3 Hour  
  6 Hour  
  24 Hour  
  48 Hour  
 72 Hour  
 96 Hour  
 1 Week  
 2 Week

\*For TEM Air 3 hours/6 hours, please call ahead to schedule. There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

<b>PCM - Air</b> <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA <b>PLM - Bulk (reporting limit)</b> <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198.1 (friable in NY) <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY) <input type="checkbox"/> NIOSH 9002 (<1%)	<b>TEM - Air</b> <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 <b>TEM - Bulk</b> <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5 <b>TEM - Water:</b> EPA 100.2 Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	<b>TEM - Dust</b> <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167) <b>Soil/Rock/Vermiculite</b> <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> EPA Protocol (Semi-Quantitative) <input type="checkbox"/> EPA Protocol (Quantitative) <b>Other:</b> <input type="checkbox"/>
---	--	---

Check For Positive Stop - Clearly Identify Homogenous Group

Samplers Name: Kelly Brown      Samplers Signature: [Signature]

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
1A-C	FG dust - mech room		6-17-11
2A	FG TSI - room 1 SWC		
2B	" " Room 1 north		
2C	" " Room 3		
3	tan counter-top - women's		
4	green counter-top - locker		
5	off white counter-top - men's		
6	gray counter-top - office		

Client Sample # (s): 1A, 2B      Total # of Samples: 30 bags

Relinquished (Client): [Signature]      Date: 6-19-11      Time:

Received (Lab): Crother Courier      Date: 6-20-11      Time: 10:50 am

Comments/Special Instructions: Blng 6



## Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3477

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
7	maroon BB - office		
8	4" white ceramic wall tile - women's		
9	conc block + form bull files - by office		
10	gray sink - lunch		
11	FG ceiling panel - lunch		
12	SR comp - office		
13	Carpet mastic - office (1/2 area)		
14	Door cork - office, interior 20CF		
15	6" brown ceramic FT - women's		
16	1x1 tan marble FT - lunch		
17	2x2 p/d CT - women's		
18	2x2 p/f CT - lunch		
19	2x2 CS CT - men's		
20	2x2 p/f CT - office		
21	Door cork - exterior east		
22	wall cork - exterior NE + SE 50 CF		
Comments/Special Instructions: <u>B 1596</u>			

Controlled Document - Asbestos Lab Services COC - A1.0 - 11/23/2009

Page 2 of 3 Pages





**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Ryan Spencer**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/24/11 4:00 PM  
EMSL Order: 351103638

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer/20074**

EMSL Proj:  
Analysis Date: 6/28/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos			Asbestos
			%	Fibrous	% Non-Fibrous	% Type
27 351103638-0001	Black roof deck tar	Black Fibrous Heterogeneous	35%	Cellulose	65% Non-fibrous (other)	None Detected
28-Brown Layer 351103638-0002	Black roof paper	Brown Fibrous Heterogeneous	90%	Cellulose	10% Non-fibrous (other)	None Detected
28-Black Layer 351103638-0002A	Black roof paper	Black Fibrous Heterogeneous	40%	Cellulose	60% Non-fibrous (other)	None Detected
29 351103638-0003	Gray roof Flashing	Black Fibrous Heterogeneous	10%	Glass 5% Cellulose	85% Non-fibrous (other)	<1% Chrysotile
30 351103638-0004	Gray wall caulk	Gray Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
31 351103638-0005	Black wall caulk	Brown/Black Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected

Initial report from 06/29/2011 08:16:57

Analyst(s)

Kaitlyn Kubokawa (6)

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. E no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be use client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem ; therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



# Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3638

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

Company: Peer Engineering		EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different <small>If Bill to is Different note instructions in Comments**</small>	
Street: 7615 Golden Triangle Dr. Suite N		Third Party Billing requires written authorization from third party	
City/State/Zip: Eden Prairie, MN 55344			
Report To (Name): Ryan Spencer		Fax: 952-831-4552	
Telephone: 952-831-3341		Email Address: rspencer@peerengineering.com	
Project Name/Number: <u>Scherer / 20074</u>			
Please Provide Results: Email		Purchase Order:	State Samples Taken: MN

**Turnaround Time (TAT) Options\* - Please Check**

3 Hour   
  6 Hour   
  24 Hour   
  48 Hour   
 72 Hour   
 96 Hour   
 1 Week   
 2 Week

\*For TEM Air 3 hours/6 hours, please call ahead to schedule. There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

<b>PCM - Air</b> <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA <b>PLM - Bulk (reporting limit)</b> <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198.1 (friable in NY) <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY) <input type="checkbox"/> NIOSH 9002 (<1%)	<b>TEM - Air</b> <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 <b>TEM - Bulk</b> <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 800 sec. 2.5 <b>TEM - Water:</b> EPA 100.2 Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	<b>TEM- Dust</b> <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167) <b>Soil/Rock/Vermiculite</b> <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> EPA Protocol (Semi-Quantitative) <input type="checkbox"/> EPA Protocol (Quantitative) <b>Other:</b> <input type="checkbox"/>
---	--	--

Check For Positive Stop - Clearly Identify Homogenous Group

Samplers Name: <u>Ryan Spencer</u>	Samplers Signature: <u>Ryan Spencer</u>
------------------------------------	---

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
27	Black roof deck tar		6-24-11
28	Black roof paper		↓
29	Gray roof Flashing		
30	Gray wall caulk		
31	Black wall caulk		

Client Sample # (s):	-	Total # of Samples:
Relinquished (Client): <u>Ryan Spencer</u>	Date: <u>6-24-11</u>	Time: <u>3:00</u>
Received (Lab): <u>Kelly Smeltz</u>	Date: <u>6/24/11</u>	Time: <u>4 pm</u>

COURIER

Comments/Special Instructions:

**APPENDIX O**

<b>ASBESTOS SUMMARY TABLE - Scherer Brothers Lumber, Building 9, Minneapolis, MN</b>					
<b>SAMPLE REFERENCE NUMBER</b>	<b>SUSPECT MATERIAL</b>	<b>LOCATION</b>	<b>% ASBESTOS ANALYTICAL RESULTS</b>	<b>FRIABLE OR NON-FRIABLE</b>	<b>QUANTITY</b>
1	Remnant black floor tar	Interior - north	ND	NA	NA
2A-C	Fiberglass pipe insulation	Interior	ND	NA	NA
3	Drywall	Office	ND	NA	NA
4	Gray countertop material	Office	ND	NA	NA
5	White wall caulk	Exterior - west (NWC)	ND	NA	NA
6	Gray wall expansion caulk	Exterior - east (NEC)	ND	NA	NA
7A-B	Tan door caulk	Exterior	ND	NA	NA
8	Concrete block	Interior and exterior	ND	NA	NA
9	Roof deck material (tar, tarpaper and fiberboard)	Roof	ND	NA	NA
10	Roof flashing (tar, trapaper and fiberboard)	Roof	ND	NA	NA
	<b>Metal-clad fire doors</b>	<b>Interior</b>	<b>Assumed</b>		<b>5 EA</b>

ND - Not detected at or above the laboratory detection limits.  
SF - Square Feet.  
LF - Linear Feet.




7615 Golden Triangle Dr., Suite N  
Eden Prairie, MN 55344  
(952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 9

By NOT TO SCALE Date \_\_\_\_\_



8<sup>th</sup> AVE NE



**APPENDIX P**



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:50 AM  
EMSL Order: 351103465

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 9**

EMSL Proj:  
Analysis Date: 6/21/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1 351103465-0001	Floor tar	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
2A 351103465-0002	F6 TSI	White/Yellow Fibrous Homogeneous	85% Min. Wool 10% Cellulose	5% Non-fibrous (other)	None Detected
2B 351103465-0003	F6 TSI	White/Yellow Fibrous Heterogeneous	10% Cellulose 85% Min. Wool	5% Non-fibrous (other)	None Detected
2C 351103465-0004	F6 TSI	White/Yellow Fibrous Heterogeneous	10% Cellulose 85% Min. Wool	5% Non-fibrous (other)	None Detected
3 351103465-0005	SR - office	Tan/White Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (other)	None Detected
4 351103465-0006	gray contact p 15 - office	Gray Fibrous Heterogeneous	75% Cellulose	25% Non-fibrous (other)	None Detected

Initial report from 06/21/2011 16:20:18

Analyst(s)  

---

*Heidi Johnson (15)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:50 AM  
EMSL Order: 351103465

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 9**

EMSL Proj:  
Analysis Date: 6/21/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
5 351103465-0007	Exterior West - wall caulk	White Non-Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (other)	None Detected
6 351103465-0008	Exterior East - NEC expansion caulk	Gray/White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
7A 351103465-0009	Exterior West - Door caulk	Tan Non-Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (other)	None Detected
7B 351103465-0010	Exterior East - Door caulk	Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
8 351103465-0011	cone block	Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
9-Black Layer 351103465-0012	Roof Deck	Black Non-Fibrous Homogeneous	15% Glass	85% Non-fibrous (other)	None Detected

Initial report from 06/21/2011 16:20:18

Analyst(s)  

---

*Heidi Johnson (15)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



**EMSL Analytical, Inc.**

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: [minneapolislab@emsl.com](mailto:minneapolislab@emsl.com)

Attn: **Kelly Brown**  
**Peer Engineering**  
**7615 Golden Triangle Drive**  
**Suite N**  
**Eden Prairie, MN 55344**

Customer ID: PEER50  
Customer PO:  
Received: 06/20/11 10:50 AM  
EMSL Order: 351103465

Fax: (952) 831-4552 Phone: (952) 831-3341  
Project: **Scherer Bldg 9**

EMSL Proj:  
Analysis Date: 6/21/2011

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**


Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
9-Fibrous Layer 351103465-0012A	Roof Deck	Brown Fibrous Homogeneous	85% Cellulose	15% Non-fibrous (other)	<b>None Detected</b>
10-Grey Layer 351103465-0013	Roof flashing	Gray/Black Non-Fibrous Homogeneous	35% Cellulose	65% Non-fibrous (other)	<b>None Detected</b>
10-Tar Layer 351103465-0013A	Roof flashing	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	<b>None Detected</b>

Initial report from 06/21/2011 16:20:18

Analyst(s)  

---

*Heidi Johnson (15)*

---

Rachel Travis, Laboratory Manager  
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.  
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn NVLAP Lab Code 200019-0



# Asbestos Lab Services Chain of Custody

EMSL Order Number (Lab Use Only):

3465

Minneapolis, MN  
 14375 23rd Avenue North  
 Minneapolis, MN 55447  
 PHONE: (763) 449-4922  
 FAX: (763) 449-4924

**Company:** Peer Engineering  
**Street:** 7615 Golden Triangle Drive Suite N  
**City/State/Zip:** Eden Prairie, MN 55447  
**Report To (Name):** Kelly Brown  
**Telephone:** 952-831-3341  
**Project Name/Number:** Scherer

**EMSL-Bill to:**  Same  Different  
 If Bill to is Different note instructions in Comments\*\*  
 Third Party Billing requires written authorization from third party

**Fax:**  
**Email Address:** kbrown@peerengineering.com

**Please Provide Results:** Email **Purchase Order:** **State Samples Taken:** MN

**Turnaround Time (TAT) Options\* - Please Check**  
 3 Hour  6 Hour  24 Hour  48 Hour  72 Hour  96 Hour  1 Week  2 Week

\*For TEM Air 3 hours/6 hours, please call ahead to schedule. There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

<b>PCM - Air</b> <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA <b>PLM - Bulk (reporting limit)</b> <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198.1 (friable in NY) <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY) <input type="checkbox"/> NIOSH 9002 (<1%)	<b>TEM - Air</b> <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 <b>TEM - Bulk</b> <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5 <b>TEM - Water:</b> EPA 100.2 Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	<b>TEM - Dust</b> <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167) <b>Soil/Rock/Vermiculite</b> <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> EPA Protocol (Semi-Quantitative) <input type="checkbox"/> EPA Protocol (Quantitative) <b>Other:</b> <input type="checkbox"/>
---	--	---

Check For Positive Stop - Clearly Identify Homogenous Group

**Samplers Name:** Kelly Brown **Samplers Signature:** *[Signature]*

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
1	Floor tan 500φ		6-15-11
2A-C	F6 TSI		
3	SR-office		
4	gray contact p 15φ - office		
5	exterior west - wall walk		
6	exterior east - MEC expansion walk		
7A	exterior west - door walk		
7B	" exit - door walk		

**Client Sample # (s):** 1 - 10 **Total # of Samples:** 13 bags

**Relinquished (Client):** *[Signature]* **Date:** 6-19-11 **Time:**

**Received (Lab):** *[Signature]* **Date:** 6-20-11 **Time:** 10:50am

**Comments/Special Instructions:** *Blng 9*



**APPENDIX Q**

Reading No	Time	Type	Duration	Units	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Misc 1	Misc 2	Results	Depth Index	Action Level	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
1	6/20/2011 7:18	SHUTTER_CAL	58.39	cps														5.63	0	1.08	0	0	0
2	6/20/2011 7:19	Calibration to 1.0	8.61	mg / cm ^2											Positive	1.18	1	1.1	0.1	1.1	0.1	0.8	0.5
3	6/20/2011 7:19	Calibration to 1.0	6.96	mg / cm ^2											Negative	1.09	1	0.9	0.1	0.9	0.1	0.8	0.5
4	6/20/2011 7:20	Calibration to 1.0	6.45	mg / cm ^2											Negative	1.05	1	0.9	0.1	0.9	0.1	1	0.6
5	6/20/2011 7:24	PAINT	3.77	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	1B	1	Vault			Negative	1	1	0	0.02	0	0.02	0.4	0.9
6	6/20/2011 7:24	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1B	1	Vault			Negative	2.87	1	0.01	0.02	0.01	0.02	0.5	0.9
7	6/20/2011 7:24	PAINT	4.29	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	1B	1	Vault			Positive	2.65	1	2.1	1	1.2	0.2	2.1	1
8	6/20/2011 7:25	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	1B	1	Vault			Negative	1	1	0	0.02	0	0.02	0.4	0.9
9	6/20/2011 7:25	PAINT	3.23	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	1B	1	Vault			Negative	1	1	0	0.02	0	0.02	0.11	1.52
10	6/20/2011 7:27	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	1B	1	Vault			Negative	1	1	0	0.02	0	0.02	0.3	0.93
11	6/20/2011 7:28	PAINT	2.14	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1B	1	Behind communications			Negative	1.07	1	0	0.02	0	0.02	< LOD	0
12	6/20/2011 7:31	PAINT	3.22	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	1B	1	West electrical room			Negative	3.84	1	0.01	0.05	0.01	0.05	0.19	1.48
13	6/20/2011 7:34	PAINT	3.78	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	1B	1	Storage 1			Negative	1	1	0	0.02	0	0.02	0.7	0.9
14	6/20/2011 7:34	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1B	1	Storage 1			Negative	1	1	0	0.02	0	0.02	0.5	0.8
15	6/20/2011 7:34	PAINT	3.23	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	1B	1	Storage 1			Negative	1.94	1	0	0.02	0	0.02	0.18	1.38
16	6/20/2011 7:35	PAINT	2.15	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	1B	1	Storage 1			Negative	3.84	1	0.01	0.06	0.01	0.06	0.06	1.61
17	6/20/2011 7:36	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	1B	1	Storage 2			Negative	1	1	0	0.02	0	0.02	0.8	0.8
18	6/20/2011 7:37	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	1B	1	Mechanical			Negative	1	1	0	0.02	0	0.02	0.6	0.9
19	6/20/2011 7:39	PAINT	3.24	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	1B	1	West stairwell			Negative	1	1	0	0.02	0	0.02	0.12	1.52
20	6/20/2011 7:39	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	1B	1	Storage 3			Negative	1	1	0	0.02	0	0.02	0.5	0.9
21	6/20/2011 7:40	PAINT	4.28	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	1B	1	Storage 3			Negative	6.62	1	0.04	0.07	0.04	0.07	0.4	0.9
22	6/20/2011 7:41	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	1B	1	West Drive Thru			Negative	1	1	0	0.02	0	0.02	0.7	0.9
23	6/20/2011 7:41	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1B	1	West Drive Thru			Negative	1.41	1	0.02	0.02	0.02	0.02	0.28	0.9
24	6/20/2011 7:42	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	1B	1	West Drive Thru			Negative	1	1	0.01	0.02	0.01	0.02	0.28	0.95
25	6/20/2011 7:42	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	1B	1	West Drive Thru			Negative	1.72	1	0.01	0.02	0.01	0.02	0.4	0.9
26	6/20/2011 7:43	PAINT	1.07	mg / cm ^2	WALL	WOOD	A	FAIR	WHITE	1B	1	South Drive Thru		2000 SF	Positive	2.33	1	2.9	1.5	2.9	1.5	3	3.5
27	6/20/2011 7:44	PAINT	1.07	mg / cm ^2	WALL	WOOD	A	FAIR	WHITE	1B	1	South Drive Thru		2000 SF	Positive	2.97	1	2.7	1.7	2.7	1.7	2.5	3.3
28	6/20/2011 7:45	PAINT	1.07	mg / cm ^2	WALL	WOOD	D	FAIR	WHITE	1B	1	East Drive Thru			Negative	1	1	0.01	0.04	0.01	0.04	0.5	2.2
29	6/20/2011 7:45	PAINT	1.07	mg / cm ^2	WALL	WOOD	D	FAIR	WHITE	1B	1	East Drive Thru			Negative	1	1	0	0.02	0	0.02	0.05	1.78
30	6/20/2011 7:46	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1B	1	East Drive Thru			Negative	1.58	1	0.02	0.02	0.02	0.02	0.6	0.9
31	6/20/2011 7:47	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	1B	1	South Drive Thru			Negative	2.83	1	0.02	0.03	0.02	0.03	0.3	0.91
32	6/20/2011 7:47	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	1B	1	South Drive Thru			Negative	3.83	1	0.01	0.02	0.01	0.02	0.7	0.9
33	6/20/2011 7:49	PAINT	3.75	mg / cm ^2	FLOOR	CONCRETE		FAIR	YELLOW	1B	1	South Drive Thru	Stripe		Negative	1	1	0	0.02	0	0.02	0.7	0.9
34	6/20/2011 7:50	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	1B	1	South Drive Thru			Negative	1.76	1	0	0.02	0	0.02	0.5	0.8
35	6/20/2011 7:51	PAINT	3.77	mg / cm ^2	FLOOR	CONCRETE		INTACT	YELLOW	1B	1	West Drive Thru	Stripe		Negative	1	1	0	0.02	0	0.02	0.4	0.9
36	6/20/2011 7:53	PAINT	3.74	mg / cm ^2	FLOOR	CONCRETE		INTACT	YELLOW	1B	1	East Drive Thru	Stripe		Negative	1.92	1	0.01	0.02	0.01	0.02	0.4	1
37	6/20/2011 7:55	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	1C	1	Open area			Negative	1	1	0	0.02	0	0.02	0.4	0.9
38	6/20/2011 7:55	PAINT	3.22	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1C	1	Open area			Negative	1.15	1	0	0.02	0	0.02	0.3	1.39
39	6/20/2011 7:56	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1C	1	Open area			Negative	1.74	1	0	0.02	0	0.02	0.4	0.9
40	6/20/2011 7:56	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	1C	1	Open area			Negative	1.19	1	0	0.02	0	0.02	0.4	0.9
41	6/20/2011 7:57	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	D	FAIR	WHITE	1C	1	Open area			Negative	6.59	1	0.03	0.06	0.03	0.06	< LOD	0
42	6/20/2011 7:58	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	D	FAIR	WHITE	1C	1	Open area			Negative	1	1	0	0.02	0	0.02	0.6	0.9
43	6/20/2011 7:59	PAINT	4.28	mg / cm ^2	WALL	CONCRETE	A	INTACT	GREEN	1C	1	Open area			Negative	2.04	1	0	0.02	0	0.02	0.8	0.8
44	6/20/2011 8:00	PAINT	4.81	mg / cm ^2	WALL	CONCRETE	B	POOR	WHITE	1C	1	Open area bay			Negative	2.97	1	0.5	0.1	0.5	0.1	0.8	0.8
45	6/20/2011 8:01	PAINT	6.98	mg / cm ^2	WALL	CONCRETE	C	POOR	WHITE	1C	1	Open area bay			Negative	6.63	1	0.05	0.06	0.05	0.06	1	0.7
46	6/20/2011 8:01	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	D	POOR	WHITE	1C	1	Open area bay			Negative	2.71	1	0.01	0.02	0.01	0.02	0.7	0.9
47	6/20/2011 8:03	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	1C	1	South loading dock			Negative	1	1	0	0.02	0	0.02	0.4	0.9
48	6/20/2011 8:04	PAINT	1.6	mg / cm ^2	WALL	WOOD	B	FAIR	WHITE	1C	1	South loading dock		60 SF	Positive	4.38	1	3.1	1.4	3.1	1.4	3.5	2.3
49	6/20/2011 8:05	PAINT	1.07	mg / cm ^2	DOOR	METAL	D	POOR	WHITE	1C	1	South loading dock	Overhead door		Negative	1	1	0	0.03	0	0.03	0.3	1.88
50	6/20/2011 8:06	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	A	FAIR	WHITE	1C	1	Wood shop			Negative	1	1	0	0.02	0	0.02	0.4	0.9
51	6/20/2011 8:06	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1C	1	Wood shop			Negative	1	1	0	0.02	0	0.02	0.4	0.9
52	6/20/2011 8:07	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	C	POOR	WHITE	1C	1	Wood shop			Negative	2.4	1	0	0.02	0	0.02	0.8	0.9
53	6/20/2011 8:07	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	D	POOR	WHITE	1C	1	Wood shop			Negative	1	1	0	0.02	0	0.02	0.6	0.9
54	6/20/2011 8:08	PAINT	1.08	mg / cm ^2	DOOR	METAL	A	POOR	WHITE	1C	1	Wood shop	Overhead door		Negative	1	1	0	0.03	0	0.03	< LOD	0
55	6/20/2011 8:09	PAINT	0.53	mg / cm ^2	FLOOR	CONCRETE		FAIR	YELLOW	1C	1	Wood shop	Stripe	75 LF	Positive	1.45	1	4.5	2.5	4.5	2.5	6.1	9.2
56	6/20/2011 8:11	PAINT	2.67	mg / cm ^2	WALL	CONCRETE	C	INTACT	YELLOW	1C	1	Wood shop	East door		Negative	1.42	1	0	0.02	0	0.02	0.03	1.62
57	6/20/2011 8:12	PAINT	3.22	mg / cm ^2	FLOOR	CONCRETE		INTACT	YELLOW	1C	1	Open area	Stripe		Negative	1	1	0	0.02	0	0.02	0.15	1.46
58	6/20/2011 8:13	PAINT	3.76	mg / cm ^2	FLOOR	CONCRETE		INTACT	YELLOW	1C	1	Open area											

62	6/20/2011 8:16	PAINT	1.6	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	1C	1	North loading dock		Negative	1	1	0	0.02	0	0.02	< LOD	0
63	6/20/2011 8:16	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	1C	1	North loading dock		Negative	1.82	1	0.01	0.02	0.01	0.02	0.3	0.95
<b>64</b>	<b>6/20/2011 8:17</b>	<b>PAINT</b>	<b>0.54</b>	<b>mg / cm ^2</b>	<b>FLOOR</b>	<b>CONCRETE</b>		<b>INTACT</b>	<b>YELLOW</b>	<b>1C</b>	<b>1</b>	<b>North loading dock</b>	<b>Stripe</b>	<b>Positive</b>	<b>1.18</b>	<b>1</b>	<b>2.5</b>	<b>1.4</b>	<b>2.5</b>	<b>1.4</b>	<b>4.5</b>	<b>8.5</b>
65	6/20/2011 8:18	PAINT	3.73	mg / cm ^2	FLOOR	CONCRETE		INTACT	WHITE	1C	1	North loading dock	Stripe	Negative	1	1	0	0.02	0	0.02	0.3	0.92
<b>66</b>	<b>6/20/2011 8:20</b>	<b>PAINT</b>	<b>3.77</b>	<b>mg / cm ^2</b>	<b>WALL</b>	<b>WOOD</b>	<b>B</b>	<b>FAIR</b>	<b>WHITE</b>	<b>1D</b>	<b>1</b>	<b>Shop</b>		<b>Positive</b>	<b>6.52</b>	<b>1</b>	<b>1.9</b>	<b>0.8</b>	<b>1.4</b>	<b>0.4</b>	<b>1.9</b>	<b>0.8</b>
67	6/20/2011 8:21	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1D	1	Shop		Negative	5.2	1	0.06	0.08	0.06	0.08	0.5	0.9
68	6/20/2011 8:22	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	1D	1	Shop		Negative	3.13	1	0.01	0.02	0.01	0.02	0.5	0.9
69	6/20/2011 8:23	PAINT	3.73	mg / cm ^2	FLOOR	CONCRETE		INTACT	YELLOW	1D	1	Shop	Stripe	Negative	1	1	0	0.02	0	0.02	0.6	0.9
70	6/20/2011 8:24	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	1D	1	Electrical room		Negative	1	1	0	0.02	0	0.02	0.7	0.9
71	6/20/2011 8:24	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1D	1	Electrical room		Negative	1.53	1	0	0.02	0	0.02	0.25	0.9
72	6/20/2011 8:25	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	B	INTACT	GREEN	1D	1	Electrical room		Negative	2.33	1	0.01	0.02	0.01	0.02	0.4	0.9
73	6/20/2011 8:26	PAINT	3.74	mg / cm ^2	WALL	BRICK	B	INTACT	GREEN	1D	1	Electrical room		Negative	1.61	1	0	0.02	0	0.02	0.3	0.88
74	6/20/2011 8:27	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	1D	1	Electrical room		Negative	1	1	0	0.02	0	0.02	0.5	0.9
75	6/20/2011 8:28	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1D	2	Mezzanine		Negative	2.03	1	0	0.02	0	0.02	0.5	0.9
76	6/20/2011 8:28	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	1D	2	Mezzanine		Negative	1	1	0	0.02	0	0.02	0.6	0.9
77	6/20/2011 8:29	PAINT	3.78	mg / cm ^2	WALL	BRICK	B	INTACT	WHITE	1D	2	Mezzanine		Negative	1	1	0	0.02	0	0.02	0.3	0.88
78	6/20/2011 8:35	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	1B	2	West storage by mezzanine		Negative	1	1	0	0.02	0	0.02	0.22	0.9
79	6/20/2011 8:35	PAINT	0.54	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE					Null	1.16	1	0	0.02	0	0.02	< LOD	0
80	6/20/2011 8:36	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	1B	2	Mezzanine		Negative	1.33	1	0	0.02	0	0.02	0.7	0.8
81	6/20/2011 8:37	PAINT	1.07	mg / cm ^2	WALL	WOOD	B	FAIR	WHITE	1B	2	Mezzanine		Negative	4.63	1	0.17	0.44	0.17	0.44	0.24	2.07
82	6/20/2011 8:37	PAINT	1.07	mg / cm ^2	WALL	WOOD	B	FAIR	WHITE	1B	2	Mezzanine		Negative	5.58	1	0.08	0.35	0.08	0.35	0.25	1.99
83	6/20/2011 8:43	PAINT	0.54	mg / cm ^2	WINDOW	WOOD	C	POOR	BROWN				SASH	Null	1	1	0	0.04	0	0.04	< LOD	0
84	6/20/2011 8:43	PAINT	1.06	mg / cm ^2	WINDOW	WOOD	C	POOR	BROWN	1B	2	Exterior north	SASH	Negative	1	1	0	0.02	0	0.02	0.01	1.63
85	6/20/2011 8:44	PAINT	1.07	mg / cm ^2	WINDOW	WOOD	C	POOR	BROWN	1B	2	Exterior north	SILL	Negative	1	1	0	0.02	0	0.02	0.7	1.9
86	6/20/2011 8:46	PAINT	1.07	mg / cm ^2	WINDOW	WOOD	C	POOR	BROWN	1B	2	Exterior north	SILL	Negative	1	1	0	0.03	0	0.03	0.05	1.96
87	6/20/2011 8:46	PAINT	1.07	mg / cm ^2	WINDOW	WOOD	C	POOR	BROWN	1B	2	Exterior north	SASH	Negative	1	1	0	0.02	0	0.02	0.5	1.9
88	6/20/2011 8:47	PAINT	1.07	mg / cm ^2	WINDOW	WOOD	C	POOR	BROWN	1B	2	Exterior north	FRAME	Negative	1	1	0	0.02	0	0.02	0.17	1.85
89	6/20/2011 8:50	PAINT	1.06	mg / cm ^2	DOOR	WOOD	B	POOR	WHITE	1B	3	Exterior west - roof access	FRAME	Negative	1	1	0	0.02	0	0.02	< LOD	0
90	6/20/2011 8:50	PAINT	1.08	mg / cm ^2	DOOR	WOOD	B	POOR	WHITE	1B	3	Exterior west - roof access	STOP	Negative	1	1	0	0.02	0	0.02	0.1	1.79
91	6/20/2011 8:51	PAINT	1.07	mg / cm ^2	WALL	WOOD	D	POOR	WHITE	1B	3	Exterior west - roof access		Negative	1.05	1	0.01	0.04	0.01	0.04	0.18	2.63
92	6/20/2011 8:52	PAINT	1.07	mg / cm ^2	VENT	WOOD	B	POOR	WHITE	1B	3	Exterior west wall on roof	SLAT	Negative	1	1	0	0.03	0	0.03	0.29	1.42
93	6/20/2011 8:53	PAINT	1.08	mg / cm ^2	VENT	WOOD	B	POOR	WHITE	1B	3	Exterior west wall on roof	frame	Negative	1	1	0	0.02	0	0.02	0.3	1.68
94	6/20/2011 8:57	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	9		Exterior north wall near roof		Negative	1.57	1	0	0.02	0	0.02	0.3	0.89
95	6/20/2011 8:59	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1B		Exterior west wall on roof		Negative	1.88	1	0	0.02	0	0.02	0.6	0.9
96	6/20/2011 8:59	PAINT	1.07	mg / cm ^2	WALL	WOOD	B	POOR	WHITE	1B		Exterior west wall on roof	trim	Negative	1	1	0	0.02	0	0.02	0.4	1.7
97	6/20/2011 9:01	PAINT	1.08	mg / cm ^2	WALL	WOOD	B	POOR	WHITE				trim	Negative	1.16	1	0.01	0.04	0.01	0.04	0.4	1.9
98	6/20/2011 9:01	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1B		Exterior west wall on roof		Negative	1.54	1	0	0.02	0	0.02	0.3	0.9
99	6/20/2011 9:02	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	9		Exterior north wall near roof		Negative	1	1	0	0.02	0	0.02	0.4	0.9
100	6/20/2011 9:03	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	D	FAIR	WHITE	1D		Exterior east wall on roof		Negative	1	1	0	0.02	0	0.02	0.8	0.9
101	6/20/2011 9:03	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	D	FAIR	WHITE	1D		Exterior east wall on roof		Negative	2.09	1	0.01	0.02	0.01	0.02	0.6	0.8
102	6/20/2011 9:04	PAINT	4.27	mg / cm ^2	WALL	BRICK	D	FAIR	WHITE	1D		Exterior east wall on roof		Negative	1	1	0	0.02	0	0.02	0.8	0.8
103	6/20/2011 9:08	PAINT	1.07	mg / cm ^2	WALL	WOOD	B	FAIR	BROWN	1B		Exterior west wall on roof	roof trim	Negative	1	1	0.01	0.04	0.01	0.04	0.29	1.53
104	6/20/2011 9:13	PAINT	1.61	mg / cm ^2	WALL	WOOD	C	POOR	WHITE	1A	1	Exterior north wall	siding trim	Negative	2.98	1	0.6	0.4	0.6	0.4	0.8	1.3
105	6/20/2011 9:14	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	1B	1	Exterior north wall		Negative	1	1	0	0.02	0	0.02	0.5	0.9
106	6/20/2011 9:15	PAINT	3.77	mg / cm ^2	WALL	CONCRETE	C	FAIR	WHITE	1C	1	Exterior north wall		Negative	1	1	0	0.02	0	0.02	0.6	0.8
107	6/20/2011 9:15	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	C	FAIR	WHITE	1C	1	Exterior north wall		Negative	1	1	0	0.02	0	0.02	0.5	0.9
108	6/20/2011 9:16	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1C	1	Exterior west wall		Negative	1.52	1	0	0.02	0	0.02	0.7	0.9
109	6/20/2011 9:17	PAINT	3.21	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1C	1	Exterior west wall		Negative	1	1	0	0.02	0	0.02	0.08	1.48
110	6/20/2011 9:17	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	1C	1	Exterior south wall		Negative	1.49	1	0	0.02	0	0.02	0.5	0.9
111	6/20/2011 9:17	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	1C	1	Exterior south wall		Negative	1	1	0	0.02	0	0.02	0.6	0.9
112	6/20/2011 9:19	PAINT	3.2	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1D	1	Exterior west wall		Negative	1	1	0	0.02	0	0.02	0.26	1.4
113	6/20/2011 9:21	PAINT	1.06	mg / cm ^2	WALL	WOOD	B	POOR	WHITE	1D	1	Exterior west wall	overhang beam	Negative	1	1	0	0.02	0	0.02	0.6	1.7
114	6/20/2011 9:22	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	1D	1	Exterior west wall		Negative	2.02	1	0.01	0.02	0.01	0.02	0.6	0.9
115	6/20/2011 9:23	PAINT	1.07	mg / cm ^2	WALL	WOOD	A	POOR	WHITE	1D	1	Exterior south wall	overhang wall	Negative	1	1	0	0.02	0	0.02	< LOD	0
116	6/20/2011 9:25	PAINT	1.09	mg / cm ^2	WALL	WOOD	A	POOR	BROWN	1D	1	Exterior south wall	overhang wall	Negative	4.55	1	0.02	0.15	0.02	0.15	0.07	1.48
117	6/20/2011 9:25	PAINT	1.07	mg / cm ^2	COLUMN	WOOD	A	POOR	WHITE	1D	1	Exterior south wall		Negative	1	1	0	0.02	0	0.02	0.9	2
118	6/20/2011 9:26	PAINT	3.78	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	1D	1	Exterior south wall		Negative	1.3	1	0	0.02	0	0.02	0.6	0.8
119	6/20/2011 9:27	PAINT	1.07	mg / cm ^2	WALL	WOOD	A	POOR	WHITE	1D	1	Exterior south wall		Negative	1	1	0	0.02	0	0.02	0.29	1.9
120	6/20/2011 9:28	PAINT	1.07	mg / cm ^2	ROOF	WOOD		POOR	WHITE	1D		Exterior south wall	soffit	Negative	1	1	0	0.02	0	0.02	0.4	2
121	6/20/2011 9:29	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	B	FAIR	WHITE	9	1	Exterior west wall		Negative	1	1	0	0.02	0	0.02	0.6	0.9
122	6/20/2011 9:30	PAINT	20.36	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	9	1	Exterior west wall	decorative block	Negative	1	1	0	0.02	0	0.02	0.8	0.3
123	6/20/2011 9:32	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	B	FAIR	WHITE	9	1	Exterior west wall		Negative	1	1	0	0.02	0	0.02	0.7	0.9

124	6/20/2011 9:34	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	9	1			Negative	1.26	1	0	0.02	0	0.02	0.7	0.9	
125	6/20/2011 9:34	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	9	1			Negative	1.15	1	0	0.02	0	0.02	0.7	0.8	
126	6/20/2011 9:35	PAINT	3.77	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	9	1			Negative	2.24	1	0.01	0.02	0.01	0.02	0.8	0.8	
127	6/20/2011 9:35	PAINT	3.22	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	9	1			Negative	1	1	0	0.02	0	0.02	0.17	1.45	
128	6/20/2011 9:36	PAINT	3.77	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	9	1			Negative	1	1	0	0.02	0	0.02	0.6	0.9	
129	6/20/2011 9:36	PAINT	3.21	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	9	1			Negative	1.87	1	0	0.02	0	0.02	0.24	1.4	
130	6/20/2011 9:37	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	9	1			Negative	1.38	1	0	0.02	0	0.02	0.6	0.9	
131	6/20/2011 9:37	PAINT	2.7	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	9	1			Negative	1	1	0	0.02	0	0.02	0.13	1.55	
132	6/20/2011 9:45	PAINT	3.76	mg / cm ^2	COLUMN	CONCRETE	B	INTACT	WHITE	9	1			Negative	1	1	0	0.02	0	0.02	0.5	0.9	
133	6/20/2011 9:45	PAINT	3.74	mg / cm ^2	COLUMN	CONCRETE	A	INTACT	WHITE	9	1			Negative	1	1	0	0.02	0	0.02	0.6	0.9	
134	6/20/2011 9:46	PAINT	3.77	mg / cm ^2	COLUMN	CONCRETE	A	INTACT	RED	9	1			Negative	1.13	1	0	0.02	0	0.02	0.5	0.9	
135	6/20/2011 9:46	PAINT	3.76	mg / cm ^2	COLUMN	CONCRETE	B	INTACT	RED	9	1			Negative	1	1	0	0.02	0	0.02	0.4	0.9	
<b>136</b>	<b>6/20/2011 9:47</b>	<b>PAINT</b>	<b>0.54</b>	<b>mg / cm ^2</b>	<b>FLOOR</b>	<b>ASPHALT</b>		<b>POOR</b>	<b>YELLOW</b>	<b>9</b>	<b>1</b>		<b>Stripe</b>	<b>360 LF</b>	<b>Positive</b>	<b>1.52</b>	<b>1</b>	<b>3.1</b>	<b>1.8</b>	<b>3.1</b>	<b>1.8</b>	<b>4.8</b>	<b>8.2</b>
137	6/20/2011 9:50	PAINT	3.74	mg / cm ^2	FLOOR	ASPHALT		INTACT	BLUE	9	1			Negative	1.81	1	0	0.02	0	0.02	0.6	0.9	
138	6/20/2011 9:51	PAINT	3.75	mg / cm ^2	FLOOR	ASPHALT		INTACT	BLACK	9	1			Negative	1	1	0	0.02	0	0.02	0.7	0.8	
139	6/20/2011 9:51	PAINT	4.3	mg / cm ^2	WALL	CONCRETE	A	INTACT	BLACK	9	1			Negative	2.82	1	0.01	0.02	0.01	0.02	0.8	0.8	
<b>140</b>	<b>6/20/2011 9:53</b>	<b>PAINT</b>	<b>4.79</b>	<b>mg / cm ^2</b>	<b>FLOOR</b>	<b>CONCRETE</b>		<b>INTACT</b>	<b>YELLOW</b>	<b>9</b>	<b>1</b>		<b>Stripe</b>	<b>200 LF</b>	<b>Positive</b>	<b>1.87</b>	<b>1</b>	<b>1.9</b>	<b>0.8</b>	<b>1</b>	<b>0.2</b>	<b>1.9</b>	<b>0.8</b>
141	6/20/2011 10:00	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	6	1	Bay 1		Negative	1	1	0	0.02	0	0.02	0.6	0.9	
142	6/20/2011 10:00	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	6	1	Bay 1		Negative	1	1	0	0.02	0	0.02	0.4	0.9	
143	6/20/2011 10:01	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	6	1	Bay 1		Negative	1	1	0	0.02	0	0.02	0.7	0.9	
144	6/20/2011 10:01	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	6	1	Bay 1		Negative	1.24	1	0	0.02	0	0.02	0.5	0.9	
145	6/20/2011 10:01	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	6	1	Bay 1		Negative	1	1	0	0.02	0	0.02	0.6	0.9	
146	6/20/2011 10:02	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	6	1	Bay 1		Negative	1	1	0	0.02	0	0.02	0.4	0.9	
147	6/20/2011 10:02	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	6	1	Bay 1		Negative	1.32	1	0	0.02	0	0.02	0.28	0.91	
148	6/20/2011 10:02	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	6	1	Bay 1		Negative	2.11	1	0.01	0.02	0.01	0.02	0.4	0.9	
149	6/20/2011 10:04	PAINT	6.45	mg / cm ^2	COLUMN	CONCRETE	B	INTACT	WHITE	6	1	Bay 1		Negative	5.71	1	0.02	0.03	0.02	0.03	1	0.6	
150	6/20/2011 10:04	PAINT	3.75	mg / cm ^2	COLUMN	CONCRETE	A	INTACT	WHITE	6	1	Bay 1		Negative	1	1	0	0.02	0	0.02	0.21	0.94	
151	6/20/2011 10:05	PAINT	3.75	mg / cm ^2	COLUMN	CONCRETE	A	INTACT	RED	6	1	Bay 1		Negative	3.55	1	0.01	0.03	0.01	0.03	0.5	0.9	
<b>152</b>	<b>6/20/2011 10:06</b>	<b>PAINT</b>	<b>1.07</b>	<b>mg / cm ^2</b>	<b>DOOR</b>	<b>CONCRETE</b>	<b>B</b>	<b>INTACT</b>	<b>YELLOW</b>	<b>6</b>	<b>1</b>	<b>Bay 1</b>	<b>Overhead door bollard</b>	<b>96 SF</b>	<b>Positive</b>	<b>1.42</b>	<b>1</b>	<b>2.4</b>	<b>1</b>	<b>2.4</b>	<b>1</b>	<b>1.5</b>	<b>3.7</b>
<b>153</b>	<b>6/20/2011 10:08</b>	<b>PAINT</b>	<b>1.6</b>	<b>mg / cm ^2</b>	<b>FLOOR</b>	<b>CONCRETE</b>	<b>B</b>	<b>FAIR</b>	<b>YELLOW</b>	<b>6</b>	<b>1</b>	<b>Bay 1</b>	<b>Stripe</b>	<b>80 LF</b>	<b>Positive</b>	<b>1.51</b>	<b>1</b>	<b>1.8</b>	<b>0.5</b>	<b>1.8</b>	<b>0.5</b>	<b>2.5</b>	<b>2.6</b>
154	6/20/2011 10:10	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	6	1	Office		Negative	1.6	1	0	0.02	0	0.02	0.3	0.92	
155	6/20/2011 10:10	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	6	1	Office		Negative	1	1	0	0.02	0	0.02	0.5	0.9	
156	6/20/2011 10:11	PAINT	3.24	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	6	1	Office		Negative	1	1	0	0.02	0	0.02	0.21	1.44	
157	6/20/2011 10:11	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	6	1	Office		Negative	1	1	0	0.02	0	0.02	0.5	0.8	
158	6/20/2011 10:12	PAINT	3.72	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	6	1	Men's		Negative	1	1	0	0.02	0	0.02	0.3	0.91	
159	6/20/2011 10:12	PAINT	3.72	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	6	1	Men's		Negative	1	1	0	0.02	0	0.02	0.4	0.9	
160	6/20/2011 10:13	PAINT	1.61	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	6	1	Men's		Negative	1	1	0	0.02	0	0.02	< LOD	0	
161	6/20/2011 10:13	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	6	1	Men's		Negative	1.47	1	0	0.02	0	0.02	0.5	0.9	
162	6/20/2011 10:14	PAINT	5.37	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	6	1	Women's		Negative	1.25	1	0	0.02	0	0.02	1	0.7	
163	6/20/2011 10:14	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	6	1	Women's		Negative	1	1	0	0.02	0	0.02	0.4	0.9	
164	6/20/2011 10:14	PAINT	3.78	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	6	1	Women's		Negative	1	1	0	0.02	0	0.02	0.7	0.9	
165	6/20/2011 10:14	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	6	1	Women's		Negative	1	1	0	0.02	0	0.02	0.6	0.8	
166	6/20/2011 10:15	PAINT	4.28	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	6	2	Locker/lunchroom		Negative	1.53	1	0	0.02	0	0.02	0.7	0.9	
167	6/20/2011 10:16	PAINT	3.77	mg / cm ^2	WALL	CONCRETE	A	INTACT	GRAY	6	2	Locker/lunchroom		Negative	2.2	1	0.01	0.02	0.01	0.02	0.8	0.9	
168	6/20/2011 10:16	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	6	2	Locker/lunchroom		Negative	1	1	0	0.02	0	0.02	0.7	0.9	
169	6/20/2011 10:16	PAINT	3.77	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	6	2	Locker/lunchroom		Negative	1	1	0	0.02	0	0.02	0.6	0.9	
170	6/20/2011 10:17	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	6	2	Locker/lunchroom		Negative	1	1	0	0.02	0	0.02	0.7	0.9	
171	6/20/2011 10:17	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	D	INTACT	GRAY	6	2	Locker/lunchroom		Negative	2.02	1	0.01	0.02	0.01	0.02	0.5	0.9	
172	6/20/2011 10:18	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	D	INTACT	TAN	6	2	Locker/lunchroom		Negative	1	1	0	0.02	0	0.02	0.6	0.9	
173	6/20/2011 10:18	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	D	INTACT	GREEN	6	2	Locker/lunchroom		Negative	1	1	0	0.02	0	0.02	0.6	0.9	
174	6/20/2011 10:21	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	6	1	Bay 2		Negative	1	1	0	0.02	0	0.02	0.7	0.9	
175	6/20/2011 10:21	PAINT	3.77	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	6	1	Bay 2		Negative	1.25	1	0	0.02	0	0.02	0.24	0.92	
176	6/20/2011 10:21	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	6	1	Bay 2		Negative	1	1	0	0.02	0	0.02	0.7	0.9	
177	6/20/2011 10:22	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	6	1	Bay 2		Negative	1.56	1	0	0.02	0	0.02	0.5	0.9	
178	6/20/2011 10:22	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	6	1	Bay 2		Negative	1.39	1	0	0.02	0	0.02	0.7	0.9	
179	6/20/2011 10:22	PAINT	4.81	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	6	1	Bay 2		Negative	1	1	0	0.02	0	0.02	0.8	0.8	
180	6/20/2011 10:23	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	6	1	Bay 2		Negative	5.47	1	0.03	0.05	0.03	0.05	0.3	0.9	
181	6/20/2011 10:23	PAINT	4.29	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	6	1	Bay 2		Negative	1	1	0	0.02	0	0.02	0.7	0.8	
<b>182</b>	<b>6/20/2011 10:24</b>	<b>PAINT</b>	<b>1.6</b>	<b>mg / cm ^2</b>	<b>DOOR</b>	<b>CONCRETE</b>	<b>D</b>	<b>INTACT</b>	<b>YELLOW</b>	<b>6</b>	<b>1</b>	<b>Bay 2</b>	<b>Overhead door bollard</b>	<b>48 SF</b>	<b>Positive</b>	<b>1.47</b>	<b>1</b>	<b>1.6</b>	<b>0.5</b>	<b>1.6</b>	<b>0.5</b>	<b>1.2</b>	<b>2.6</b>
183	6/20/2011 10:24	PAINT	3.74	mg / cm ^2	COLUMN	CONCRETE	D	INTACT	WHITE	6	1	Bay 2		Negative	1.82	1	0	0.02	0	0.02	0.8	0.9	
184	6/20/2011 10:26	PAINT	3.75	mg / cm ^2	CEILING	CONCRETE		INTACT	WHITE	6	1	Bay 2	West stair	Negative	1.02	1	0	0.02	0	0.02	0.8	0.9	
185	6/20/2011 10:27	PAINT	3.77	mg / cm ^2	CEILING	CONCRETE	A	INTACT	BROWN	6	1	Bay 2	West stair	Negative	1	1	0	0.02	0	0.02	0.27	0.92	

186	6/20/2011 10:27	PAINT	3.75	mg / cm ^2	CEILING	CONCRETE	B	INTACT	WHITE	6	1	Bay 2	beam	West stair	Negative	2.17	1	0	0.02	0	0.02	0.7	0.9
187	6/20/2011 10:29	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	6	2	Bay 3			Negative	1	1	0	0.02	0	0.02	0.6	0.9
188	6/20/2011 10:30	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	6	2	Bay 3			Negative	1	1	0	0.02	0	0.02	0.5	0.9
189	6/20/2011 10:30	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	6	2	Bay 3			Negative	1	1	0	0.02	0	0.02	0.7	0.9
190	6/20/2011 10:30	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	6	2	Bay 3			Negative	1	1	0	0.02	0	0.02	0.5	0.9
191	6/20/2011 10:31	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	6	2	Bay 3			Negative	1.5	1	0	0.02	0	0.02	0.3	0.91
192	6/20/2011 10:31	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	6	2	Bay 3			Negative	1	1	0	0.02	0	0.02	0.5	0.9
193	6/20/2011 10:31	PAINT	3.19	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	6	2	Bay 3			Negative	1.31	1	0	0.02	0	0.02	0.14	1.45
194	6/20/2011 10:32	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	6	2	Bay 3			Negative	1	1	0	0.02	0	0.02	0.5	0.9
195	6/20/2011 10:35	PAINT	3.75	mg / cm ^2	CEILING	CONCRETE		INTACT	WHITE	6	2	Bay 3			Negative	4.35	1	0.01	0.03	0.01	0.03	0.5	0.9
196	6/20/2011 10:37	PAINT	3.23	mg / cm ^2	CEILING	CONCRETE		INTACT	WHITE	6	1	Bay 2		East stair	Negative	1	1	0	0.02	0	0.02	0.17	1.41
197	6/20/2011 10:37	PAINT	3.76	mg / cm ^2	CEILING	CONCRETE	A	INTACT	BROWN	6	1	Bay 2		East stair	Negative	1.93	1	0	0.02	0	0.02	0.5	0.9
198	6/20/2011 10:38	PAINT	3.75	mg / cm ^2	CEILING	CONCRETE	D	INTACT	WHITE	6	1	Bay 2	beam	East stair	Negative	1	1	0	0.02	0	0.02	0.8	0.8
199	6/20/2011 10:44	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	6	1	Exterior east wall			Negative	1	1	0	0.02	0	0.02	0.6	0.9
200	6/20/2011 10:45	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	D	INTACT	BROWN	6	1	Exterior east wall			Negative	1	1	0	0.02	0	0.02	0.4	0.9
201	6/20/2011 10:46	PAINT	1.07	mg / cm ^2	DOOR	CONCRETE	D	INTACT	BROWN	6	1	Exterior east wall	Overhead door bollard		Negative	1	1	0	0.02	0	0.02	0.3	2.67
202	6/20/2011 10:54	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	6	1	Exterior south wall			Negative	2.44	1	0.01	0.02	0.01	0.02	0.24	0.88
203	6/20/2011 10:54	PAINT	3.2	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	6	1	Exterior south wall			Negative	1	1	0	0.02	0	0.02	0.15	1.44
204	6/20/2011 10:55	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	A	INTACT	BROWN	6	1	Exterior south wall			Negative	1.37	1	0	0.02	0	0.02	0.5	0.9
205	6/20/2011 10:55	PAINT	1.08	mg / cm ^2	DOOR	WOOD	A	POOR	WHITE	6	1	Exterior south wall	Overhead door trim		Negative	1	1	0	0.02	0	0.02	0.6	1.8
206	6/20/2011 10:56	PAINT	1.07	mg / cm ^2	DOOR	CONCRETE	A	INTACT	BROWN	6	1	Exterior south wall	Overhead door bollard		Negative	1	1	0	0.02	0	0.02	0.5	3
207	6/20/2011 10:58	PAINT	3.22	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	6	1	Exterior west wall			Negative	1	1	0	0.02	0	0.02	0.28	1.42
208	6/20/2011 10:58	PAINT	3.77	mg / cm ^2	WALL	CONCRETE	B	INTACT	WHITE	6	1	Exterior west wall			Negative	1.08	1	0	0.02	0	0.02	0.7	0.9
209	6/20/2011 10:59	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	B	INTACT	BROWN	6	1	Exterior west wall			Negative	1	1	0	0.02	0	0.02	0.6	0.9
210	6/20/2011 10:59	PAINT	1.08	mg / cm ^2	DOOR	CONCRETE	B	INTACT	BROWN	6	1	Exterior west wall	Overhead door bollard		Negative	1	1	0	0.02	0	0.02	< LOD	0
211	6/20/2011 11:01	PAINT	5.86	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	6	1	Exterior north wall			Negative	1	1	0	0.02	0	0.02	0.9	0.7
212	6/20/2011 11:01	PAINT	3.74	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	6	1	Exterior north wall			Negative	1	1	0	0.02	0	0.02	0.4	0.9
213	6/20/2011 11:02	PAINT	4.85	mg / cm ^2	WALL	CONCRETE	C	INTACT	BROWN	6	1	Exterior north wall			Negative	3.23	1	0.01	0.02	0.01	0.02	0.9	0.8
214	6/20/2011 11:02	PAINT	3.78	mg / cm ^2	COLUMN	CONCRETE	A	INTACT	WHITE	6	1	Exterior north wall			Negative	1	1	0	0.02	0	0.02	0.5	0.9
<b>215</b>	<b>6/20/2011 11:02</b>	<b>PAINT</b>	<b>2.15</b>	<b>mg / cm ^2</b>	<b>COLUMN</b>	<b>CONCRETE</b>	<b>A</b>	<b>INTACT</b>	<b>YELLOW</b>	<b>6</b>	<b>1</b>	<b>Exterior north wall</b>		<b>200 SF</b>	<b>Positive</b>	<b>1.61</b>	<b>1</b>	<b>1.4</b>	<b>0.4</b>	<b>1.4</b>	<b>0.4</b>	<b>2.4</b>	<b>2.2</b>
216	6/20/2011 11:05	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	B	FAIR	WHITE	5	1	Exterior west wall			Negative	1	1	0	0.02	0	0.02	0.7	0.9
217	6/20/2011 11:05	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	B	FAIR	WHITE	5	1	Exterior west wall			Negative	1	1	0	0.02	0	0.02	0.6	0.9
218	6/20/2011 11:05	PAINT	1.08	mg / cm ^2	COLUMN	WOOD	B	POOR	WHITE	5	1	Exterior west wall			Negative	1	1	0	0.02	0	0.02	0.4	1.2
219	6/20/2011 11:07	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	5	1	Exterior south wall			Negative	1	1	0	0.02	0	0.02	0.4	0.9
220	6/20/2011 11:07	PAINT	3.77	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	5	1	Exterior south wall			Negative	1	1	0	0.02	0	0.02	0.7	0.9
221	6/20/2011 11:07	PAINT	4.28	mg / cm ^2	WALL	CONCRETE	A	INTACT	BROWN	5	1	Exterior south wall			Negative	1	1	0	0.02	0	0.02	0.8	0.8
222	6/20/2011 11:08	PAINT	4.83	mg / cm ^2	WALL	CONCRETE	D	INTACT	BROWN	5	1	Exterior east wall			Negative	1.87	1	0	0.02	0	0.02	0.9	0.7
223	6/20/2011 11:09	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	5	1	Exterior east wall			Negative	1	1	0	0.02	0	0.02	0.8	0.8
224	6/20/2011 11:09	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	5	1	Exterior east wall			Negative	1	1	0	0.02	0	0.02	0.8	0.9
225	6/20/2011 11:11	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	5	1	Exterior north wall			Negative	1	1	0	0.02	0	0.02	0.28	0.86
226	6/20/2011 11:11	PAINT	4.26	mg / cm ^2	WALL	CONCRETE	C	INTACT	WHITE	5	1	Exterior north wall			Negative	1	1	0	0.02	0	0.02	0.8	0.8
227	6/20/2011 11:11	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	C	INTACT	BROWN	5	1	Exterior north wall			Negative	1	1	0	0.02	0	0.02	0.5	0.9
228	6/20/2011 11:15	PAINT	3.73	mg / cm ^2	WALL	CONCRETE	D	INTACT	BROWN	9	1	Exterior east wall			Negative	1	1	0	0.02	0	0.02	0.8	0.9
229	6/20/2011 11:15	PAINT	3.76	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	9	1	Exterior east wall			Negative	4.03	1	0.02	0.03	0.02	0.03	0.5	0.9
230	6/20/2011 11:15	PAINT	3.21	mg / cm ^2	WALL	CONCRETE	D	INTACT	WHITE	9	1	Exterior east wall			Negative	1.75	1	0	0.02	0	0.02	0.11	1.45
231	6/20/2011 11:17	PAINT	4.29	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	9	1	Exterior south wall			Negative	1	1	0	0.02	0	0.02	0.9	0.8
232	6/20/2011 11:17	PAINT	3.75	mg / cm ^2	WALL	CONCRETE	A	INTACT	WHITE	9	1	Exterior south wall			Negative	1.39	1	0	0.02	0	0.02	0.7	0.8
233	6/20/2011 11:18	PAINT	4.29	mg / cm ^2	WALL	CONCRETE	A	INTACT	BROWN	9	1	Exterior south wall			Negative	3.29	1	0.01	0.02	0.01	0.02	0.8	0.8
234	6/20/2011 11:26	PAINT	3.77	mg / cm ^2	CEILING	CONCRETE		FAIR	WHITE	6		Exterior east wall	overhang in NEC		Negative	1	1	0	0.02	0	0.02	0.7	0.9
235	6/20/2011 11:30	PAINT	1.07	mg / cm ^2	WALL	WOOD	B	POOR	WHITE	5		Exterior west wall	roof trim		Negative	1	1	0	0.02	0	0.02	< LOD	0
236	6/20/2011 11:32	PAINT	1.08	mg / cm ^2	ROOF	WOOD	B	POOR	WHITE	5		Exterior west wall	roof underside		Negative	1.9	1	0.28	0.34	0.28	0.34	0.5	1.8
237	6/20/2011 11:36	PAINT	1.08	mg / cm ^2	WALL	WOOD	D	POOR	BROWN	5		Exterior east wall	roof trim		Negative	1	1	0	0.02	0	0.02	0.4	1.9
238	6/20/2011 11:43	Calibration to 1.0	6.43	mg / cm ^2											Negative	1.05	1	0.9	0.1	0.9	0.1	0.5	0.5
239	6/20/2011 11:44	Calibration to 1.0	16.1	mg / cm ^2											Negative	1.05	1	0.9	0.1	0.9	0.1	0.5	0.3
240	6/20/2011 11:44	Calibration to 1.0	9.09	mg / cm ^2											Positive	1.16	1	1.1	0.1	1.1	0.1	0.6	0.4

**APPENDIX R**



7615 Golden Triangle Dr., Suite N  
Eden Prairie, MN 55344  
(952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_


Project Name Scherer Brothers - Building 1A

By NOT TO SCALE Date \_\_\_\_\_

B Sibley Street NE

A

C



104



D



7615 Golden Triangle Dr., Suite N  
 Eden Prairie, MN 55344  
 (952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_


Project Name Scherer Brothers - Building 1B

By NOT TO SCALE Date \_\_\_\_\_

Sibley Street NE B

A

C



Ground Floor D






7615 Golden Triangle Dr., Suite N  
 Eden Prairie, MN 55344  
 (952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 1B

By NOT TO SCALE Date \_\_\_\_\_

**B** Sibley Street NE



2nd FLOOR






7615 Golden Triangle Dr., Suite N  
 Eden Prairie, MN 55344  
 (952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 1B

By \_\_\_\_\_ Date \_\_\_\_\_






7615 Golden Triangle Dr., Suite N  
Eden Prairie, MN 55344  
(952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 1C

By NOT TO SCALE Date \_\_\_\_\_

A



C




7615 Golden Triangle Dr., Suite N  
 Eden Prairie, MN 55344  
 (952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 1D


By NOT TO SCALE Date \_\_\_\_\_

A



J

B



C




7615 Golden Triangle Dr., Suite N  
Eden Prairie, MN 55344  
(952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 5

By NOT TO SCALE Date \_\_\_\_\_






7615 Golden Triangle Dr., Suite N  
 Eden Prairie, MN 55344  
 (952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 6

By NOT TO SCALE Date \_\_\_\_\_






7615 Golden Triangle Dr., Suite N  
 Eden Prairie, MN 55344  
 (952) 831-3341 • Fax (952) 831-4552

Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 6

By NOT TO SCALE Date \_\_\_\_\_

A



D

R



2<sup>nd</sup> Floor

C



7615 Golden Triangle Dr., Suite N  
 Eden Prairie, MN 55344  
 (952) 831-3341 • Fax (952) 831-4552


Project No. 20074 Sheet \_\_\_\_\_ of \_\_\_\_\_

Project Name Scherer Brothers - Building 9

By NOT TO SCALE Date \_\_\_\_\_

A

99



8<sup>th</sup> AVE NE

C





**APPENDIX S**

# TestAmerica

THE LEADER IN ENVIRONMENTAL TESTING

## ANALYTICAL REPORT

TestAmerica Laboratories, Inc.

TestAmerica Buffalo

10 Hazelwood Drive

Amherst, NY 14228-2298

Tel: (716)691-2600

TestAmerica Job ID: 480-6508-1

Client Project/Site: Peer Engineering

For:


PEER Engineering, Inc.

7615 Golden Triangle

Suite N

Eden Prairie, Minnesota 55344

Attn: Robert Rykken



Authorized for release by:

07/01/2011 10:54:29 AM

Melissa Deyo

Project Administrator

[melissa.deyo@testamericainc.com](mailto:melissa.deyo@testamericainc.com)

Designee for

Sally Hoffman

Project Manager II

[sally.hoffman@testamericainc.com](mailto:sally.hoffman@testamericainc.com)

### LINKS

Review your project  
results through

TotalAccess

Have a Question?



Visit us at:

[www.testamericainc.com](http://www.testamericainc.com)

*Results relate only to the items tested and the sample(s) as received by the laboratory. The test results in this report meet all 2003 NELAC requirements for accredited parameters, exceptions are noted in this report. Pursuant to NELAC, this report may not be reproduced except in full, and with written approval from the laboratory. For questions please contact the Project Manager at the e-mail address or telephone number listed on this page.*

*This report has been electronically signed and authorized by the signatory. Electronic signature is intended to be the legally binding equivalent of a traditionally handwritten signature.*



# Table of Contents

Cover Page . . . . .	1
Table of Contents . . . . .	2
Definitions/Glossary . . . . .	3
Case Narrative . . . . .	4
Detection Summary . . . . .	5
Client Sample Results . . . . .	6
Surrogate Summary . . . . .	10
QC Sample Results . . . . .	11
QC Association Summary . . . . .	12
Lab Chronicle . . . . .	13
Certification Summary . . . . .	16
Method Summary . . . . .	17
Sample Summary . . . . .	18
Chain of Custody . . . . .	19
Receipt Checklists . . . . .	21

# Definitions/Glossary

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

## Qualifiers

### GC Semi VOA

Qualifier	Qualifier Description
X	Surrogate is outside control limits

## Glossary

Abbreviation	These commonly used abbreviations may or may not be present in this report.
☼	Listed under the "D" column to designate that the result is reported on a dry weight basis.
EPA	United States Environmental Protection Agency
ND	Not Detected above the reporting level.
MDL	Method Detection Limit
RL	Reporting Limit
RE, RE1 (etc.)	Indicates a Re-extraction or Reanalysis of the sample.
%R	Percent Recovery
RPD	Relative Percent Difference, a measure of the relative difference between two points.

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15

# Case Narrative

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

---

**Job ID: 480-6508-1**

---

**Laboratory: TestAmerica Buffalo**

## Narrative

---

**Job Narrative**  
**480-6508-1**

### Receipt

All samples were received in good condition within temperature requirements.

### GC Semi VOA

Method 8082: The following samples were diluted due to matrix effect: C-13 (480-6508-10) and C-14 (480-6508-11). Surrogate recoveries are not representative and elevated reporting limits (RLs) are provided.

Method 8082: The following samples had one surrogate outside recovery limits: (480-6508-1 MS) and (480-6508-1 MSD). However, the second surrogate recovery was within limits.

No other analytical or quality issues were noted.

### Organic Prep

No analytical or quality issues were noted.

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15

# Detection Summary

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

**Client Sample ID: C-1**

**Lab Sample ID: 480-6508-1**

No Detections.

**Client Sample ID: C-2**

**Lab Sample ID: 480-6508-2**

No Detections.

**Client Sample ID: C-4**

**Lab Sample ID: 480-6508-3**

No Detections.

**Client Sample ID: C-6**

**Lab Sample ID: 480-6508-4**

No Detections.

**Client Sample ID: C-8**

**Lab Sample ID: 480-6508-5**

No Detections.

**Client Sample ID: C-9**

**Lab Sample ID: 480-6508-6**

No Detections.

**Client Sample ID: C-10**

**Lab Sample ID: 480-6508-7**

No Detections.

**Client Sample ID: C-11**

**Lab Sample ID: 480-6508-8**

No Detections.

**Client Sample ID: C-12**

**Lab Sample ID: 480-6508-9**

No Detections.

**Client Sample ID: C-13**

**Lab Sample ID: 480-6508-10**

No Detections.

**Client Sample ID: C-14**

**Lab Sample ID: 480-6508-11**

No Detections.

**Client Sample ID: C-15**

**Lab Sample ID: 480-6508-12**

No Detections.

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15

# Client Sample Results

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

## Client Sample ID: C-1

Lab Sample ID: 480-6508-1

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

### Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
PCB-1016	ND		3100	610	ug/Kg		06/28/11 19:55	06/29/11 13:05	1
PCB-1221	ND		3100	610	ug/Kg		06/28/11 19:55	06/29/11 13:05	1
PCB-1232	ND		3100	610	ug/Kg		06/28/11 19:55	06/29/11 13:05	1
PCB-1242	ND		3100	680	ug/Kg		06/28/11 19:55	06/29/11 13:05	1
PCB-1248	ND		3100	610	ug/Kg		06/28/11 19:55	06/29/11 13:05	1
PCB-1254	ND		3100	660	ug/Kg		06/28/11 19:55	06/29/11 13:05	1
PCB-1260	ND		3100	1500	ug/Kg		06/28/11 19:55	06/29/11 13:05	1
<b>Surrogate</b>	<b>% Recovery</b>	<b>Qualifier</b>	<b>Limits</b>				<b>Prepared</b>	<b>Analyzed</b>	<b>Dil Fac</b>
DCB Decachlorobiphenyl	105		34 - 148				06/28/11 19:55	06/29/11 13:05	1
Tetrachloro-m-xylene	116		35 - 134				06/28/11 19:55	06/29/11 13:05	1

## Client Sample ID: C-2

Lab Sample ID: 480-6508-2

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

### Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
PCB-1016	ND		2900	580	ug/Kg		06/28/11 19:55	06/29/11 13:50	1
PCB-1221	ND		2900	580	ug/Kg		06/28/11 19:55	06/29/11 13:50	1
PCB-1232	ND		2900	580	ug/Kg		06/28/11 19:55	06/29/11 13:50	1
PCB-1242	ND		2900	640	ug/Kg		06/28/11 19:55	06/29/11 13:50	1
PCB-1248	ND		2900	580	ug/Kg		06/28/11 19:55	06/29/11 13:50	1
PCB-1254	ND		2900	620	ug/Kg		06/28/11 19:55	06/29/11 13:50	1
PCB-1260	ND		2900	1400	ug/Kg		06/28/11 19:55	06/29/11 13:50	1
<b>Surrogate</b>	<b>% Recovery</b>	<b>Qualifier</b>	<b>Limits</b>				<b>Prepared</b>	<b>Analyzed</b>	<b>Dil Fac</b>
DCB Decachlorobiphenyl	111		34 - 148				06/28/11 19:55	06/29/11 13:50	1
Tetrachloro-m-xylene	114		35 - 134				06/28/11 19:55	06/29/11 13:50	1

## Client Sample ID: C-4

Lab Sample ID: 480-6508-3

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

### Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
PCB-1016	ND		3100	610	ug/Kg		06/28/11 19:55	06/29/11 14:05	1
PCB-1221	ND		3100	610	ug/Kg		06/28/11 19:55	06/29/11 14:05	1
PCB-1232	ND		3100	610	ug/Kg		06/28/11 19:55	06/29/11 14:05	1
PCB-1242	ND		3100	680	ug/Kg		06/28/11 19:55	06/29/11 14:05	1
PCB-1248	ND		3100	610	ug/Kg		06/28/11 19:55	06/29/11 14:05	1
PCB-1254	ND		3100	660	ug/Kg		06/28/11 19:55	06/29/11 14:05	1
PCB-1260	ND		3100	1500	ug/Kg		06/28/11 19:55	06/29/11 14:05	1
<b>Surrogate</b>	<b>% Recovery</b>	<b>Qualifier</b>	<b>Limits</b>				<b>Prepared</b>	<b>Analyzed</b>	<b>Dil Fac</b>
DCB Decachlorobiphenyl	115		34 - 148				06/28/11 19:55	06/29/11 14:05	1
Tetrachloro-m-xylene	113		35 - 134				06/28/11 19:55	06/29/11 14:05	1

# Client Sample Results

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

## Client Sample ID: C-6

Lab Sample ID: 480-6508-4

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

### Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
PCB-1016	ND		2600	510	ug/Kg		06/28/11 19:55	06/29/11 14:19	1
PCB-1221	ND		2600	510	ug/Kg		06/28/11 19:55	06/29/11 14:19	1
PCB-1232	ND		2600	510	ug/Kg		06/28/11 19:55	06/29/11 14:19	1
PCB-1242	ND		2600	570	ug/Kg		06/28/11 19:55	06/29/11 14:19	1
PCB-1248	ND		2600	520	ug/Kg		06/28/11 19:55	06/29/11 14:19	1
PCB-1254	ND		2600	560	ug/Kg		06/28/11 19:55	06/29/11 14:19	1
PCB-1260	ND		2600	1200	ug/Kg		06/28/11 19:55	06/29/11 14:19	1
<b>Surrogate</b>	<b>% Recovery</b>	<b>Qualifier</b>	<b>Limits</b>				<b>Prepared</b>	<b>Analyzed</b>	<b>Dil Fac</b>
DCB Decachlorobiphenyl	114		34 - 148				06/28/11 19:55	06/29/11 14:19	1
Tetrachloro-m-xylene	113		35 - 134				06/28/11 19:55	06/29/11 14:19	1

## Client Sample ID: C-8

Lab Sample ID: 480-6508-5

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

### Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
PCB-1016	ND		3600	700	ug/Kg		06/28/11 19:55	06/29/11 14:35	1
PCB-1221	ND		3600	700	ug/Kg		06/28/11 19:55	06/29/11 14:35	1
PCB-1232	ND		3600	700	ug/Kg		06/28/11 19:55	06/29/11 14:35	1
PCB-1242	ND		3600	780	ug/Kg		06/28/11 19:55	06/29/11 14:35	1
PCB-1248	ND		3600	700	ug/Kg		06/28/11 19:55	06/29/11 14:35	1
PCB-1254	ND		3600	750	ug/Kg		06/28/11 19:55	06/29/11 14:35	1
PCB-1260	ND		3600	1700	ug/Kg		06/28/11 19:55	06/29/11 14:35	1
<b>Surrogate</b>	<b>% Recovery</b>	<b>Qualifier</b>	<b>Limits</b>				<b>Prepared</b>	<b>Analyzed</b>	<b>Dil Fac</b>
DCB Decachlorobiphenyl	115		34 - 148				06/28/11 19:55	06/29/11 14:35	1
Tetrachloro-m-xylene	119		35 - 134				06/28/11 19:55	06/29/11 14:35	1

## Client Sample ID: C-9

Lab Sample ID: 480-6508-6

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

### Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
PCB-1016	ND		3300	650	ug/Kg		06/28/11 19:55	06/29/11 14:50	1
PCB-1221	ND		3300	650	ug/Kg		06/28/11 19:55	06/29/11 14:50	1
PCB-1232	ND		3300	650	ug/Kg		06/28/11 19:55	06/29/11 14:50	1
PCB-1242	ND		3300	720	ug/Kg		06/28/11 19:55	06/29/11 14:50	1
PCB-1248	ND		3300	650	ug/Kg		06/28/11 19:55	06/29/11 14:50	1
PCB-1254	ND		3300	700	ug/Kg		06/28/11 19:55	06/29/11 14:50	1
PCB-1260	ND		3300	1600	ug/Kg		06/28/11 19:55	06/29/11 14:50	1
<b>Surrogate</b>	<b>% Recovery</b>	<b>Qualifier</b>	<b>Limits</b>				<b>Prepared</b>	<b>Analyzed</b>	<b>Dil Fac</b>
DCB Decachlorobiphenyl	116		34 - 148				06/28/11 19:55	06/29/11 14:50	1
Tetrachloro-m-xylene	118		35 - 134				06/28/11 19:55	06/29/11 14:50	1

# Client Sample Results

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

## Client Sample ID: C-10

Lab Sample ID: 480-6508-7

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

### Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
PCB-1016	ND		2800	540	ug/Kg		06/28/11 19:55	06/29/11 15:34	1
PCB-1221	ND		2800	540	ug/Kg		06/28/11 19:55	06/29/11 15:34	1
PCB-1232	ND		2800	540	ug/Kg		06/28/11 19:55	06/29/11 15:34	1
PCB-1242	ND		2800	600	ug/Kg		06/28/11 19:55	06/29/11 15:34	1
PCB-1248	ND		2800	550	ug/Kg		06/28/11 19:55	06/29/11 15:34	1
PCB-1254	ND		2800	590	ug/Kg		06/28/11 19:55	06/29/11 15:34	1
PCB-1260	ND		2800	1300	ug/Kg		06/28/11 19:55	06/29/11 15:34	1
<b>Surrogate</b>	<b>% Recovery</b>	<b>Qualifier</b>	<b>Limits</b>				<b>Prepared</b>	<b>Analyzed</b>	<b>Dil Fac</b>
DCB Decachlorobiphenyl	113		34 - 148				06/28/11 19:55	06/29/11 15:34	1
Tetrachloro-m-xylene	110		35 - 134				06/28/11 19:55	06/29/11 15:34	1

## Client Sample ID: C-11

Lab Sample ID: 480-6508-8

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

### Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
PCB-1016	ND		4200	820	ug/Kg		06/28/11 19:55	06/29/11 15:49	1
PCB-1221	ND		4200	820	ug/Kg		06/28/11 19:55	06/29/11 15:49	1
PCB-1232	ND		4200	820	ug/Kg		06/28/11 19:55	06/29/11 15:49	1
PCB-1242	ND		4200	910	ug/Kg		06/28/11 19:55	06/29/11 15:49	1
PCB-1248	ND		4200	820	ug/Kg		06/28/11 19:55	06/29/11 15:49	1
PCB-1254	ND		4200	880	ug/Kg		06/28/11 19:55	06/29/11 15:49	1
PCB-1260	ND		4200	2000	ug/Kg		06/28/11 19:55	06/29/11 15:49	1
<b>Surrogate</b>	<b>% Recovery</b>	<b>Qualifier</b>	<b>Limits</b>				<b>Prepared</b>	<b>Analyzed</b>	<b>Dil Fac</b>
DCB Decachlorobiphenyl	113		34 - 148				06/28/11 19:55	06/29/11 15:49	1
Tetrachloro-m-xylene	110		35 - 134				06/28/11 19:55	06/29/11 15:49	1

## Client Sample ID: C-12

Lab Sample ID: 480-6508-9

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

### Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
PCB-1016	ND		3800	750	ug/Kg		06/28/11 19:55	06/29/11 16:04	1
PCB-1221	ND		3800	750	ug/Kg		06/28/11 19:55	06/29/11 16:04	1
PCB-1232	ND		3800	750	ug/Kg		06/28/11 19:55	06/29/11 16:04	1
PCB-1242	ND		3800	840	ug/Kg		06/28/11 19:55	06/29/11 16:04	1
PCB-1248	ND		3800	750	ug/Kg		06/28/11 19:55	06/29/11 16:04	1
PCB-1254	ND		3800	810	ug/Kg		06/28/11 19:55	06/29/11 16:04	1
PCB-1260	ND		3800	1800	ug/Kg		06/28/11 19:55	06/29/11 16:04	1
<b>Surrogate</b>	<b>% Recovery</b>	<b>Qualifier</b>	<b>Limits</b>				<b>Prepared</b>	<b>Analyzed</b>	<b>Dil Fac</b>
DCB Decachlorobiphenyl	117		34 - 148				06/28/11 19:55	06/29/11 16:04	1
Tetrachloro-m-xylene	112		35 - 134				06/28/11 19:55	06/29/11 16:04	1

# Client Sample Results

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

## Client Sample ID: C-13

Lab Sample ID: 480-6508-10

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

### Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
PCB-1016	ND		28000	5400	ug/Kg		06/28/11 19:55	06/29/11 16:19	10
PCB-1221	ND		28000	5400	ug/Kg		06/28/11 19:55	06/29/11 16:19	10
PCB-1232	ND		28000	5400	ug/Kg		06/28/11 19:55	06/29/11 16:19	10
PCB-1242	ND		28000	6000	ug/Kg		06/28/11 19:55	06/29/11 16:19	10
PCB-1248	ND		28000	5500	ug/Kg		06/28/11 19:55	06/29/11 16:19	10
PCB-1254	ND		28000	5900	ug/Kg		06/28/11 19:55	06/29/11 16:19	10
PCB-1260	ND		28000	13000	ug/Kg		06/28/11 19:55	06/29/11 16:19	10
<b>Surrogate</b>	<b>% Recovery</b>	<b>Qualifier</b>	<b>Limits</b>				<b>Prepared</b>	<b>Analyzed</b>	<b>Dil Fac</b>
DCB Decachlorobiphenyl	34		34 - 148				06/28/11 19:55	06/29/11 16:19	10
Tetrachloro-m-xylene	150	X	35 - 134				06/28/11 19:55	06/29/11 16:19	10

## Client Sample ID: C-14

Lab Sample ID: 480-6508-11

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

### Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
PCB-1016	ND		290000	58000	ug/Kg		06/28/11 21:58	06/29/11 16:33	100
PCB-1221	ND		290000	58000	ug/Kg		06/28/11 21:58	06/29/11 16:33	100
PCB-1232	ND		290000	58000	ug/Kg		06/28/11 21:58	06/29/11 16:33	100
PCB-1242	ND		290000	64000	ug/Kg		06/28/11 21:58	06/29/11 16:33	100
PCB-1248	ND		290000	58000	ug/Kg		06/28/11 21:58	06/29/11 16:33	100
PCB-1254	ND		290000	62000	ug/Kg		06/28/11 21:58	06/29/11 16:33	100
PCB-1260	ND		290000	140000	ug/Kg		06/28/11 21:58	06/29/11 16:33	100
<b>Surrogate</b>	<b>% Recovery</b>	<b>Qualifier</b>	<b>Limits</b>				<b>Prepared</b>	<b>Analyzed</b>	<b>Dil Fac</b>
DCB Decachlorobiphenyl	-915	X	34 - 148				06/28/11 21:58	06/29/11 16:33	100
Tetrachloro-m-xylene	467	X	35 - 134				06/28/11 21:58	06/29/11 16:33	100

## Client Sample ID: C-15

Lab Sample ID: 480-6508-12

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

### Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
PCB-1016	ND		3100	610	ug/Kg		06/28/11 21:58	06/29/11 16:48	1
PCB-1221	ND		3100	610	ug/Kg		06/28/11 21:58	06/29/11 16:48	1
PCB-1232	ND		3100	610	ug/Kg		06/28/11 21:58	06/29/11 16:48	1
PCB-1242	ND		3100	680	ug/Kg		06/28/11 21:58	06/29/11 16:48	1
PCB-1248	ND		3100	610	ug/Kg		06/28/11 21:58	06/29/11 16:48	1
PCB-1254	ND		3100	660	ug/Kg		06/28/11 21:58	06/29/11 16:48	1
PCB-1260	ND		3100	1500	ug/Kg		06/28/11 21:58	06/29/11 16:48	1
<b>Surrogate</b>	<b>% Recovery</b>	<b>Qualifier</b>	<b>Limits</b>				<b>Prepared</b>	<b>Analyzed</b>	<b>Dil Fac</b>
DCB Decachlorobiphenyl	112		34 - 148				06/28/11 21:58	06/29/11 16:48	1
Tetrachloro-m-xylene	110		35 - 134				06/28/11 21:58	06/29/11 16:48	1

# Surrogate Summary

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

## Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

Matrix: Solid

Prep Type: Total/NA

Lab Sample ID	Client Sample ID	Percent Surrogate Recovery (Acceptance Limits)	
		DCB2 (34-148)	TCX2 (35-134)
480-6508-1	C-1	105	116
480-6508-1 MS	C-1	166 X	121
480-6508-1 MSD	C-1	105	139 X
480-6508-2	C-2	111	114
480-6508-3	C-4	115	113
480-6508-4	C-6	114	113
480-6508-5	C-8	115	119
480-6508-6	C-9	116	118
480-6508-7	C-10	113	110
480-6508-8	C-11	113	110
480-6508-9	C-12	117	112
480-6508-10	C-13	34	150 X
480-6508-11	C-14	-915 X	467 X
480-6508-12	C-15	112	110
LCS 480-21893/2-A	Lab Control Sample	124	123
MB 480-21893/1-A	Method Blank	111	113

### Surrogate Legend

DCB = DCB Decachlorobiphenyl

TCX = Tetrachloro-m-xylene

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15

# QC Sample Results

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

## Method: 8082 - Polychlorinated Biphenyls (PCBs) by Gas Chromatography

**Lab Sample ID: MB 480-21893/1-A**  
**Matrix: Solid**  
**Analysis Batch: 21988**

**Client Sample ID: Method Blank**  
**Prep Type: Total/NA**  
**Prep Batch: 21893**

Analyte	MB MB		RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
	Result	Qualifier							
PCB-1016	ND		2800	540	ug/Kg		06/28/11 19:55	06/29/11 12:20	1
PCB-1221	ND		2800	540	ug/Kg		06/28/11 19:55	06/29/11 12:20	1
PCB-1232	ND		2800	540	ug/Kg		06/28/11 19:55	06/29/11 12:20	1
PCB-1242	ND		2800	600	ug/Kg		06/28/11 19:55	06/29/11 12:20	1
PCB-1248	ND		2800	550	ug/Kg		06/28/11 19:55	06/29/11 12:20	1
PCB-1254	ND		2800	590	ug/Kg		06/28/11 19:55	06/29/11 12:20	1
PCB-1260	ND		2800	1300	ug/Kg		06/28/11 19:55	06/29/11 12:20	1

Surrogate	MB MB		Limits	Prepared	Analyzed	Dil Fac
	% Recovery	Qualifier				
DCB Decachlorobiphenyl	111		34 - 148	06/28/11 19:55	06/29/11 12:20	1
Tetrachloro-m-xylene	113		35 - 134	06/28/11 19:55	06/29/11 12:20	1

**Lab Sample ID: LCS 480-21893/2-A**  
**Matrix: Solid**  
**Analysis Batch: 21988**

**Client Sample ID: Lab Control Sample**  
**Prep Type: Total/NA**  
**Prep Batch: 21893**

Analyte	Spike Added	LCS LCS		Unit	D	% Rec	% Rec. Limits
		Result	Qualifier				
PCB-1016	38500	51400		ug/Kg		134	59 - 154
PCB-1260	38500	50400		ug/Kg		131	51 - 179

Surrogate	LCS LCS		Limits
	% Recovery	Qualifier	
DCB Decachlorobiphenyl	124		34 - 148
Tetrachloro-m-xylene	123		35 - 134

**Lab Sample ID: 480-6508-1 MS**  
**Matrix: Solid**  
**Analysis Batch: 21988**

**Client Sample ID: C-1**  
**Prep Type: Total/NA**  
**Prep Batch: 21893**

Analyte	Sample Result	Sample Qualifier	Spike Added	MS MS		Unit	D	% Rec	% Rec. Limits
				Result	Qualifier				
PCB-1016	ND		31300	35900		ug/Kg		115	59 - 154
PCB-1260	ND		31300	41900		ug/Kg		134	51 - 179

Surrogate	MS MS		Limits
	% Recovery	Qualifier	
DCB Decachlorobiphenyl	166	X	34 - 148
Tetrachloro-m-xylene	121		35 - 134

**Lab Sample ID: 480-6508-1 MSD**  
**Matrix: Solid**  
**Analysis Batch: 21988**

**Client Sample ID: C-1**  
**Prep Type: Total/NA**  
**Prep Batch: 21893**

Analyte	Sample Result	Sample Qualifier	Spike Added	MSD MSD		Unit	D	% Rec	% Rec. RPD		
				Result	Qualifier				Limits	RPD	Limit
PCB-1016	ND		45500	56900		ug/Kg		125	59 - 154	45	50
PCB-1260	ND		45500	50800		ug/Kg		112	51 - 179	19	50

Surrogate	MSD MSD		Limits
	% Recovery	Qualifier	
DCB Decachlorobiphenyl	105		34 - 148
Tetrachloro-m-xylene	139	X	35 - 134

# QC Association Summary

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

## GC Semi VOA

### Prep Batch: 21893

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
MB 480-21893/1-A	Method Blank	Total/NA	Solid	3550B	
LCS 480-21893/2-A	Lab Control Sample	Total/NA	Solid	3550B	
480-6508-1 MS	C-1	Total/NA	Solid	3550B	
480-6508-1 MSD	C-1	Total/NA	Solid	3550B	
480-6508-1	C-1	Total/NA	Solid	3550B	
480-6508-2	C-2	Total/NA	Solid	3550B	
480-6508-3	C-4	Total/NA	Solid	3550B	
480-6508-4	C-6	Total/NA	Solid	3550B	
480-6508-5	C-8	Total/NA	Solid	3550B	
480-6508-6	C-9	Total/NA	Solid	3550B	
480-6508-7	C-10	Total/NA	Solid	3550B	
480-6508-8	C-11	Total/NA	Solid	3550B	
480-6508-9	C-12	Total/NA	Solid	3550B	
480-6508-10	C-13	Total/NA	Solid	3550B	
480-6508-11	C-14	Total/NA	Solid	3550B	
480-6508-12	C-15	Total/NA	Solid	3550B	

### Analysis Batch: 21988

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
MB 480-21893/1-A	Method Blank	Total/NA	Solid	8082	21893
LCS 480-21893/2-A	Lab Control Sample	Total/NA	Solid	8082	21893
480-6508-1	C-1	Total/NA	Solid	8082	21893
480-6508-1 MS	C-1	Total/NA	Solid	8082	21893
480-6508-1 MSD	C-1	Total/NA	Solid	8082	21893
480-6508-2	C-2	Total/NA	Solid	8082	21893
480-6508-3	C-4	Total/NA	Solid	8082	21893
480-6508-4	C-6	Total/NA	Solid	8082	21893
480-6508-5	C-8	Total/NA	Solid	8082	21893
480-6508-6	C-9	Total/NA	Solid	8082	21893
480-6508-7	C-10	Total/NA	Solid	8082	21893
480-6508-8	C-11	Total/NA	Solid	8082	21893
480-6508-9	C-12	Total/NA	Solid	8082	21893
480-6508-10	C-13	Total/NA	Solid	8082	21893
480-6508-11	C-14	Total/NA	Solid	8082	21893
480-6508-12	C-15	Total/NA	Solid	8082	21893

# Lab Chronicle

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

## Client Sample ID: C-1

Lab Sample ID: 480-6508-1

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared Or Analyzed	Analyst	Lab
Total/NA	Prep	3550B			21893	06/28/11 19:55	LT	TAL BUF
Total/NA	Analysis	8082		1	21988	06/29/11 13:05	JM	TAL BUF

## Client Sample ID: C-2

Lab Sample ID: 480-6508-2

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared Or Analyzed	Analyst	Lab
Total/NA	Prep	3550B			21893	06/28/11 19:55	LT	TAL BUF
Total/NA	Analysis	8082		1	21988	06/29/11 13:50	JM	TAL BUF

## Client Sample ID: C-4

Lab Sample ID: 480-6508-3

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared Or Analyzed	Analyst	Lab
Total/NA	Prep	3550B			21893	06/28/11 19:55	LT	TAL BUF
Total/NA	Analysis	8082		1	21988	06/29/11 14:05	JM	TAL BUF

## Client Sample ID: C-6

Lab Sample ID: 480-6508-4

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared Or Analyzed	Analyst	Lab
Total/NA	Prep	3550B			21893	06/28/11 19:55	LT	TAL BUF
Total/NA	Analysis	8082		1	21988	06/29/11 14:19	JM	TAL BUF

## Client Sample ID: C-8

Lab Sample ID: 480-6508-5

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared Or Analyzed	Analyst	Lab
Total/NA	Prep	3550B			21893	06/28/11 19:55	LT	TAL BUF
Total/NA	Analysis	8082		1	21988	06/29/11 14:35	JM	TAL BUF

## Client Sample ID: C-9

Lab Sample ID: 480-6508-6

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared Or Analyzed	Analyst	Lab
Total/NA	Prep	3550B			21893	06/28/11 19:55	LT	TAL BUF
Total/NA	Analysis	8082		1	21988	06/29/11 14:50	JM	TAL BUF

# Lab Chronicle

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

## Client Sample ID: C-10

Lab Sample ID: 480-6508-7

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared Or Analyzed	Analyst	Lab
Total/NA	Prep	3550B			21893	06/28/11 19:55	LT	TAL BUF
Total/NA	Analysis	8082		1	21988	06/29/11 15:34	JM	TAL BUF

## Client Sample ID: C-11

Lab Sample ID: 480-6508-8

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared Or Analyzed	Analyst	Lab
Total/NA	Prep	3550B			21893	06/28/11 19:55	LT	TAL BUF
Total/NA	Analysis	8082		1	21988	06/29/11 15:49	JM	TAL BUF

## Client Sample ID: C-12

Lab Sample ID: 480-6508-9

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared Or Analyzed	Analyst	Lab
Total/NA	Prep	3550B			21893	06/28/11 19:55	LT	TAL BUF
Total/NA	Analysis	8082		1	21988	06/29/11 16:04	JM	TAL BUF

## Client Sample ID: C-13

Lab Sample ID: 480-6508-10

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared Or Analyzed	Analyst	Lab
Total/NA	Prep	3550B			21893	06/28/11 19:55	LT	TAL BUF
Total/NA	Analysis	8082		10	21988	06/29/11 16:19	JM	TAL BUF

## Client Sample ID: C-14

Lab Sample ID: 480-6508-11

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared Or Analyzed	Analyst	Lab
Total/NA	Prep	3550B			21893	06/28/11 21:58	LT	TAL BUF
Total/NA	Analysis	8082		100	21988	06/29/11 16:33	JM	TAL BUF

## Client Sample ID: C-15

Lab Sample ID: 480-6508-12

Date Collected: 06/23/11 00:00

Matrix: Solid

Date Received: 06/24/11 09:40

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared Or Analyzed	Analyst	Lab
Total/NA	Prep	3550B			21893	06/28/11 21:58	LT	TAL BUF
Total/NA	Analysis	8082		1	21988	06/29/11 16:48	JM	TAL BUF

# Lab Chronicle

Client: PEER Engineering, Inc.

Project/Site: Peer Engineering

**Laboratory References:**

TAL BUF = TestAmerica Buffalo, 10 Hazelwood Drive, Amherst, NY 14228-2298, TEL (716)691-2600

TestAmerica Job ID: 480-6508-1

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

# Certification Summary

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

Laboratory	Authority	Program	EPA Region	Certification ID
TestAmerica Buffalo	Arkansas	State Program	6	88-0686
TestAmerica Buffalo	California	NELAC	9	1169CA
TestAmerica Buffalo	Connecticut	State Program	1	PH-0568
TestAmerica Buffalo	Florida	NELAC	4	E87672
TestAmerica Buffalo	Georgia	Georgia EPD	4	N/A
TestAmerica Buffalo	Georgia	State Program	4	956
TestAmerica Buffalo	Illinois	NELAC	5	100325 / 200003
TestAmerica Buffalo	Iowa	State Program	7	374
TestAmerica Buffalo	Kansas	NELAC	7	E-10187
TestAmerica Buffalo	Kentucky	Kentucky UST	4	30
TestAmerica Buffalo	Kentucky	State Program	4	90029
TestAmerica Buffalo	Louisiana	NELAC	6	02031
TestAmerica Buffalo	Maine	State Program	1	NY0044
TestAmerica Buffalo	Maryland	State Program	3	294
TestAmerica Buffalo	Massachusetts	State Program	1	M-NY044
TestAmerica Buffalo	Michigan	State Program	5	9937
TestAmerica Buffalo	Minnesota	NELAC	5	036-999-337
TestAmerica Buffalo	New Hampshire	NELAC	1	68-00281
TestAmerica Buffalo	New Hampshire	NELAC	1	2337
TestAmerica Buffalo	New Jersey	NELAC	2	NY455
TestAmerica Buffalo	New York	NELAC	2	10026
TestAmerica Buffalo	North Dakota	State Program	8	R-176
TestAmerica Buffalo	Oklahoma	State Program	6	9421
TestAmerica Buffalo	Oregon	NELAC	10	NY200003
TestAmerica Buffalo	Pennsylvania	NELAC	3	68-00281
TestAmerica Buffalo	Tennessee	State Program	4	TN02970
TestAmerica Buffalo	Texas	NELAC	6	T104704412-08-TX
TestAmerica Buffalo	USDA	USDA		P330-08-00242
TestAmerica Buffalo	Virginia	State Program	3	278
TestAmerica Buffalo	Washington	State Program	10	C1677
TestAmerica Buffalo	West Virginia	West Virginia DEP	3	252
TestAmerica Buffalo	Wisconsin	State Program	5	998310390

Accreditation may not be offered or required for all methods and analytes reported in this package. Please contact your project manager for the laboratory's current list of certified methods and analytes.



# Method Summary

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

---

Method	Method Description	Protocol	Laboratory
8082	Polychlorinated Biphenyls (PCBs) by Gas Chromatography	SW846	TAL BUF

---

**Protocol References:**

SW846 = "Test Methods For Evaluating Solid Waste, Physical/Chemical Methods", Third Edition, November 1986 And Its Updates.

**Laboratory References:**

TAL BUF = TestAmerica Buffalo, 10 Hazelwood Drive, Amherst, NY 14228-2298, TEL (716)691-2600



# Sample Summary

Client: PEER Engineering, Inc.  
Project/Site: Peer Engineering

TestAmerica Job ID: 480-6508-1

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
480-6508-1	C-1	Solid	06/23/11 00:00	06/24/11 09:40
480-6508-2	C-2	Solid	06/23/11 00:00	06/24/11 09:40
480-6508-3	C-4	Solid	06/23/11 00:00	06/24/11 09:40
480-6508-4	C-6	Solid	06/23/11 00:00	06/24/11 09:40
480-6508-5	C-8	Solid	06/23/11 00:00	06/24/11 09:40
480-6508-6	C-9	Solid	06/23/11 00:00	06/24/11 09:40
480-6508-7	C-10	Solid	06/23/11 00:00	06/24/11 09:40
480-6508-8	C-11	Solid	06/23/11 00:00	06/24/11 09:40
480-6508-9	C-12	Solid	06/23/11 00:00	06/24/11 09:40
480-6508-10	C-13	Solid	06/23/11 00:00	06/24/11 09:40
480-6508-11	C-14	Solid	06/23/11 00:00	06/24/11 09:40
480-6508-12	C-15	Solid	06/23/11 00:00	06/24/11 09:40

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15



**TestAmerica**  
 THE LEADER IN ENVIRONMENTAL TESTING

Watertown Division  
 602 Commerce Drive  
 Watertown, WI 53094

Phone 920-261-1660 or 800-833-7036  
 Fax 920-261-8120

Client Name: Peer Engineering Client # \_\_\_\_\_  
 Address: \_\_\_\_\_  
 City/State/Zip Code: Eder Prairie MN  
 Project Manager: Bob Rykken  
 Telephone Number: \_\_\_\_\_  
 Sampler Name (Print Name): Bob Rykken  
 Sampler Signature: [Signature]  
 Fax: \_\_\_\_\_

Project Name: MARR - Scherer Bros  
 Project #: 2007A  
 Site/Location ID: \_\_\_\_\_ State: \_\_\_\_\_  
 Report To: \_\_\_\_\_  
 Invoice To: \_\_\_\_\_  
 Quote #: \_\_\_\_\_ PO# \_\_\_\_\_

TAT Standard <input type="checkbox"/> Flush (surcharges may apply)  Date Needed: Fax Results: Y N E-mail: <input checked="" type="radio"/> N	Date Sampled	Time Sampled	C = Grab, C = Composite	Field Filtered	Matrix Preservation & # of Containers						Analyze For	QC Deliverables None Level 2 (Batch QC) Level 3 Level 4 Other _____	REMARKS							
					ST - Sludge OW - Drinking Water	GW - Groundwater S - Soil/Solid	WW - Wastewater Specify Other	HNO <sub>3</sub>	HCl	NaOH				H <sub>2</sub> SO <sub>4</sub>	Methanol	None	Other (Specify)			
C-14	6-23-11	6	6																	
C-15	↓																			

Special Instructions: 5 day TAT no Rush Charge.

LABORATORY COMMENTS:  
 Init Lab Temp: \_\_\_\_\_  
 Rec Lab Temp: 3.4  
 Custody Seals: Y N N/A  
 Bottles Supplied by TestAmerica: Y N

Relinquished By: Bob Rykken Date: 6-23-11 Time: 4:30  
 Relinquished By: [Signature] Date: 6-23-11 Time: 1:30  
 Relinquished By: [Signature] Date: 6-24-11 Time: 09:00



## Login Sample Receipt Checklist

Client: PEER Engineering, Inc.

Job Number: 480-6508-1

**Login Number: 6508**


**List Source: TestAmerica Buffalo**

**List Number: 2**

**Creator: Wienke, Robert**

Question	Answer	Comment
Radioactivity either was not measured or, if measured, is at or below background	True	
The cooler's custody seal, if present, is intact.	True	
The cooler or samples do not appear to have been compromised or tampered with.	True	
Samples were received on ice.	True	
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	True	
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
Is the Field Sampler's name present on COC?	True	
There are no discrepancies between the sample IDs on the containers and the COC.	True	
Samples are received within Holding Time.	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
Appropriate sample containers are used.	True	
Sample bottles are completely filled.	True	
Sample Preservation Verified	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
VOA sample vials do not have headspace or bubble is <6mm (1/4") in diameter.	True	
If necessary, staff have been informed of any short hold time or quick TAT needs	True	
Multiphasic samples are not present.	True	
Samples do not require splitting or compositing.	True	
Sampling Company provided.	False	
Samples received within 48 hours of sampling.	True	
Samples requiring field filtration have been filtered in the field.	N/A	
Chlorine Residual checked.	N/A	

**APPENDIX T**



**LEAD  
Risk Assessor**

Licensed by:  
State of Minnesota  
Department of Health  
License No. LR188  
Expires 02/04/2012

**Kelly W Brown**  
4780 154th Ln NW  
Ramsey, MN 55303

*Frank J. Buschner*  
Director, Env. Health Div.



**MINNESOTA MDH DEPARTMENT OF HEALTH ASBESTOS INSPECTOR**

Certified by:  
State of Minnesota  
Department of Health  
**Expires: 06/15/2011**

**Kelly W Brown**  
4780 154th Ln NW  
Ramsey, MN 55303

*Linda S. Bremer*  
Director, Env. Health Div.

No. AI3036 Issued: 06/22/2010



**MINNESOTA MDH DEPARTMENT OF HEALTH LEAD Risk Assessor**

Licensed by:  
State of Minnesota  
Department of Health  
**License No. LR188**  
**Expires 02/10/2011**

**Kelly W Brown**  
4780 154th Ln NW  
Ramsey, MN 55303

*Linda S. Bremer*  
Director, Env. Health Div.



**MINNESOTA MDH DEPARTMENT OF HEALTH ASBESTOS MANAGEMENT PLANNER**

Certified by:  
State of Minnesota  
Department of Health  
**Expires: 06/15/2011**

**Kelly W Brown**  
4780 154th Ln NW  
Ramsey, MN 55303

*Linda S. Bremer*  
Director, Env. Health Div.

No. AM3036 Issued: 06/22/2010